

Status Report

HAWKER 850XP
S/N 258980 N850TK

OWNER: TEXTRON FINANCIAL CORPORATION
ADDRESS: TWO CESSNA BOULEVARD
WICHITA KS 67215-1423

OPERATOR: TEXTRON FINANCIAL CORPORATION
ADDRESS: TWO CESSNA BOULEVARD
WICHITA KS 67215-1423

OPERATOR: ESSAR SHIPPING & LOGISTICS LIMITED
ADDRESS: C/O: JADE GLOBAL SERVICES FZE, NO
6EA417
DUBAI AIRPORT FREE ZONE DUBAI
293778

PHONE:
FAX:

PHONE:
FAX:

PHONE:
FAX:

ANALYST: GLEN WATSON
EMAIL: GWATSON@AVTRAK.COM

1-866-581-2267 (OFFICE)
316-462-2442 (FAX)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST
ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO
CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 258980/N850TK **MODEL:** HAWKER 850XP **MANUFACTURER:** TEXTRON AVIATION INC.

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 03-OCT-2008	2893:12 A/C HRS	as of 13-MAR-2019	_____ A/C HRS	as of ____/____/____
MANUFACTURER DATE: 26-NOV-2008	1939 AFL	as of 13-MAR-2019	_____ AFL	as of ____/____/____
	3709 APH	as of 06-MAR-2019	_____ APH	as of ____/____/____

APU SERIAL/PART: P-1101/3800304-1 **MODEL:** GTCP36-150(W) **MANUFACTURER:** HONEYWELL

INSTALLED ON 31-JUL-2018	LAST ACTUALS		CURRENT ACTUAL	
3598 APU HRS	3709 APU HRS	as of 06-MAR-2019	_____ APU HRS	as of ____/____/____
0 APUS	0 APUS	as of 14-NOV-2018	_____ APUS	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: P129435/3075160-4 **MODEL:** TFE731-5BR-1H **MANUFACTURER:** HONEYWELL

INSTALLED ON 15-SEP-2008	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2893:12 ENG. HRS	as of 13-MAR-2019	_____ ENG. HRS
0 ENC		1945 ENC	as of 13-MAR-2019	_____ ENC

ENGINE NO. 2 SERIAL/PART: P129434/3075160-4 **MODEL:** TFE731-5BR-1H **MANUFACTURER:** HONEYWELL

INSTALLED ON 15-SEP-2008	LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2893:12 ENG. HRS	as of 13-MAR-2019	_____ ENG. HRS
0 ENC		1945 ENC	as of 13-MAR-2019	_____ ENC



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS								
+ 050110	INSPECTION B1-B12 COMPLETE							
	PKG 91	MOS				04-MAR-2019		
		HRS/MSC	800	+40/-10		2892:42	3692:42	3732:42
	REF:	AFL				1938		
+ 050240	INSPECTION C1-C12 COMPLETE							
	PKG 92	MOS				27-JUN-2015		
		HRS/MSC	1600	+50/-50	-43:39	1643:39	3200	3250
	REF:	AFL				1058		
+ 050370	INSPECTION D1-D12 COMPLETE							
	PKG 93	MOS				26-NOV-2008		
		HRS/MSC	3200	+150/-50		0	3200	3350
	REF:	AFL				0		
+ 050500	INSPECTION E1-E12 COMPLETE							
	PKG 94	MOS	12	+1m/-1m	-73	04-MAR-2019	21-DEC-2019	21-JAN-2020
		HRS/MSC				2892:42		
	REF:	AFL				1938		
+ 050630	INSPECTION F1-F12 COMPLETE							
	PKG 95	MOS	24	+2m/-2m	-94	04-MAR-2019	30-NOV-2020	31-JAN-2021
		HRS/MSC				2892:42		
	REF:	AFL				1938		
+ 050760	INSPECTION G COMPLETE							
	PKG 96	MOS	48	+2m/-2m	-25	21-DEC-2016	26-NOV-2020	26-JAN-2021
		HRS/MSC				2148:39		
	REF:	AFL				1399		
ENGINE NO. 1 Model : TFE731-5BR Serial # P129435 Part # 3075160-4								
+ 057110 (s)	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION							
	PKG 1	MOS				04-MAR-2019		
		HRS/MSC	150	+100		2892:42		
	REF:	ENC				1944		
+ 057120 (s)	NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION							
	PKG 2	MOS				04-MAR-2019		
		HRS/MSC	300	+100		2892:42		
	REF:	ENC				1944		
057140 (s)	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION							
	PKG 4	MOS				04-MAR-2019		
		HRS/MSC	500	+350		2892:42		
	REF:	ENC				1944		
+ 057160 (s)	NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION							
	PKG 0	MOS				16-NOV-2016		
		HRS/MSC	1200	+200		2148:39		
	REF:	ENC				1402		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057170 (s)	NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION								
	PKG 5	MOS					04-MAR-2019		
		HRS/MSC	1200				2892:42		
	REF:	ENC					1944		
ENGINE NO. 2 Model : TFE731-5BR Serial # P129434 Part # 3075160-4									
+ 057110 (s)	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION								
	PKG 1	MOS					04-MAR-2019		
		HRS/MSC	150				2892:42		
	REF:	ENC					1944		
+ 057120 (s)	NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION								
	PKG 2	MOS					04-MAR-2019		
		HRS/MSC	300				2892:42		
	REF:	ENC					1944		
057140 (s)	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION								
	PKG 4	MOS					04-MAR-2019		
		HRS/MSC	500				2892:42		
	REF:	ENC					1944		
+ 057160 (s)	NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION								
	PKG 0	MOS					11-NOV-2016		
		HRS/MSC	1200				2148:39		
	REF:	ENC					1402		
057170 (s)	NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION								
	PKG 5	MOS					04-MAR-2019		
		HRS/MSC	1200				2892:42		
	REF:	ENC					1944		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
BCXP-160901	REVIEW HAWKER 750/800XP/850XP/900XP AFMS REVISION 32 DATED SEP.16 REVISION SUMMARY CHANGE FORM								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF BCXP	HRS/MSC -							
		AFL							
BCXP-170711	REVIEW HAWKER 750/800XP/850XP/900XP AFMS AUDIT SUMMARY CHANGE FORM								
		MOS							
REQUIREMENT CHANGE FORMS	REF: RCF BCXP	HRS/MSC -							
		AFL							
APU Model : GTCP36-150(W) Serial # P-1101 Part # 3800304-1									
A010-161102	APU - REVIEW SERVICE INFORMATION LETTER APU-56 (D199709000077) REVISION 2								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF A010-161102	HRS/MSC -							
		APUS							
A010-180112	APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	HRS/MSC -							
		APUS							
ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4									
E006-170921	NO. 1 ENGINE - REVIEW SB TFE331-72-3263 REV 16								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E006	HRS/MSC -							
		ENC							
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E006-170921	NO. 2 ENGINE - REVIEW	SB TFE331-72-3263 REV 16					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E006	MOS HRS/MSC - ENC							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
+ 050141 (s)	INSPECT AREA F1-800 HOURS						PKG		
05.203	PKG 91	MOS	800	+40/-10			04-MAR-2019 2892:42 1938		
	REF: See Workcard	HRS/MSC AFL							
+ 050171 (s)	INSPECT AREA F3 ABOVE FLOOR-800 HOURS						PKG		
05.206	PKG 91	MOS	800	+40/-10			04-MAR-2019 2892:42 1938		
	REF: See Workcard	HRS/MSC AFL							
+ 050181 (s)	INSPECT AREA F4-800 HOURS						PKG		
05.207	PKG 91	MOS	800	+40/-10			04-MAR-2019 2892:42 1938		
	REF: See Workcard	HRS/MSC AFL							
+ 050191 (s)	INSPECT AREA T1-800 HOURS						PKG		
05.208	PKG 91	MOS	800	+40/-10			04-MAR-2019 2892:42 1938		
	REF: See Workcard	HRS/MSC AFL							
+ 050201 (s)	INSPECT AREA W1-800 HOURS						PKG		
05.209	PKG 91	MOS	800	+40/-10			04-MAR-2019 2892:42 1938		
	REF: See Workcard	HRS/MSC AFL							
+ 050211 (s)	INSPECT AREA W2-800 HOURS						PKG		
05.210	PKG 91	MOS	800	+40/-10			04-MAR-2019 2892:42 1938		
	REF: See Workcard	HRS/MSC AFL							

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050221 (s)	INSPECT AREA M1/M2-800 HOURS						PKG		
05.211	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 050231 (s)	INSPECT AREA G-800 HOURS						PKG		
05.212	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 050271 (s)	INSPECT AREA F1-1600 HOURS						PKG		
05.303	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050281 (s)	INSPECT AREA F2-1600 HOURS						PKG		
05.304	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050291 (s)	INSPECT AREA F3 UNDERFLOOR-1600 HOURS						PKG		
05.305	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050301 (s)	INSPECT AREA F3- ABOVE FLOOR-1600 HOURS						PKG		
05.306	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050311 (s)	INSPECT AREA F4-1600 HOURS						PKG		
05.307	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050321 (s)	INSPECT AREA T1-1600 HOURS						PKG		
05.308	PKG 92 REF: AFMS INSPECTION C8	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050331 (s)	INSPECT AREA W1-1600 HOURS						PKG		
05.309	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050341 (s)	INSPECT AREA W2-1600 HOURS						PKG		
05.310	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050351 (s)	INSPECT AREA M1/M2-1600 HOURS						PKG		
05.311	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050361 (s)	INSPECT AREA G-1600 HOURS						PKG		
05.312	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 050411 (s)	INSPECT AREA F2-3200 HOURS						PKG		
05.404	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 050431 (s)	INSPECT AREA F3 ABOVE FLOOR-3200 HOURS						PKG		
05.406	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050441 (s)	INSPECT AREA F4-3200 HOURS						PKG		
05.407	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 050491 (s)	INSPECT AREA G-3200 HOURS						PKG		
05.412	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
050571 (s)	INSPECT AREA F4-12 MONTHS						PKG		
05.506	PKG 94 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		
+ 050661 (s)	INSPECT AREA F1-24 MONTHS						PKG		
05.603	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 050671 (s)	INSPECT AREA F2-24 MONTHS						PKG		
05.604	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 050691 (s)	INSPECT AREA F3-24 MONTHS						PKG		
05.606	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 050701 (s)	INSPECT AREA F4-24 MONTHS						PKG		
05.607	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050721 (s)	INSPECT AREA W1-24 MONTHS						PKG		
05.609	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 050731 (s)	INSPECT AREA W2-24 MONTHS						PKG		
05.610	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 050751 (s)	INSPECT AREA G-24 MONTHS						PKG		
05.612	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 050761 (s)	INSPECT AREA F1-48 MONTHS						PKG		
05.703	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 050762 (s)	INSPECT AREA F2-48 MONTHS						PKG		
05.704	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 050763 (s)	INSPECT AREA F3-48 MONTHS						PKG		
05.705	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 050764 (s)	INSPECT AREA F4-48 MONTHS						PKG		
05.707	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050765 (s)	INSPECT AREA T1-48 MONTHS						PKG		
05.708	PKG 96 REF: AFMS INTRODUCTION	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 050766 (s)	INSPECT AREA W1/W2-48 MONTHS						PKG		
05.709	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 050771	INSPECTION 400 HOUR DETAILED WALK-AROUND								
05.100	REF: See Workcard	MOS HRS/MSC AFL	400	+40/-10			04-MAR-2019 2892:42 1938	3292:42	3332:42
055005	ACCOMPLISH INSPECTIONS AFTER AN OVERWEIGHT OR HEAVY LANDING								
05.710	REF: AFMS HEAVY LANDING INSPECTION	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055010	ACCOMPLISH INSPECTIONS AFTER FLIGHT IN HEAVY TURBULENCE								
05.711	REF: AFMS TURBULENCE	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055015	ACCOMPLISH INSPECTIONS AFTER A LIGHTENING STRIKE								
05.712	REF: AFMS LIGHTNING STRIKE INSPECTION	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055035	ACCOMPLISH INSPECTIONS AFTER A COLD SOAK BELOW -40 DEGREE C								
05.713	REF:	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055040	ACCOMPLISH INSPECTIONS AFTER MISUSE OF REVERSE THRUST								
05.714	REF: AFMS REVERSE THRUST INSPECTION	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055045	ACCOMPLISH INSPECTIONS AFTER LANDING GEAR VIBRATION								
05.715	REF: AFMS VIBRATION INSP.	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055050	ACCOMPLISH INSPECTIONS AFTER LANDING OR ABORTED TAKE-OFF IN DEEP WATER PUDDLES, SLUSH OR SNOW								
05.716	REF: AFMS SLUSHY RUNWAY INSPECTION	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055060	ACCOMPLISH INSPECTIONS AFTER AN EMERGENCY STOP								
05.717	REF: AFMS EMERGENCY STOP INSPECTION	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055065	ACCOMPLISH INSPECTIONS AFTER ABNORMAL APU CONDITIONS								
05.718	REF: AFMS ABNORMAL APU INSPECTION	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
055070	ACCOMPLISH INSPECTIONS AFTER FLAP OVERSPEED								
05.719	REF: AFMS FLAP OVERSPEED	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
055075	ACCOMPLISH INSPECTIONS AFTER EXPOSURE TO VOLCANIC ASH								
05.720	REF: AFMS VOLCANIC ASH	MOS HRS/MSC AFL	A/R				03-OCT-2008 0 0		
T05T01	INSPECTION PRE-FLIGHT								
05.T01	REF: AFMS 05-00-00	MOS HRS/MSC AFL	O/C				14-OCT-2010 436:30 359		
T05T03	INSPECTION CRITERIA/STRUCTURAL INSPECTIONS								
05.T03	REF: AFMS INTRODUCTION	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		

ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4

E006-170919	NO. 1 ENGINE - REVIEW TFE731-5BR LMM TR 72-232								
		MOS HRS/MSC ENC	-				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E006								

ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4

E006-170919	NO. 2 ENGINE - REVIEW TFE731-5BR LMM TR 72-232								
		MOS HRS/MSC ENC	-				(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E006								

CHAPTER 06 DIMENSIONS AND AREAS

T06T01	GENERAL INSPECTION PANEL LOCATION CHARTS								
06.T01	REF: AFMS PANEL LOCATION	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		

CHAPTER 08 LEVELING AND WEIGHING

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 080001	WEIGHT AND BALANCE AIRCRAFT								
		MOS	36				04-MAR-2019	04-MAR-2022	
	REF:	HRS/MSC					2892:42		
		AFL					1938		
CHAPTER 12 SERVICING									
120001	LUBRICATE AREA G-200 HOURS								
		MOS					22-JUL-2018		
12.001		HRS/MSC	200	+40/-10			2823:13	3023:13	3063:13
	REF: See Workcard	AFL					1889		
+ 120003	LUBRICATE AREA F1-400 HOURS								
		MOS					22-JUL-2018		
12.003		HRS/MSC	400	+40/-10			2823:13	3223:13	3263:13
	REF: AFMS LUBRICATION	AFL					1889		
+ 120004	LUBRICATE AREA T1-400 HOURS								
		MOS					22-JUL-2018		
12.004		HRS/MSC	400	+40/-10			2823:13	3223:13	3263:13
	REF: See Workcard	AFL					1889		
+ 120007	LUBRICATE AREA W1/W2-400 HOURS								
		MOS					22-JUL-2018		
12.007		HRS/MSC	400	+40/-10			2823:13	3223:13	3263:13
	REF: See Workcard	AFL					1889		
120012 (s)	LUBRICATE AREA F3 (ABOVE FLOOR)-800 HOURS						PKG		
	PKG 91	MOS					04-MAR-2019		
12.012		HRS/MSC	800	+40/-10			2892:42		
	REF: AFMS LUBRICATION	AFL					1938		
+ 120013 (s)	LUBRICATE AREA F4-800 HOURS						PKG		
	PKG 91	MOS					04-MAR-2019		
12.009		HRS/MSC	800	+40/-10			2892:42		
	REF: AFMS LUBRICATION	AFL					1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
120015 (s)	LUBRICATE AREA W1-800 HOURS						PKG		
12.015	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
120016 (s)	LUBRICATE AREA W2-800 HOURS						PKG		
12.016	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
120018 (s)	LUBRICATE AREA G-800 HOURS						PKG		
12.018	PKG 91 REF:	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 120019 (s)	LUBRICATE AREA F1-1600 HOURS						PKG		
12.013	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
120020 (s)	LUBRICATE AREA F2-1600 HOURS						PKG		
12.020	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
120021 (s)	LUBRICATE AREA F3 (UNDERFLOOR)-1600 HOURS						PKG		
12.021	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
120022 (s)	LUBRICATE AREA F3-1600 HOURS						PKG		
12.022	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
120023 (s)	LUBRICATE AREA F4-1600 HOURS						PKG		
12.023	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
120024 (s)	LUBRICATE AREA T1-1600 HOURS						PKG		
12.024	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
120025 (s)	LUBRICATE AREA W1-1600 HOURS						PKG		
12.025	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
120026 (s)	LUBRICATE AREA W2-1600 HOURS						PKG		
12.026	PKG 92 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
120030 (s)	LUBRICATE AREA F2-3200 HOURS						PKG		
12.030	PKG 93 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 120049 (s)	LUBRICATE AREA F1-24 MONTHS						PKG		
12.049	PKG 95 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
120050 (s)	LUBRICATE AREA F2-24 MONTHS						PKG		
12.050	PKG 95 REF: AFMS LUBRICATION	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		

CHAPTER 20 STANDARD PRACTICES - AIRFRAME

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 200001 (s)	BONDING CHECK CONTROL SURFACES						PKG		
20.010	PKG 91 REF: AFMS INSPECTION B1	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 200002 (s)	FUNCTIONAL TEST REFUEL POINT EARTHING STUDS (3 OFF)						PKG		
20.020	PKG 91 REF: AFMS INSPECTION B1	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 200003 (s)	CHECK RADIO RACKING, ELECTRICAL-BONDING						PKG		
20.030	PKG 96 REF: AFMS INSPECTION G	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
CHAPTER 21 AIR CONDITIONING									
+ 210002 (s)	CHECK/TEST RAM AIR VALVE/DUMP VALVE/VENT VALVE						PKG		
21.075	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 210003 (s)	BENCH CHECK ENVIRONMENTAL CONTROL SYSTEM						PKG		
21.110	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 210004 (s)	CHECK MANUAL CABIN ALTITUDE CONTROL VALVE						PKG		
21.270	PKG 91 REF: AFMS INSPECTION B4	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 210005 (s)	CHECK COOLING TURBINE EXHAUST DUCT DRAIN						PKG		
21.260	PKG 91 REF: AFMS INSPECTION B7	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 210006	INSPECT WATER SEPARATOR FOR SATISFACTORY CONDITION								
21.221	REF: See Workcard	MOS HRS/MSC AFL	400	+10%			04-MAR-2019 2892:42 1938	3292:42	3332:42
+ 210007	INSPECT WATER SEPARATOR WATER DRAIN, WATER DRAIN PIPELINE, HP LINE TO WATER INJECTOR NOZZLE AND WATER INJECTOR NOZZLE ARE FREE FROM BLOCKAGES AND OBSTRUCTIONS								
21.280	REF: See Workcard	MOS HRS/MSC AFL	400	+10%			04-MAR-2019 2892:42 1938	3292:42	3332:42
210008 (s)	VISUALLY INSPECT CABIN PRESSURE OUTFLOW/SAFETY VALVE CONTROLLER						PKG		
21.118	PKG 92 REF: AFMS INSPECTION C4	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 210009 (s)	CHECK PRESSURIZATION CONTROL VENTURI SCREEN						PKG		
21.275	PKG 92 REF: AFMS INSPECTION C6	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
210010 (s)	CLEAN PRESSURE REGULATOR FILTER SCREENS						PKG		
21.155	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 210011 (s)	CLEAN/FUNCTIONAL TEST OUTFLOW/SAFETY VALVES						PKG		
21.120	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 210012 (s)	INSPECT AIR CONDITIONING DUCTS						PKG		
21.250	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 210013 (s)	INSPECT RAM AIR DUCT PKG 92	MOS					PKG		
21.255	REF: AFMS INSPECTION C7	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 210014 (s)	INSPECT CABIN AIR FILTERS (PRESSURIZATION SYSTEM) PKG 96	MOS	48	+2m/-2m			PKG		
21.310	REF: AFMS INSPECTION G	HRS/MSC AFL					21-DEC-2016 2148:39 1399		
+ 210015 (s)	INSPECT SILENCER DUCT/SOUNDPROOFING PKG 93	MOS					PKG		
21.015	REF: AFMS INSPECTION D7	HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 210016 (s)	BENCH CHECK SYSTEM OVERHEAT TEMPERATURE SWITCH PKG 93	MOS					PKG		
21.195	REF: AFMS INSPECTION D7	HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 210018 (s)	FUNCTIONAL TEST ALTITUDE SWITCH, CABIN DEPRESSURIZATION WARNING PKG 96	MOS	48	+2m/-2m			PKG		
21.135	REF: See Workcard	HRS/MSC AFL					21-DEC-2016 2148:39 1399		
+ 210019 (s)	INSPECT CABIN SUPPLY NON-RETURN VALVE PKG 93	MOS					PKG		
21.065	REF: See Workcard	HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 210020 (s)	FUNCTIONAL TEST ELECTRICALLY ACTUATED AUXILIARY HEATING VALVE PKG 92	MOS					PKG		
21.180	REF: See Workcard	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 210021 (s)	INSPECT/CHECK APU SUPPLY, AUXILIARY SUPPLY, RAM AIR SUPPLY AND MAIN ENGINE SUPPLY CHECK/NON-RETURN VALVES						PKG		
21.030	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 210022	CHECK TORQUE AIR CONDITIONING DUCTS								
21.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				09-APR-2009 64:42 48		
210024 (s)	CLEAN/REPLACE LOW LIMIT TEMPERATURE CONTROL VALVE FILTER						PKG		
21.290	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 210025 (s)	INSPECT PATS APU GTCP36-150W BLEED AIR SYSTEM						PKG		
21.035	PKG 92 REF: AFMS INSPECTION C7	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 211013	BENCH CHECK LEFT BLEED AIR OVER TEMPERATURE SWITCH								
21.265	REF:	MOS HRS/MSC AFL	60				03-SEP-2018 2835:14 1893	03-SEP-2023	
+ 211014	BENCH CHECK RIGHT BLEED AIR OVER TEMPERATURE SWITCH								
21.265	REF:	MOS HRS/MSC AFL	60				03-SEP-2018 2835:14 1893	03-SEP-2023	
211019	APU SHUTOFF VALVE								
21.020	PN SN-UNKNOWN REF: AMM 21-10-195	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211031	APU BLEED AIR NON-RETURN VALVE								
21.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
211088	NO. 1 AIR DISTRIBUTION ACTUATOR								
21.108	1092TH100-47 51170 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
211089	NO. 2 AIR DISTRIBUTION ACTUATOR								
21.108	1092TH100-47 5176D REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
211090	NO. 3 AIR DISTRIBUTION ACTUATOR								
21.108	1092TH100-47 5025D REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
211091	NO. 4 AIR DISTRIBUTION ACTUATOR								
21.108	1092TH100-47 5027D REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
211092	NO. 5 AIR DISTRIBUTION ACTUATOR								
21.108	1092TH100-47 5136D REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212001	LEFT MAIN AIR VALVE								
21.040	321292-1 3256 REF: AMM 21-10-25	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212002	RIGHT MAIN AIR VALVE								
21.045	HTE250072 14080475 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212008	PRESSURE REGULATOR VALVE								
21.295	3215086-3 965 REF: AMM 21-10-76	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212026	NO. 1 ENGINE BLEED AIR NON-RETURN VALVE								
21.050	HTE4168 MO254VNR1007 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212027	NO. 2 ENGINE BLEED AIR NON-RETURN VALVE								
21.050	HTE4168 MO259VNR1007 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212050	AUXILIARY HEATING BLEED AIR NON-RETURN VALVE								
21.055	123190-1 7737 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212062	LEFT (HP/LP) MIXING VALVE								
21.060	3213788-3 P-438C REF: AMM 21-10-35	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212063	RIGHT (HP/LP) MIXING VALVE								
21.060	3213788-3 2219C REF: AMM 21-10-35	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		
212074	MAIN SUPPLY NON-RETURN VALVE								
21.245 OVERHAUL	PN SN-UNKNOWN REF: AMM 21-10-107	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	12000	
212082	BLEED AIR CHECK VALVE								
21.070	HTE4405 25081367 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212086	RAM AIR NON-RETURN VALVE								
21.075	321262-1 1666 REF: AMM 21-10-165	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212098	RAM AIR SUPPLY NON-RETURN VALVE								
21.080	PN SN-UNKNOWN REF: AMM 21-10-165	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212103	TEMPERATURE DUCT SWITCH								
21.085	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212122	UPPER CHECK VALVE								
21.095	130156-2 58-A1107 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212123	LOWER CHECK VALVE								
21.095	130156-2 58-A1100 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
212146	CABIN RECIRCULATING FAN								
21.100	0901-2 0934 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213001	NO. 1 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE								
21.105	B01A2-14128A HAY0519 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213002	NO. 2 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE								
21.105	B01A2-14128A HAY0521 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213019	OUTFLOW/SAFETY VALVE CONTROLLER								
21.115	130530-5 104-142 REF: AMM 21-30-16	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-OCT-2010 446:12 364		
213031	LEFT OUTFLOW VALVE								
21.120	103278-18 58-G-0359 REF: AMM 21-30-25	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213032	RIGHT OUTFLOW VALVE								
21.120	103278-13 38-A0990 REF: AMM 21-30-25	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213035	2" BUTTERFLY VALVE								
21.320	AWE113-13A HAY0259 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213067	CABIN ALTITUDE CONTROL VALVE								
21.125	131004-2 38-6534 REF: AMM 21-30-95	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213073	MECHANICAL DUMP VALVE								
21.130	HTE940008 46072076 REF: AMM 21-30-136	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213097	ALTIMETER PRESSURE SWITCH								
21.135	140-380024-11 J009463 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213098	ALTIMETER PRESSURE SWITCH								
21.300	140-380024-7 J014137 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213109	VENTURI								
21.140	131052-1 47-4333 REF: AMM 21-30-105	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213115	FAN OPERATED VENTURI								
21.145	132322-3-1 48-A0878 REF: AMM 21-30-65	MOS HRS/MSC AFL	O/C	TSN:72 TSN:1463:45 TSN:958			13-OCT-2014 1463:45 958		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213121	LEFT PNEUMATIC VALVE								
21.150	107312-4-1 48-13301 REF: AMM 21-30-35	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213122	RIGHT PNEUMATIC VALVE								
21.150	107312-4-1 48-13289 REF: AMM 21-30-35	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213133	LEFT ABSOLUTE PRESSURE CONTROL								
21.155	102466-13 58-A0966 REF: AMM 21-30-55	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213134	RIGHT ABSOLUTE PRESSURE CONTROL								
21.155	102466-13 127-A0891 REF: AMM 21-30-55	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213157	JET PUMP								
21.160	131150-1-1 48-35530 REF: AMM 21-30-45	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213169	CABIN DIFFERENTIAL PRESSURE INDICATOR								
21.165	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
213181	GROUND PRESSURE CONNECTOR								
21.170	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216001	CABIN TEMPERATURE CONTROL VALVE								
21.175	104968 1819 REF: AMM 21-60-57	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
216025	AUXILIARY HEATING VALVE								
21.180	104568 13052 REF: AMM 21-60-105	MOS HRS/MSC AFL	O/C	TSO:4 TSO:0 TSO:0			23-NOV-2015 1757:19 1128		
216055	CABIN TEMPERATURE (CONTROLLER) SENSOR								
21.185	PN SN-UNKNOWN REF: MMA 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
216073	CABIN TEMPERATURE CONTROLLER								
21.190	617452-4 617452-01806 REF: AMM 21-60-67	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
216097	TEMPERATURE DUCT SELECTOR								
21.195	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
216115	COLD AIR UNIT PACK								
21.200	2214070-5 916 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
216121	MODULATING VALVE								
21.210	978836-5-1 1182 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216127	CONTROL SENSOR								
21.215	1150642-3 092C-11252 REF: AMM 21-60-60	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-NOV-2008 8:24 4		
216135	TOTAL TEMPERATURE SENSOR								
21.305	102ER1EC A81039 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
217001	WATER SEPARATOR								
21.220	25VF1351-131 1782 REF: AMM 21-10-95	MOS HRS/MSC AFL	O/C				19-DEC-2015 1775:09 1137		
217014	CABIN TRIPLE INDICATOR								
21.225	51010-1113 507997A REF: AMM 21-30-90	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-NOV-2008 8:24 4		
217023	PRESSURE SWITCH								
21.235	HTE690090 22082786 REF: AMM 21-10-39	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 22 AUTO FLIGHT									
221001	AFCS CONTROL PANEL								
22.010	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
221007	NO. 1 FLIGHT GUIDANCE COMPUTER								
22.015	822-1108-023 340XX REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221008	NO. 2 FLIGHT GUIDANCE COMPUTER								
22.015	822-1108-023 340XP REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
221010	NO. 1 AUTO PILOT MODE SELECT PANEL								
22.040	PN SN-UNKNOWN REF: MMA 34-22-56	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
221011	NO. 2 AUTO PILOT MODE SELECT PANEL								
22.040	PN SN-UNKNOWN REF: MMA 34-22-56	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
221037	AUTOPILOT ELEVATOR SERVO								
22.020	822-1168-002 2HJNB REF: AMM 22-10-30	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			07-NOV-2011 753:05 541		
221039	ELEVATOR SERVO MOUNT								
22.050	622-5735-004 347WH REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
221043	AUTOPILOT RUDDER SERVO								
22.020	822-1168-002 33XLW REF: AMM 22-10-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
221045	RUDDER SERVO MOUNT								
22.050	622-5735-004 302BB REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221049	AUTOPILOT AILERON SERVO								
22.020	822-1168-002 347DV REF: AMM 22-10-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
221052	AILERON SERVO MOUNT								
22.050	622-5735-004 309PK REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 23 COMMUNICATIONS									
231001	NO. 1 HF COMMUNICATIONS CONTROLLER								
23.015	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231002	NO. 2 HF COMMUNICATIONS CONTROLLER								
23.015	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231004	NO. 1 HF CONTROLLER ADAPTER								
23.020	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231006	NO. 2 HF CONTROLLER ADAPTER								
23.020	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231011	NO. 1 HF COMMUNICATIONS POWER AMPLIFIER								
23.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231012	NO. 2 HF COMMUNICATIONS POWER AMPLIFIER								
23.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231015	COLLINS HG 9041 HF ANTENNA								
23.130	622-8114-002 8789 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231016	COLLINS HF 9031A RECEIVER/TRANSMITTER								
23.135	822-0101-002 3953 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231025	NO. 1 HF RECEIVER EXCITER								
23.030	PN SN-UNKNOWN REF: AMM 23-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231026	NO. 2 HF RECEIVER EXCITER								
23.030	PN SN-UNKNOWN REF: AMM 23-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231027	NO. 1 HF BRIDGING AMPLIFIER								
23.035	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231028	NO. 2 HF BRIDGING AMPLIFIER								
23.035	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231029	DUAL HF CAPACITOR								
23.040	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231041	VHF COMMUNICATION (CTL-23D) CONTROL								
23.136	822-2177-001 34DMV REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231043	NO. 1 VHF COMMUNICATIONS TRANSCEIVER								
23.045	822-1468-102 342KW REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231049	NO. 2 VHF COMMUNICATIONS TRANSCEIVER								
23.045	822-1468-102 342LC REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231050	ATC UPPER ANTENNA								
23.050	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231055	NO. 1 VHF AERIAL								
23.055	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231056	NO. 2 VHF AERIAL								
23.055	16-41-1T 50125 REF: AMM 23-10-35	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231058	AUDIO TONE GENERATOR								
23.060	PN SN-UNKNOWN REF: MMA 23-50-67	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231061	NO. 1 RADIO MANAGEMENT UNIT								
23.065	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231062	NO. 2 RADIO MANAGEMENT UNIT								
23.065	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
231064	CLEARANCE DELIVERY CONTROL								
23.070	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
234051	AIRCELL TRANSCEIVER								
	400-10680-001 1068021300 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 0 0		
234052	AIRCELL ANTENNA								
	S65-8282-101 3635 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 0 0		
234054	COCKPIT AIRCELL HANDSET								
	310-10590-002 1059017012 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
234055	COCKPIT AIRCELL HANDSET CRADLE 310-10595-002 1059511193 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		
234056	CABIN AIRCELL HANDSET 310-10590-002 1059017016 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
234057	CABIN AIRCELL HANDSET CRADLE 310-10595-002 1059512736 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		
235001	NO. 1 AUDIO CONTROLLER 803-004 424 REF: MMA 23-50-67	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			13-MAR-2019 2893:12 1939		
235002	NO. 2 AUDIO CONTROLLER 803-004 1278 REF: MMA 23-50-67	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
235017	NO. 1 HANDHELD AUDIO MICROPHONE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
235019	NO. 2 HANDHELD AUDIO MICROPHONE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237001	COCKPIT VOICE RECORDER								
23.105	1603-02-12 2171 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:77 TSN:1605:09 TSN:1038			15-APR-2015 1614:15 1043		
237004	COCKPIT VOICE RECORDER NO.1 MICROPHONE								
23.110	16301-01 2750 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
237005	COCKPIT VOICE RECORDER NO.2 MICROPHONE								
23.110	16301-01 2752 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
237014	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON								
23.105	DK-120 SD20361 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-FEB-2014 1292:18 858		
+ 237016	CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON								
23.105	REF: See Workcard	MOS HRS/MSC AFL	24				21-DEC-2017 2552:56 1694	21-DEC-2019	
237017	REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY								
23.105	DK-120 SD20361 REF: See Workcard	MOS HRS/MSC AFL	DUE				26-FEB-2014 1292:18 858	31-OCT-2019 M	
237019	LEFT COCKPIT VOICE RECORDER CONTROL								
23.125	1634-01 1164 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237020	RIGHT COCKPIT VOICE RECORDER CONTROL								
23.125	PN SN-UNKNOWN REF: AMM 23-70-36	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
237021	VOICE RECORDER INERTIA SWITCH								
23.115	3LO453/2.0 82615 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
238015	SELCAL DECODER UNIT								
23.120	1200008-002 5720 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
23R502	PERFORM COCKPIT VOICE (CVR) RECORDER READOUT								
	REF:	DAYS HRS/MSC AFL	180				04-MAR-2019 2892:42 1938	31-AUG-2019	
CHAPTER 24 ELECTRICAL POWER									
+ 240001	INSPECT/CHECK NO. 1 ENGINE STARTER/GENERATOR								
24.045	23080-64 P1237/CA REF: See Workcard	MOS HRS/MSC AFL	300	+100			03-SEP-2018 2835:14 1893	3135:14	3235:14
+ 240001	INSPECT/CHECK NO. 2 ENGINE STARTER/GENERATOR								
24.045	23080-64 P2387 REF: See Workcard	MOS HRS/MSC AFL	300	+100			03-SEP-2018 2835:14 1893	3135:14	3235:14
+ 240002 (s)	OPERATE NO.1 AND NO.2 MAIN STATIC INVERTERS								
24.010	PKG 91 REF: AFMS INSPECTION B1	MOS HRS/MSC AFL	800	+40/-10			PKG 04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 240003 (s)	FUNCTION TEST FREQUENCY WILD A.C. SYSTEM PKG 93	MOS					PKG		
24.030	REF: See Workcard	HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240004 (s)	CHECK BUSBAR CONTACTOR CONTROL PKG 92	MOS					PKG		
24.145	REF: AFMS INSPECTION C1	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 240006 (s)	CHECK D.C. BUSBAR PROTECTION/VOLTAGE SENSING UNIT PKG 93	MOS					PKG		
24.070	REF: See Workcard	HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240007 (s)	BENCH CHECK GROUND POWER OVERVOLTAGE SENSOR (IF FITTED). PKG 93	MOS					PKG		
24.110	REF: See Workcard	HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240009 (s)	FUNCTIONAL TEST D.C. GENERATING SYSTEM PKG 91	MOS					PKG		
24.065	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 240010 (s)	INSPECT PE, PS1 AND PS2 BUSBAR FEEDER CABLES BELOW PANEL DA PKG 92	MOS					PKG		
24.160	REF: See Workcard	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
240011 (s)	REPLACE BUSBAR PE, PS1 AND PS2 FEEDER FUSES PKG 92	MOS					PKG		
24.150	REF: See Workcard	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 240012 (s)	INSPECT BUSBAR PE, PS1 AND PS2 FEEDER SYSTEM CONNECTIONS						PKG		
24.165	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 240013 (s)	FUNCTION TEST ALL CIRCUIT BREAKERS						PKG		
24.005	PKG 93 REF: AFMS INSPECTION D1	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240014 (s)	FUNCTION TEST MAIN GENERATOR CONTROL UNIT (GCU)						PKG		
24.040	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240015 (s)	FUNCTION TEST APU GENERATOR CONTROL UNIT (GCU)						PKG		
24.040	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240016 (s)	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)						PKG		
24.235	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240017 (s)	INSPECT/CHECK EARTH STATIONS *16, *17, *18, AND *19						PKG		
24.155	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		
+ 240018 (s)	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE REAR PRESSURE-BULKHEAD)						PKG		
24.235	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 240024	INSPECT/CHECK APU STARTER/GENERATOR								
24.085	23080-064 Y0866 REF: See Workcard	MOS HRS/MSC AFL APH	500				04-MAR-2019 2892:42 1938 3702		4202
240025 (s)	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FUSELAGE KEEL AT THE FRONT SPAR)						PKG		
24.245	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 240026 (s)	INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD)						PKG		
24.240	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
240027 (s)	CHECK MAIN BATTERIES						PKG		
24.250	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
240028	VISUAL INSPECTION PANEL GG AND TERMINAL BLOCK M								
24.095	REF: See Workcard	MOS HRS/MSC AFL	400	+10%			22-MAY-2018 2755:18 1841	3155:18	3195:18
240029 (s)	VISUAL INSPECTION FOR DISCOLORATION AND SIGNS OF DISTRESS, INSPECT DA-PANEL FOR PROPER MOUNTING OF COMPONENTS						PKG		
24.260	PKG 94 REF: AFMS INSPECTION E6	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		
+ 240030	FUNCTION TEST CABIN INVERTER (115 VAC) SYSTEM (IF INSTALLED)								
24.255	REF: See Workcard	DAYS HRS/MSC AFL	200	+10% +10%			04-MAR-2019 2892:42 1938	3092:42	3112:42

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242001	NO. 1 (MAIN) INVERTER								
24.015	140-380010-3 0809220E REF: AMM 24-21-102	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
242002	NO. 2 (MAIN) INVERTER								
24.015	100-1600-04 1115M REF: AMM 24-21-102	MOS HRS/MSC AFL	O/C				20-AUG-2016 2088:29 1352		
242013	NO. 3 (STANDBY) INVERTER								
24.015	SPS-1607A 952 REF: AMM 24-21-105	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
242031	NO. 1 INVERTER CONTACTOR								
24.020 OVERHAUL	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	5000	
242032	NO. 2 INVERTER CONTACTOR								
24.020 OVERHAUL	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	5000	
242073	NO. 1 ENGINE AC GENERATOR								
24.025 OVERHAUL	BA02801-1 2449 REF: AMM 24-22-21	MOS HRS/MSC AFL	96 3000	TSO:2 TSO:0 TSO:0			28-MAY-2016 1973:56 1275	28-MAR-2024 4973:56	
242074	NO. 2 ENGINE AC GENERATOR								
24.025 OVERHAUL	BA02801-1 2453 REF: AMM 24-22-21	MOS HRS/MSC AFL	96 3000	TSO:1 TSO:0 TSO:0			28-MAY-2016 1973:56 1275	28-APR-2024 4973:56	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242097	LEFT AC GENERATOR CONTROL UNIT								
24.035	CB02701 3353 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
242098	RIGHT AC GENERATOR CONTROL UNIT								
24.035	CB02701 3350 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243001	NO. 1 ENGINE STARTER/GENERATOR								
24.045 OVERHAUL	23080-64 P1237/CA REF: AMM 24-30-21	MOS HRS/MSC AFL	1000	TSO:0			21-DEC-2017 2577:06 1721	3577:06	
243002	NO. 2 ENGINE STARTER/GENERATOR								
24.045 OVERHAUL	23080-64 P2387 REF: AMM 24-30-21	MOS HRS/MSC AFL	1000	TSO:0			21-DEC-2017 2577:06 1721	3577:06	
243037	NO. 1 DC GENERATOR CONTROL UNIT								
24.050	51539-006H P1939 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243038	NO. 2 DC GENERATOR CONTROL UNIT								
24.050	51539-006H P1940 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243049	H (UPPER) CONTACTOR								
24.055	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243050	H (LOWER) CONTACTOR								
24.055	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243061	G (UPPER) CONTACTOR								
24.060	140-380021-0001 CP-88979 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243062	G (LOWER) CONTACTOR								
24.060	140-380017-0001 CP-81963 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243079	DC VOLTAGE SENSING UNIT								
24.070	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243091	GROUND SUPPLY START (E) CONTACTOR								
24.075 OVERHAUL	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	6000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		6000
243103	APU STARTER/GENERATOR CONTROL UNIT								
24.080	51539-006H P1945 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
+ 243115	APU STARTER/GENERATOR								
24.085 OVERHAUL	23080-064 Y0866 REF: See Workcard	MOS HRS/MSC AFL APH	1000	TSO:0 TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938 3702		4702

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243137 (s) 24.090	NO. 1 BATTERY RG-390E 40684156 REF: AMM 24-30-151	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
243138 24.090	NO. 2 BATTERY RG-390E 40726187 REF: AMM 24-30-151	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
243139 24.210	NO. 3 BATTERY 100-0540-04 0811137 REF: AMM 24-30-155	MOS HRS/MSC AFL	48	TSN:2			28-MAY-2016 1973:56 1275	28-MAR-2020	
243140 24.220	NO. 4 BATTERY 100-0540-04 0705390 REF: AMM 24-30-155	MOS HRS/MSC AFL	48	TSN:2			28-MAY-2016 1973:56 1275	28-MAR-2020	
243141 24.230	NO. 5 BATTERY 100-0540-04 1127688 REF: AMM 24-30-155	MOS HRS/MSC AFL	48	TSN:2			28-MAY-2016 1973:56 1275	28-MAR-2020	
243142	NO. 6 BATTERY 100-0540-04 1123981 REF: AMM 24-30-155	MOS HRS/MSC AFL	48	TSN:8			28-MAY-2016 1973:56 1275	28-SEP-2019	
243143	NO. 7 BATTERY 100-0540-04 1127038 REF:	MOS HRS/MSC AFL	48	TSN:2			28-MAY-2016 1973:56 1275	28-MAR-2020	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243154	CAPACITY CHECK NO. 1 BATTERY								
24.090	RG-390E 40684156 REF: AMM 24-30-151	MOS HRS/MSC AFL	3	+30d/-30d			04-MAR-2019 2892:42 1938	04-JUN-2019	
243155	CAPACITY CHECK NO. 2 BATTERY								
24.090	RG-390E 40726187 REF: AMM 24-30-151	MOS HRS/MSC AFL	6				04-MAR-2019 2892:42 1938	04-SEP-2019	
243156	ENERGY LEVEL TEST NO. 3 BATTERY								
24.210	100-0540-04 0811137 REF: AMM 24-30-155	MOS HRS/MSC AFL	12				18-MAY-2018 2745 1838	18-MAY-2019	
243157	ENERGY LEVEL TEST NO. 4 BATTERY								
24.220	100-0540-04 0705390 REF: AMM 24-30-155	MOS HRS/MSC AFL	12				18-MAY-2018 2745 1838	18-MAY-2019	
243158	ENERGY LEVEL TEST NO. 5 BATTERY								
24.230	100-0540-04 1127688 REF: AMM 24-30-155	MOS HRS/MSC AFL	12				18-MAY-2018 2745 1838	18-MAY-2019	
+ 243159	ENERGY LEVEL TEST NO. 6 BATTERY								
	100-0540-04 1123981 REF: AMM 24-30-155	MOS HRS/MSC AFL	12				18-MAY-2018 2745 1838	18-MAY-2019	
243160	ENERGY LEVEL TEST NO. 7 BATTERY								
	100-0540-04 1127038 REF:	MOS HRS/MSC AFL	12				18-MAY-2018 2745 1838	18-MAY-2019	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243238	OVERVOLTAGE SENSOR								
24.110	E311TS CP-99584 REF: AMM 24-30-146	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243246	THERMAL SWITCH								
24.115	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243247	S CONTACTOR								
24.120	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243253	FORWARD U CONTACTOR								
24.120	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243259	J CONTACTOR								
24.125	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243265	K CONTACTOR								
24.125	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243271	AFT U CONTACTOR								
24.130	A848MAS CP-88539 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243277	L CONTACTOR								
24.135	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
243283	M CONTACTOR								
24.135	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
245001	BUS TIE (T) CONTACTOR								
24.140 OVERHAUL	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	5000	
245043	TEMPERATURE SENSOR								
24.170	548408-1 548408-02425 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
+ 250003 (s)	CHECK 3RD CREW MEMBERS SEAT						PKG		
25.115	PKG 91 REF: AFMS INSPECTION B6	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 250005 (s)	INSPECT EMERGENCY PACKS (IF FITTED)						PKG		
25.125	PKG 94 REF: AFMS INSPECTION E6	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		
+ 250006 (s)	CHECK FIRST AID KITS						PKG		
25.130	PKG 94 REF: AFMS INSPECTION E6	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 250007 (s)	OPERATIONAL CHECK CREW SEATS PKG 91	MOS					PKG		
25.145	REF: AFMS INSPECTION B4	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 250008 (s)	DETAILED CHECK CREW SEATS PKG 93	MOS					PKG		
25.150	REF: See Workcard	HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
251001	NO. 1 CREW SEAT 3A026-0013-00	MOS					PKG		
25.010	54299 REF: AMM 25-10-14	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
251002	NO. 2 CREW SEAT 3A026-0014-00	MOS					PKG		
25.010	54345 REF: AMM 25-10-14	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
251020	THROTTLE BOX DOIW01738-101A	MOS					PKG		
25.020	1218 REF:	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
251038	FLIGHT DECK CONTROLLER 922000-2	MOS					PKG		
25.135	H01004347 REF:	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		25-NOV-2008 11 10		
251057	NO. 1 DIGITAL AUDIO AMPLIFIER MODEL700-007	MOS					PKG		
25.050	3247 REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		07-NOV-2008 6:06 3		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251058	NO. 2 DIGITAL AUDIO AMPLIFIER								
25.050	MODEL700-007 3289 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 6:06 3		
+ 251060	INSPECT TIA MICROWAVE OVEN - CHECK WAVEGUIDE MOISTURE COVER								
	REF:	MOS HRS/MSC AFL	6 1500				04-MAR-2019 2892:42 1938	04-SEP-2019 4392:42	
251061	MICROWAVE OVEN								
25.055	400-1744-01 08-09-44153 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
251062	MICROWAVE OVEN WIRING CHASSIS FACIA AND DOORS								
INSPECT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	24	TSO:0			04-MAR-2019 2892:42 1938	04-MAR-2021	
256001	EMERGENCY LOCATOR TRANSMITTER								
25.025	453-5000 08678 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-OCT-2016 2148:39 1399		
+ 256005	INSPECT EMERGENCY LOCATOR TRANSMITTER								
25.025	453-5000 08678 REF:	MOS HRS/MSC AFL	12				26-SEP-2018 2843:23 1903	26-SEP-2019	
256006	ELT REMOTE (CONTROL UNIT) SWITCH								
25.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256007	REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY								
25.025	452-0133 380001-005 REF: See Workcard	MOS HRS/MSC AFL	60				04-MAR-2019 2892:42 1938	01-FEB-2024 M	
256009	EMERGENCY LOCATOR TRANSMITTER ANTENNA								
25.015	110-337 234929 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
+ 256010	FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER								
25.025	453-5000 08678 REF: See Workcard	MOS HRS/MSC AFL	12				04-MAR-2019 2892:42 1938	04-MAR-2020	
256011	REPLACE ELT REMOTE (CONTROL UNIT) SWITCH BATTERY								
25.030	PN SN-UNKNOWN REF: AMM 25-60-05	MOS HRS/MSC AFL	N/A						
256080	PILOT LIFE VEST								
	63600-505 L785901 REF:	MOS HRS/MSC AFL	O/C	TSN:125 TSN:2729:42 TSN:1827			25-APR-2018 2729:42 1827		
+ 256080A	RECERTIFY PILOT LIFE VEST								
	63600-505 L785901 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256081	COPILOT LIFE VEST								
	63600-505 L785875 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256081A	RECERTIFY COPILOT LIFE VEST 63600-505 L785875 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256082	CREW CABINET LIFE VEST 63600-105 L692858 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256082A	RECERTIFY CREW CABINET LIFE VEST 63600-105 L692858 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256083	NO. 1 LEFT CHAIR LIFE VEST 63600-105 L1029847 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256083A	RECERTIFY NO. 1 LEFT CHAIR LIFE VEST 63600-105 L1029847 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256084	NO. 2 LEFT CHAIR LIFE VEST 63600-105 L1029846 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256084A	RECERTIFY NO. 2 LEFT CHAIR LIFE VEST 63600-105 L1029846 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256085	NO. 1 RIGHT CHAIR LIFE VEST 63600-105 L692850 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256085A	RECERTIFY NO. 1 RIGHT CHAIR LIFE VEST 63600-105 L692850 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256086	NO. 2 RIGHT CHAIR LIFE VEST 63600-105 L1029773 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256086A	RECERTIFY NO. 2 RIGHT CHAIR LIFE VEST 63600-105 L1029773 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256087	NO. 3 RIGHT CHAIR LIFE VEST 63600-105 L692851 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256087A	RECERTIFY NO. 3 RIGHT CHAIR LIFE VEST 63600-105 L692851 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256088	NO. 1 DIVAN LIFE VEST 63600-105 L692856 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256088A	RECERTIFY NO. 1 DIVAN LIFE VEST 63600-105 L692856 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256089	NO. 2 DIVAN LIFE VEST 63600-105 L1029844 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256089A	RECERTIFY NO. 2 DIVAN LIFE VEST 63600-105 L1029844 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256090	NO. 3 DIVAN LIFE VEST 63600-105 L651135 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256090A	RECERTIFY NO. 3 DIVAN LIFE VEST 63600-105 L651135 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	
256091	LAVATORY LIFE VEST 63600-105 L1029849 REF:	MOS HRS/MSC AFL	O/C				25-APR-2018 2729:42 1827		
+ 256091A	RECERTIFY LAVATORY LIFE VEST 63600-105 L1029849 REF:	MOS HRS/MSC AFL	120				25-APR-2018 2729:42 1827	25-APR-2028	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256097	DIGITAL INTERFACE UNIT								
25.140	920055 G01004387 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
256301	EMERGENCY LOCATOR TRANSMITTER BATTERY								
	452-0133 380001-005 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
CHAPTER 26 FIRE PROTECTION									
+ 260001 (s)	CHECK AFT ENGINE FIRE EXTINGUISHER						PKG		
26.020	PKG 94 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		
+ 260001 (s)	CHECK FORWARD ENGINE FIRE EXTINGUISHER						PKG		
26.010	PKG 94 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		
+ 260002 (s)	FUNCTIONAL TEST REAR EQUIPMENT BAY OVERHEAT DETECTION SYSTEM						PKG		
26.035	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 260003 (s)	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER						PKG		
26.080	C352TS PKG 94 E-93773300 REF: AFMS INSPECTION E4	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019		
+ 260004 (s)	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER						PKG		
26.075	C352TS PKG 94 E-93773107 REF: AFMS INSPECTION E6	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 260008	FUNCTIONAL TEST SMOKE DETECTION SYSTEM (IF FITTED)								
26.115	REF: See Workcard	MOS HRS/MSC AFL	6	+10%	-81		04-MAR-2019 2892:42 1938	13-JUN-2019	01-JUL-2019
+ 260010 (s)	CHECK/FUNCTIONAL TEST APU FIRE EXTINGUISHER						PKG		
26.085	PKG 94 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		
261030	APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH								
26.120	PN SN-UNKNOWN REF: AMM 26-16-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
261031	APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH								
26.125	PN SN-UNKNOWN REF: AMM 26-16-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
261032	APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH								
26.130	PN SN-UNKNOWN REF: AMM 26-16-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
261033	APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH								
26.135	PN SN-UNKNOWN REF: AMM 26-16-03	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
+ 261034	TEST APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH								
26.120	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	60				26-SEP-2018 2843:23 1903	26-SEP-2023	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 261035	TEST APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH								
26.125	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	60				26-SEP-2018 2843:23 1903	26-SEP-2023	
+ 261036	TEST APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH								
26.130	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	60				26-SEP-2018 2843:23 1903	26-SEP-2023	
+ 261074	OVERHEAT DETECTION SWITCH TEST								
26.030	REF:	MOS HRS/MSC AFL	60				26-SEP-2018	26-SEP-2023	
261171	NO. 1 ENGINE ZONE 1 FIRE DETECTOR								
26.050	3001-112-900-400 90740 REF: AMM 26-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
261172	NO. 2 ENGINE ZONE 1 FIRE DETECTOR								
26.055	3001-112-900-400 90720 REF: AMM 26-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
261183	NO. 1 ENGINE ZONE 2 FIRE DETECTOR								
26.050	3001-133-900/500-6 042008 REF: AMM 26-10-12	MOS HRS/MSC AFL	O/C				15-DEC-2016 2148:39 1402		
261184	NO. 2 ENGINE ZONE 2 FIRE DETECTOR								
26.055	3001-133-900-500-6 91619 REF: AMM 26-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262001	ENGINE FORWARD FIRE EXTINGUISHER								
26.010	33200009-3 26643C1 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-FEB-2018 2651:48 1780		
262002	ENGINE AFT FIRE EXTINGUISHER								
26.020	33200009-3 27646C1 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-FEB-2018 2651:48 1780		
+ 262025	HYDROSTATIC TEST ENGINE FORWARD FIRE EXTINGUISHER								
26.010	33200009-3 26643C1 REF:	MOS HRS/MSC AFL	120				25-FEB-2018	25-FEB-2028	
+ 262026	HYDROSTATIC TEST ENGINE AFT FIRE EXTINGUISHER								
26.020	33200009-3 27646C1 REF:	MOS HRS/MSC AFL	120				25-FEB-2018	25-FEB-2028	
262027	FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE								
26.015	30900000M 2248VA REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			03-SEP-2018 2835:14 1893		
262028	AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE								
26.025	30900000M 2250VA REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			03-SEP-2018 2835:14 1893		
262029	FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE								
26.015	30900000M 2247VA REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			03-SEP-2018 2835:14 1893		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262030	AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE								
26.025	30900000M 2249VA REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			03-SEP-2018 2835:14 1893		
262037	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)								
26.015 LIFE LIMIT	30900000M 2248VA REF: AMM 26-20-22	MOS HRS/MSC AFL	120				03-SEP-2018	03-SEP-2028	
262038	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)								
26.025 LIFE LIMIT	30900000M 2250VA REF: AMM 26-20-22	MOS HRS/MSC AFL	120				03-SEP-2018	03-SEP-2028	
262049	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)								
26.015 LIFE LIMIT	30900000M 2247VA REF: AMM 26-20-22	MOS HRS/MSC AFL	120				03-SEP-2018	03-SEP-2028	
262050	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)								
26.025 LIFE LIMIT	30900000M 2249VA REF: AMM 26-20-22	MOS HRS/MSC AFL	120				03-SEP-2018	03-SEP-2028	
262061	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)								
26.015 LIFE LIMIT	30900000M 2248VA REF: AMM 26-20-22	MOS HRS/MSC AFL	180				19-FEB-2018	19-FEB-2033	
262062	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)								
26.025 LIFE LIMIT	30900000M 2250VA REF: AMM 26-20-22	MOS HRS/MSC AFL	180				19-FEB-2018	19-FEB-2033	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262073	REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT) 30900000M 2247VA REF: AMM 26-20-22	MOS HRS/MSC AFL	180				19-FEB-2018	19-FEB-2033	
26.015 LIFE LIMIT									
262074	REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT) 30900000M 2249VA REF: AMM 26-20-22	MOS HRS/MSC AFL	180				19-FEB-2018	19-FEB-2033	
26.025 LIFE LIMIT									
262091	CABIN PORTABLE FIRE EXTINGUISHER C352TS E-93773107 REF:	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
26.075									
+ 262103	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER C352TS E-93773107 REF:	MOS HRS/MSC AFL	144				10-JUL-2018	10-JUL-2030	
26.075									
262109	COCKPIT PORTABLE FIRE EXTINGUISHER C352TS E-93773300 REF:	MOS HRS/MSC AFL	O/C	TSN:2 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
26.080									
+ 262121	HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER C352TS E-93773300 REF:	MOS HRS/MSC AFL	144				11-JAN-2019	11-JAN-2031	
26.080									
262127	APU FIRE EXTINGUISHER 4190-01 462 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			20-DEC-2017 2577:06 1721		
26.085									

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262137	LEAK CHECK APU FIRE EXTINGUISHER								
26.085	REF: CMM 26-20-02	MOS HRS/MSC AFL	O/C				20-DEC-2017 2577:06 1721		
+ 262139	HYDROSTATIC TEST APU FIRE EXTINGUISHER								
26.085	4190-01 462 REF:	MOS HRS/MSC AFL	60				20-DEC-2017	20-DEC-2022	
262143	APU FORWARD CARTRIDGE								
26.060	30900000M SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			20-DEC-2017 2577:06 1721		
262145	REPLACE APU FORWARD CARTRIDGE (SERVICE LIFE)								
26.060 LIFE LIMIT	30900000M SN-UNKNOWN REF: CMM 26-20-02	MOS HRS/MSC AFL	120				06-SEP-2017	06-SEP-2027	
262157	REPLACE APU FORWARD CARTRIDGE (LIFE LIMIT)								
26.060 LIFE LIMIT	30900000M SN-UNKNOWN REF: CMM 26-20-02	MOS HRS/MSC AFL	180				01-MAY-2017	01-MAY-2032	
262190	FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE								
26.100	A1003(1) SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:7 TSN:0 TSN:0			04-SEP-2016 2109:48 1367		
262195	AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE								
26.105	A1003(1) SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:5 TSN:0 TSN:0			04-SEP-2016 2109:48 1367		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262199	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)								
26.100	A1003(1)	MOS	48				11-FEB-2016	11-FEB-2020	
LIFE LIMIT	SN-UNKNOWN REF: AMM 26-20-41	HRS/MSC AFL							
262200	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (LIFE LIMIT)								
26.105	A1003(1)	MOS	48				13-APR-2016	13-APR-2020	
LIFE LIMIT	SN-UNKNOWN REF: AMM 26-20-41	HRS/MSC AFL							
262201	REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE)								
26.100	A1003(1)	MOS	36				04-SEP-2016	04-SEP-2019	
LIFE LIMIT	SN-UNKNOWN REF: AMM 26-20-41	HRS/MSC AFL							
262202	REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE (SERVICE LIFE)								
26.105	A1003(1)	MOS	36				04-SEP-2016	04-SEP-2019	
LIFE LIMIT	SN-UNKNOWN REF: AMM 26-20-41	HRS/MSC AFL							
262301	SMOKE DETECTOR AMPLIFIER								
26.070	PN	MOS		TSN:0			03-OCT-2008		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
262307	FORWARD BAGGAGE COMPARTMENT SMOKE DETECTOR								
26.110	473597-14	MOS		TSN:0			25-NOV-2008		
	1732	HRS/MSC	O/C	TSN:0			11		
	REF: MMA 26-11-00	AFL		TSN:0			10		
262308	AFT BAGGAGE COMPARTMENT SMOKE DETECTOR								
26.110	473597-14	MOS		TSN:0			25-NOV-2008		
	1703	HRS/MSC	O/C	TSN:0			11		
	REF: MMA 26-11-00	AFL		TSN:0			10		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262309	VANITY SMOKE DETECTOR								
26.110	473597-14 1709 REF: MMA 26-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
CHAPTER 27 FLIGHT CONTROLS									
+ 270001	OPERATIONAL TEST AIRBRAKE SELECTOR LEVER BAULK								
27.265	REF: See Workcard	MOS HRS/MSC AFL	N/R				26-NOV-2008 0 0		
+ 270002 (s)	INSPECT LEFT WING FLAP VANE INNER						PKG		
27.490	PKG 92 REF: AFMS INSPECTION C9	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270003 (s)	INSPECT LEFT WING FLAP SCREW JACKS SCREW THREADS						PKG		
27.495	PKG 91 REF: AFMS INSPECTION B9	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270004 (s)	FUNCTIONAL TEST STALL WARNING AND IDENTIFICATION SYSTEM						PKG		
27.120	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270008 (s)	FUNCTIONAL TEST RUDDER BIAS STRUT HEATER MUFFS						PKG		
27.060	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270011 (s)	INSPECT GUST LOCKS/AILERONS AND ELEVATORS						PKG		
27.415	PKG 91 REF: AFMS INSPECTION B4	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270012 (s)	CHECK AND INSPECT RUDDER TRIM TAB AND ANTI SERVO TAB PKG 91	MOS					PKG		
27.450	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270013 (s)	CHECK AND INSPECT ELEVATORS AND TRIM TABS PKG 91	MOS					PKG		
27.485	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270014 (s)	INSPECT RUDDER AND ELEVATORS PRIMARY SURFACES PKG 91	MOS					PKG		
27.420	REF: AFMS INSPECTION B8	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270015 (s)	OPERATIONAL CHECK LEFT AILERON PRIMARY SURFACES PKG 91	MOS					PKG		
27.425	REF: AFMS INSPECTION B9	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270016 (s)	CHECK AND INSPECT LEFT AILERON TRIM AND SERVO TABS PKG 91	MOS					PKG		
27.435	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270017 (s)	CHECK LEFT FLAP SCREWJACK AND REDUCTION GEARBOX PKG 91	MOS					PKG		
27.500	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270018 (s)	INSPECT LEFT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES PKG 91	MOS					PKG		
27.550	REF: AFMS INSPECTION B9	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270019 (s)	CHECK FLAP CONTROL UNIT PKG 91	MOS					PKG		
27.525	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270020 (s)	OPERATE FLAP CONTROL UNIT PKG 91	MOS					PKG		
27.520	REF: AFMS INSPECTION B9	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270021 (s)	INSPECT LEFT FLAP DRIVE SHAFTS PKG 91	MOS					PKG		
27.510	REF: AFMS INSPECTION B9	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270022 (s)	OPERATIONAL CHECK RIGHT AILERON PRIMARY SURFACES PKG 91	MOS					PKG		
27.425	REF: AFMS INSPECTION B10	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270023 (s)	CHECK AND INSPECT RIGHT AILERON SERVO TABS PKG 91	MOS					PKG		
27.435	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270024 (s)	CHECK RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX PKG 91	MOS					PKG		
27.500	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270025 (s)	INSPECT RIGHT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES PKG 91	MOS					PKG		
27.550	REF: AFMS INSPECTION B10	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270026 (s)	INSPECT RIGHT FLAP DRIVE SHAFTS						PKG		
27.510	PKG 91 REF: AFMS INSPECTION B10	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270027 (s)	FUNCTIONAL TEST FLAP CONTROL SYSTEM						PKG		
27.200	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270028 (s)	FUNCTIONAL TEST AIRBRAKE AND LIFT DUMP SYSTEM						PKG		
27.260	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 270030 (s)	CHECK ELEVATOR TRIM SERVO						PKG		
27.095	PKG 92 REF: AFMS INSPECTION C2	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270032 (s)	CHECK AILERON AUTOPILOT SERVO CONTROL CABLES						PKG		
27.440	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270033 (s)	INSPECT ELEVATOR CONTROL SYSTEM BALANCE/FEEL SPRING						PKG		
27.100	PKG 92 REF: AFMS INSPECTION C4	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270034 (s)	CHECK ELEVATOR PRIMARY CONTROL CABLES						PKG		
27.460	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270035 (s)	CHECK FLAP CONTROL CABLES						PKG		
27.540	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270036 (s)	CHECK ELEVATOR PRIMARY AND ELEVATOR TRIM CONTROL CABLES						PKG		
27.465	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270037 (s)	CHECK RUDDER PRIMARY AND RUDDER TRIM CONTROL CABLES						PKG		
27.455	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270038 (s)	CHECK ELEVATOR AUTOPILOT SERVO CONTROL CABLES						PKG		
27.475	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270039 (s)	CHECK RUDDER AUTOPILOT SERVO CONTROL CABLES						PKG		
27.445	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270040 (s)	CHECK ELEVATOR AUTOPILOT TRIM-SERVO CONTROL CABLES						PKG		
27.480	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270041 (s)	INSPECT ELEVATOR TRIM CABLES						PKG		
27.470	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270042 (s)	CHECK LEFT AILERON PRIMARY AND TRIM CONTROL CABLES						PKG		
27.430	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270043 (s)	INSPECT LEFT FLAP DRIVE SHAFT UNIVERSAL JOINT						PKG		
27.565	PKG 92 REF: AFMS INSPECTION C9	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270044 (s)	CHECK LEFT FLAP BEVEL DRIVE ASSEMBLY						PKG		
27.535	PKG 92 REF: AFMS INSPECTION C9	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270045 (s)	CHECK FLAP CONTROL UNIT BAULK RELEASE CABLE						PKG		
27.515	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270046 (s)	CHECK FLAP/AIRBRAKE BAULK BOBBIN						PKG		
27.575	PKG 92 REF: AFMS INSPECTION C9	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270047 (s)	CHECK FLAP SPRING DRUM PULLEY-LEVER						PKG		
27.555	PKG 92 REF: AFMS INSPECTION C9	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270048 (s)	CHECK LEFT FLAP SCREWJACK/REDUCTION GEARBOX						PKG		
27.505	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270049 (s)	CHECK LEFT FLAP SYNCHRONIZING SYSTEM						PKG		
27.530	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270050 (s)	CHECK LEFT AIRBRAKE CONTROL CABLES						PKG		
27.570	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270051 (s)	CHECK RIGHT AILERON PRIMARY AND TRIM CONTROL CABLES						PKG		
27.430	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270052 (s)	INSPECT RIGHT FLAP DRIVE SHAFT UNIVERSAL JOINT						PKG		
27.565	PKG 92 REF: AFMS INSPECTION C10	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270053 (s)	CHECK RIGHT FLAP BEVEL DRIVE ASSEMBLY						PKG		
27.535	PKG 92 REF: AFMS INSPECTION C10	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270054 (s)	CHECK RIGHT FLAP SCREWJACK/REDUCTION GEARBOX						PKG		
27.505	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270055 (s)	CHECK RIGHT FLAP SYNCHRONIZING SYSTEM						PKG		
27.530	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270056 (s)	CHECK RIGHT AIRBRAKE CONTROL CABLES						PKG		
27.570	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 270057 (s)	CHECK FLAP CONTROL FORWARD SPRING STRUT						PKG		
27.560	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 270058 (s)	CHECK FLAP CONTROL INPUT-CIRCUIT						PKG		
27.210	PKG 93 REF: AFMS INSPECTION D4	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 270059 (s)	INSPECT CONTROL CABLE PRESSURE SEALS AT REAR PRESSURE BULKHEAD						PKG		
27.545	PKG 94 REF: AFMS INSPECTION E7	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		
270060 (s)	REPLACE FLAP AUXILIARY HYDRAULIC SYSTEM SUPPLY TO FLAP CONTROL UNIT FILTER						PKG		
27.215	PKG 93 REF: AFMS INSPECTION D10	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 270061	CHECK FLIGHT CONTROL CABLES TENSION								
27.010	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	O/C				10-DEC-2009 157:48 135		
+ 270063	LUBRICATE/CLEAN SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)								
27.030	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	N/R				03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 270064 (s)	INSPECT RIGHT WING FLAP VANE INNER						PKG		
27.490	PKG 92	MOS					27-JUN-2015		
	REF: AFMS INSPECTION C10	HRS/MSC	1600	+50/-50			1643:39		
		AFL					1058		
+ 270065 (s)	INSPECT RIGHT WING FLAP SCREWJACKS SCREW THREADS						PKG		
27.495	PKG 91	MOS					04-MAR-2019		
	REF: AFMS INSPECTION B10	HRS/MSC	800	+40/-10			2892:42		
		AFL					1938		
+ 270066 (s)	INSPECT LEFT AILERON CONTROL CABLE PRESSURE SEALS						PKG		
27.600	PKG 91	MOS					04-MAR-2019		
	REF: AFMS INSPECTION B9	HRS/MSC	800	+40/-10			2892:42		
		AFL					1938		
+ 270067 (s)	INSPECT RIGHT AILERON CONTROL CABLE PRESSURE SEALS						PKG		
27.605	PKG 91	MOS					04-MAR-2019		
	REF: AFMS INSPECTION B10	HRS/MSC	800	+40/-10			2892:42		
		AFL					1938		
+ 270068	LUBRICATE/CLEAN AILERON SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)								
27.610		MOS					26-NOV-2008		
	REF: AFMS INSPECTION G	HRS/MSC	N/R				0		
		AFL					0		
+ 270069	LUBRICATE/CLEAN ELEVATOR SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)								
27.615		MOS					07-NOV-2011		
	REF: AFMS INSPECTION G	HRS/MSC	N/R				753:05		
		AFL					541		
+ 270070	LUBRICATE/CLEAN RUDDER SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)								
27.620		MOS					26-NOV-2008		
	REF: GENERIC NO REF	HRS/MSC	N/R				0		
		AFL					0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270100	LEFT CONTROL COLUMN								
27.015	25-8CF53-217A PPLA/DH/2467 REF: AMM 27-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
270102	RIGHT CONTROL COLUMN								
27.015	25-8CF55-215A PPLA/DH/2470 REF: AMM 27-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
271001	LEFTAILERON								
27.020	25-8WG2001-3A DHB2035 REF: AMM 27-10-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
271002	RIGHTAILERON								
27.020	25-8WG2001-3A DHB2014 REF: AMM 27-10-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
271025	AILERON TRIM SCREWJACK								
27.025	25-8CW49-43A BPEB/DHB/25887 REF: AMM 27-10-71	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272001	RUDDER								
27.045	25-8TR105-11A SD-DH205 REF: AMM 27-20-23	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272019	RUDDER TRIM JACK								
27.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272020	RUDDER GEARED TAB								
27.125	25TR209AF CAVP08F118 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272021	RUDDER TRIM TAB								
27.285	25TR221AF CAVP08F074 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272022	LEFT RUDDER PEDAL ASSEMBLY								
27.065	25-8CF549-1A BPEB/DHB/25618 REF: AMM 27-20-35	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272023	RIGHT RUDDER PEDAL ASSEMBLY								
27.065	25-8CF549-2A BPEB/DHB/25618 REF: AMM 27-20-35	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272049	LEFT RUDDER BIAS STRUT								
27.055	ACA1218 EPB124 REF: AMM 27-20-51	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272050	RIGHT RUDDER BIAS STRUT								
27.055	ACA1218 EPB562 REF: AMM 27-20-51	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272066	LEFT RUDDER BIAS STRUT HEATER MUFF								
27.060	259W03486-603 2120 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272067	RIGHT RUDDER BIAS STRUT HEATER MUFF								
27.061	259W03486-607 2101 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272103	LEFT RUDDER BIAS PRESSURE SWITCH								
27.290	HTE690011 17081271 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
272105	RIGHT RUDDER BIAS PRESSURE SWITCH								
27.290	HTE690011 17081273 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273001	LEFT ELEVATOR								
27.070	25-8TE1-1A SD-DH1739 REF: AMM 27-30-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273002	RIGHT ELEVATOR								
27.070	25-8TE1-2A SD-DH1724 REF: AMM 27-30-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273021	ELEVATOR TRIM SERVOMOTOR								
27.085 OVERHAUL	622-3260-001 33PFW REF: AMM 27-30-61	MOS HRS/MSC AFL	3500	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	3500	
273022	ELEVATOR TRIM SERVOMOTOR MOUNT ASSEMBLY								
27.701	PN SN-UNKNOWN REF: AMM 22-10-30	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273025	LEFT ELEVATOR TRIM JACK								
27.080	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273026	RIGHT ELEVATOR TRIM JACK								
27.080	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273040	LEFT ELEVATOR TRIM TAB								
27.090	25-8TE3-1A CAVP08E101 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273041	RIGHT ELEVATOR TRIM TAB								
27.090	25-8TE3-2A CAVP08E045 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273104	LEFT STICK SHAKER								
27.140	B1443-2 9760 REF: AMM 27-33-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273105	RIGHT STICK SHAKER								
27.140	B1443-2 9759 REF: AMM 27-33-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273110	FORWARD STALL WARNING DETECTOR								
27.145	C87706-1 1476 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273111	AFT STALL WARNING DETECTOR								
27.145	C87706-1 1477 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273115	NO. 1 STALL WARNING VANE								
27.150	1703-12 3001 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273116	NO. 2 STALL WARNING VANE								
27.150	1703-12 2999 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
273121	THIRD CHANNEL STALL DETECTOR								
27.305	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
275001	LEFT FLAP								
27.155	DOIW01431-1A SDDH1753 REF: AMM 27-50-151	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
275002	RIGHT FLAP								
27.155	DOIW01432-2A SDDH1764 REF: AMM 27-50-151	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
275025	LEFT FLAP SCREWJACK AND REDUCTION GEARBOX								
27.160 OVERHAUL	25-8CW159AC BPEB/DHB26154 REF: AMM 27-50-141	MOS HRS/MSC AFL	4000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		4000

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275026	RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX								
27.160	25-8CW161AC	MOS		TSN:0			03-OCT-2008		
OVERHAUL	BPEB/DHB26171 REF: AMM 27-50-141	HRS/MSC AFL	4000	TSN:0 TSN:0			0 0		4000
275049	LEFT OUTBOARD FLAP VANE								
27.165	25-8WF13-65A	MOS		TSN:0			03-OCT-2008		
	SDDH1773 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
275050	RIGHT OUTBOARD FLAP VANE								
27.170	25-8WF13-66A	MOS		TSN:0			03-OCT-2008		
	SDDH1764 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
275051	LEFT INBOARD FLAP VANE								
27.165	25-7WF101A	MOS		TSN:0			03-OCT-2008		
	SDDH1797 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
275052	RIGHT INBOARD FLAP VANE								
27.170	25-7WF102A	MOS		TSN:0			03-OCT-2008		
	SDDH1024 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
275057	LEFT FLAP BEVEL SHAFT ASSEMBLY								
27.175	25CF2667AD	MOS		TSN:0			03-OCT-2008		
	BPEB/DHB25934 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
275058	RIGHT FLAP BEVEL SHAFT ASSEMBLY								
27.175	25CF2668A/D	MOS		TSN:0			03-OCT-2008		
	BPEB/DHB25946 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275073	FLAP CONTROL UNIT								
27.180 OVERHAUL	614MK2 614H246 REF: AMM 27-50-121	MOS HRS/MSC AFL	6000	TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938		7938
275074	FLAP DESIGN UNIT								
27.590	25-8NW111-1A 83605 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
275085	FLAP SYNCHRONIZING SYSTEM RECEIVER								
27.185 OVERHAUL	617MK4 1527 REF: AMM 27-50-162	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		4500
275091	FLAP POSITION INDICATOR								
27.190	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
275097	FLAP POSITION TRANSMITTER								
27.195	S132-3-22 83028 REF: AMM 27-50-181	MOS HRS/MSC AFL	O/C	TSO:10 TSO:0 TSO:0			14-JAN-2010 217:18 166		
275145	LEFT FLAP INBOARD FORWARD SYNCHRO CABLE								
27.220 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		5000
275146	RIGHT FLAP INBOARD FORWARD SYNCHRO CABLE								
27.225 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		5000

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275147	LEFT FLAP INBOARD AFT SYNCHRO CABLE								
	PN	MOS		TSN:0			03-OCT-2008		
27.220	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	5000	TSN:0			0		5000
<hr/>									
275148	RIGHT FLAP INBOARD AFT SYNCHRO CABLE								
	PN	MOS		TSN:0			03-OCT-2008		
27.225	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	5000	TSN:0			0		5000
<hr/>									
275149	LEFT FLAP OUTBOARD FORWARD SYNCHRO CABLE								
	PN	MOS		TSN:0			03-OCT-2008		
27.230	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	5000	TSN:0			0		5000
<hr/>									
275150	RIGHT FLAP OUTBOARD FORWARD SYNCHRO CABLE								
	PN	MOS		TSN:0			03-OCT-2008		
27.235	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	5000	TSN:0			0		5000
<hr/>									
275151	LEFT FLAP OUTBOARD AFT SYNCHRO CABLE								
	PN	MOS		TSN:0			03-OCT-2008		
27.230	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	5000	TSN:0			0		5000
<hr/>									
275152	RIGHT FLAP OUTBOARD AFT SYNCHRO CABLE								
	PN	MOS		TSN:0			03-OCT-2008		
27.235	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	5000	TSN:0			0		5000
<hr/>									
276001	LEFT UPPER AIRBRAKE								
	PN	MOS		TSN:0			03-OCT-2008		
27.240	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 27-61-21	AFL		TSN:0			0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276002	RIGHT UPPER AIRBRAKE								
27.245	PN SN-UNKNOWN REF: AMM 27-61-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
276003	LEFT LOWER AIRBRAKE								
27.240	PN SN-UNKNOWN REF: AMM 27-61-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
276004	RIGHT LOWER AIRBRAKE								
27.245	PN SN-UNKNOWN REF: AMM 27-61-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
276039	LEFT AIRBRAKE JACK								
27.250 OVERHAUL	AIR46520-2 APB003431 REF: AMM 27-61-31	MOS HRS/MSC AFL	3000	TSO:0 TSO:0 TSO:0			20-DEC-2017 2577:06 1721	5577:06	
276040	RIGHT AIRBRAKE JACK								
27.255 OVERHAUL	AIR46521-2 APB032122 REF: AMM 27-61-31	MOS HRS/MSC AFL	3000	TSO:0 TSO:0 TSO:0			20-DEC-2017 2577:06 1721	5577:06	
276051	LEFT AIRBRAKE JACK BODY								
27.250 LIFE LIMIT	PN SN-UNKNOWN REF: AMM 27-61-31	MOS HRS/MSC AFL	25000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	25000	
276052	RIGHT AIRBRAKE JACK BODY								
27.255 LIFE LIMIT	PN SN-UNKNOWN REF: AMM 27-61-31	MOS HRS/MSC AFL	25000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	25000	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276063	LEFT AIRBRAKE JACK EYE END								
27.250	PN SN-UNKNOWN REF: AMM 27-61-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
276064	RIGHT AIRBRAKE JACK EYE END								
27.255	PN SN-UNKNOWN REF: AMM 27-61-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
276110	STICK PUSHER								
27.585	104829001 SA0804113 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 28 FUEL									
+ 280001 (s)	FLOW CHECK FUEL TRANSFER SYSTEM, WING TANKS						PKG		
28.075	PKG 91 REF: AFMS INSPECTION B1	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 280002 (s)	CHECK FUEL VALVE CONTROL CABLES						PKG		
28.010	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 280003 (s)	FUNCTIONAL TEST LP VALVES						PKG		
28.050	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
280004 (s)	INSPECT/CLEAN OR REPLACE APU FUEL INLET FILTER ELEMENT (IF FITTED)						PKG		
28.085	PKG 93 REF: AFMS INSPECTION D7	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 280005 (s)	VISUALLY INSPECT LEFT WING SUCTION PIPE STRAINERS						PKG		
28.165	PKG 92	MOS					27-JUN-2015		
	REF: AFMS INSPECTION C9	HRS/MSC	1600	+50/-50			1643:39		
		AFL					1058		
+ 280006 (s)	VISUALLY INSPECT LEFT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS						PKG		
28.170	PKG 92	MOS					27-JUN-2015		
	REF: AFMS INSPECTION C9	HRS/MSC	1600	+50/-50			1643:39		
		AFL					1058		
+ 280007 (s)	VISUALLY INSPECT RIGHT WING SUCTION PIPE STRAINERS						PKG		
28.165	PKG 92	MOS					27-JUN-2015		
	REF: AFMS INSPECTION C10	HRS/MSC	1600	+50/-50			1643:39		
		AFL					1058		
+ 280008 (s)	VISUALLY INSPECT RIGHT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS						PKG		
28.170	PKG 92	MOS					27-JUN-2015		
	REF: AFMS INSPECTION C10	HRS/MSC	1600	+50/-50			1643:39		
		AFL					1058		
+ 280010	CHECK CABLE TENSION OF FUEL CONTROL VALVES								
28.020		MOS					10-DEC-2009		
	REF: See Workcard	HRS/MSC	O/C				157:48		
		AFL					135		
+ 280014	CHECK LEFT BOOST PUMP BRUSH LENGTH								
28.080	2C40-2	MOS					26-NOV-2008		
	5BD99	HRS/MSC	N/R				0		
	REF: AFMS INSPECTION C9	AFL					0		
+ 280015	CHECK RIGHT BOOST PUMP BRUSH LENGTH								
28.080	2C40-2	MOS					26-NOV-2008		
	5BD100	HRS/MSC	N/R				0		
	REF: AFMS INSPECTION C10	AFL					0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281067	VENTRAL FUEL TANK								
28.015	DOIW00325-1A PZL-DH-128 REF: AMM 28-10-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282001	LEFT WING HIGH LEVEL FLOAT SWITCH								
28.025	3515000-107 38050025 REF: AMM 28-22-143	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-APR-2011 596:12 452		
282002	RIGHT WING HIGH LEVEL FLOAT SWITCH								
28.025	3515000-107 4080774 REF: AMM 28-22-143	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282004	LOW PRESSURE FUEL COCK VALVE								
28.191	PN SN-UNKNOWN REF: AMM 28-20-52	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282005	LEFT FUEL COCK								
28.180	7913003K 8081616 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282006	RIGHT FUEL COCK								
28.180	7913003K 55070840 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282007	LEFT FUEL ACTUATOR								
28.185	HTE9044-001 M297GB0706 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				14-OCT-2010 436:30 359		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282008	RIGHT FUEL ACTUATOR								
28.185	HTE9044-001 M111GB0208 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282009	LEFT FUEL NON-RETURN VALVE								
28.190	9807870 14080786 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282010	RIGHT FUEL NON-RETURN VALVE								
28.190	9807870 14080787 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282011	LEFT FUEL NON-RETURN VALVE								
28.192	HTE4350 M0157VNR0408 REF: AMM 28-20-32	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282012	RIGHT FUEL NON-RETURN VALVE								
28.193	HTE4350 M0158VNR0408 REF: AMM 28-20-32	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282025	APU FUEL PRESSURE SWITCH								
28.030	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282053	LEFT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE								
28.035	PN SN-UNKNOWN REF: AMM 28-20-32	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282054	RIGHT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE								
28.035	PN SN-UNKNOWN REF: AMM 28-20-32	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282253	LEFT HAND LP FUEL VALVE								
28.045	HTE1984-1 11081263 REF: AMM 28-20-52	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282254	RIGHT HAND LP FUEL VALVE								
28.045	HTE1984-1 10081875 REF: AMM 28-20-52	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282289	FUEL 3C VALVE								
28.055	HTE1984-1 11081686 REF: AMM 28-20-61	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282295	FUEL 4S VALVE								
28.060	HTE1984-1 11081265 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282301	VENTRAL TANK FUEL TRANSFER VALVE								
28.065	PN SN-UNKNOWN REF: AMM 28-20-78	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282343	LEFT BOOST PUMP								
28.080	2C40-2 5BD99 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282344	RIGHT BOOST PUMP								
28.080	2C40-2 5BD100 REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
282384	SINGLE-POINT PRESSURE CONTROL VALVE								
28.175	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284013	LEFT NO. 1 FUEL TANK UNIT								
28.100	0207KTU04 FR0542906 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284014	RIGHT NO.1 FUEL TANK UNIT								
28.100	0207KTU04 FR0542909 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284015	LEFT NO.2 FUEL TANK UNIT								
28.105	0204KTU2 FR0541807 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284016	RIGHT NO.2 FUEL TANK UNIT								
28.105	0204KTU2 FR0541806 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284017	LEFT NO.3 FUEL TANK UNIT								
28.110	0207KTU3 FR0533709 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284018	RIGHT NO.3 FUEL TANK UNIT								
28.110	0207KTU3 FR0533706 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284019	LEFT NO.4 FUEL TANK UNIT								
28.115	0204KTU4 FR0537504 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284020	RIGHT NO.4 FUEL TANK UNIT								
28.115	0204KTU4 FR050604 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284021	LEFT NO.5 FUEL TANK UNIT								
28.120	0204KTU5 FR0504608 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284022	RIGHT NO.5 FUEL TANK UNIT								
28.120	0204KTU5 FR0504609 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284023	LEFT NO.6 FUEL TANK UNIT								
28.125	0204KTU6 FR0537207 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284024	RIGHT NO.6 FUEL TANK UNIT								
28.125	0204KTU6 FR0537208 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284025	LEFT NO.7 FUEL TANK CONTENTS UNIT								
28.130	0204KTU7 FR0502807 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284026	RIGHT NO.7 FUEL TANK CONTENTS UNIT								
28.130	0204KTU7 FR0502806 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284115	LEFT FUEL QUANTITY INDICATOR								
28.140	PN SN-UNKNOWN REF: AMM 28-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284116	RIGHT FUEL QUANTITY INDICATOR								
28.140	PN SN-UNKNOWN REF: AMM 28-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284130	FUEL PRESSURE SWITCH								
28.194	HTE690009 18081282 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284139	VENTRAL TANK LOW LEVEL FLOAT SWITCH								
28.145	PN SN-UNKNOWN REF: AMM 28-44-33	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284145	VENTRAL TANK HIGH LEVEL FLOAT SWITCH								
28.150	35150000-149 FR010BL REF: AMM 28-44-33	MOS HRS/MSC AFL	O/C	TSR:6 TSR:0 TSR:0			13-DEC-2009 164:06 138		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284151	LEFT SURGE TANK FLOAT SWITCH								
28.155	3515000-106 9080737 REF: AMM 28-44-43	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
284152	RIGHT SURGE TANK FLOAT SWITCH								
28.155	3515000-106 9080740 REF: AMM 28-44-43	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 29 HYDRAULIC POWER									
290003 (s)	REPLACE HYDRAULIC SUCTION FILTER ELEMENT						PKG		
29.070	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 290004 (s)	FUNCTIONAL TEST MAIN HYDRAULIC SYSTEM						PKG		
29.075	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 290005 (s)	OPERATIONAL TEST LANDING GEAR AND FLAPS EMERGENCY LOWERING SYSTEM						PKG		
29.115	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
290006 (s)	DRAIN HYDRAULIC TANK PRESSURIZATION SYSTEM						PKG		
29.160	PKG 92 REF: AFMS INSPECTION C7	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 290007 (s)	TEST FLAPS, AIRBRAKES, LANDING GEAR, NOSEWHEEL STEERING, NOSE LEG SELF-CENTERING						PKG		
29.165	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 290008 (s)	CHECK EMERGENCY BRAKE SYSTEM LEAK RATE						PKG		
29.175	PKG 92 REF: AFMS INSPECTION C12	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 290009 (s)	FUNCTIONAL TEST AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM						PKG		
29.180	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 290010 (s)	FUNCTIONAL TEST HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM						PKG		
29.170	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
290011 (s)	CLEAN FULL-FLOW RELIEF VALVE						PKG		
29.005	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 290012 (s)	INSPECT HYDRAULIC POWER HIGH TEMPERATURE WARNING SYSTEM						PKG		
29.145	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
291018	PRESSURE REGULATOR VALVE								
29.010	PAS129-163 HAY0291 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
291025	NO. 1 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE								
29.015	AIR87246-0 APB080420 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291026	NO. 2 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE								
29.015	AIR87246-0 APB080413 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291037	LEFT HYDRAULIC SUCTION VALVE								
29.020	7907015E 14081237 REF: AMM 29-10-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291038	RIGHT HYDRAULIC SUCTION VALVE								
29.020	7907015E 6082243 REF: AMM 29-10-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291049	NO. 1 FULL FLOW HYDRAULIC RELIEF VALVE								
29.025 OVERHAUL	AIR45394-0 APB072542 REF:	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		4500
291050	NO. 2 FULL FLOW HYDRAULIC RELIEF VALVE								
29.025 OVERHAUL	AIR45394-0 APB080805 REF:	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		4500
291061	NO. 1 DUNLOP VALVE								
29.106	AC69536 ENW468 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291062	NO. 2 DUNLOP VALVE								
29.106	AC69536 ENX025 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291063	NO. 3 DUNLOP VALVE								
29.106	AC69536 EKX498 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938		
291073	PRESSURE MAINTAINING VALVE								
29.030 OVERHAUL	AIR45474-0 APB080384 REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	5000	
291079	GROUND SERVICE HANDPUMP SUPPLY NONRETURN VALVE								
29.035	AIR48026-0-1 APB080747 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291091	MAIN HYDRAULIC RESERVOIR								
29.040	PN SN-UNKNOWN REF: AMM 29-10-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291096	HYDRAULIC PRESSURE GAUGE								
29.045	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291103	MAIN HYDRAULIC ACCUMULATOR								
29.050	AIR45574-4 APB081648 REF: AMM 29-10-81	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291109	EMERGENCY BRAKE ACCUMULATOR								
29.055	AIR45574-4 APB071088 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291131	HYDRAULIC FILTER								
29.060	MFHA15104 BF0810194 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291132	PRESSURE FILTER ASSEMBLY								
29.065	B2125-H4 FYH213149 REF: AMM 29-10-61	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291163	NO. 1 ENGINE HYDRAULIC PUMP								
29.080	4202203 CA697 REF: AMM 29-10-54	MOS HRS/MSC AFL	O/C				15-DEC-2016 2148:39 1402		
291164	NO. 2 ENGINE HYDRAULIC PUMP								
29.080	4202203 T42 REF: AMM 29-10-54	MOS HRS/MSC AFL	O/C				15-DEC-2016 2148:39 1402		
291170	HYDRAULIC RESERVOIR RELIEF VALVE								
29.117	AIR87236-0 APB080343 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291178	BANJO ASSEMBLY								
29.118	FRH460001C 7080292 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291182	GROUND SERVICING HANDPUMP								
29.085	AIR45424-0 APB072185 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291186	NO. 1 NON-RETURN TANK PRESSURE VALVE								
29.090	HTE4853 49071054 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
291193	NO. 2 NON-RETURN TANK PRESSURE VALVE								
29.090	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
292001	EMERGENCY HYDRAULIC TANK								
29.095	25HC161D WN150083/7 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
292003	SUCTION FILTER ASSEMBLY								
29.100	AIR87366-0 BF08-0060 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
292007	EMERGENCY HYDRAULIC HAND PUMP								
29.105	AIR45448-1 APB080891 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
292013	AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM SWITCH								
29.110	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
292031	EMERGENCY TANK ON/OFF HAND PUMP VALVE								
29.120	AIR45446-2 APB063334 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
292037	EMERGENCY SYSTEM CHECK VALVE								
29.125	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
293001	NO. 1 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH								
29.130	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
293002	NO. 2 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH								
29.130	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
293013	EMERGENCY BRAKE LOW PRESSURE WARNING SWITCH								
29.135 OVERHAUL	TP42001 1945 REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	5000	
293019	HYDRAULIC PRESSURE TRANSDUCER								
29.140	695-4-20 74679275 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
293024	HYDRAULIC SYSTEM OVERTEMPERATURE SWITCH								
29.145	PN SN-UNKNOWN REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
294001	LEFT HYDRAULIC NON-RETURN VALVE								
29.183	9840078J 10081731 REF: AMM 29-10-68	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
294002	RIGHT HYDRAULIC NON-RETURN VALVE								
29.184	9840078J 10081730 REF: AMM 29-10-68	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
294003	NO. 1 HYDRAULIC NON-RETURN VALVE								
29.186	9840000J 15081390 REF: AMM 29-10-68	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
294004	NO. 2 HYDRAULIC NON-RETURN VALVE								
29.187	9840000J 15081388 REF: AMM 29-10-68	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
294005	HYDRAULIC NON-RETURN VALVE								
29.188	AIR45468-0 APB073412 REF: AMM 29-10-68	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
294006	HYDRAULIC RELIEF VALVE								
29.189	AIR45418-0 APB071729 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
294007	LEFT HYDRAULIC NON-RETURN VALVE								
29.190	AIR87246-0 APB080420 REF: AMM 29-10-68	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
294008	RIGHT HYDRAULIC NON-RETURN VALVE								
29.191	PN SN-UNKNOWN REF: AMM 29-10-68	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

CHAPTER 30 ICE AND RAIN PROTECTION

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 300001 (s)	FUNCTIONAL TEST ROTARY ICE DETECTOR PKG 91	MOS					PKG		
30.085	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 300002 (s)	OPERATIONAL TEST WINDSHIELD ELECTRICAL DE-ICE SYSTEM PKG 92	MOS					PKG		
30.080	REF: See Workcard	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
300003 (s)	REPLACE AIRFRAME DE-ICING FILTER ELEMENT PKG 91	MOS					PKG		
30.020	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 300004 (s)	FUNCTIONAL TEST PITOT HEAD AND STATIC PLATE HEATERS PKG 92	MOS					PKG		
30.065	REF: See Workcard	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
300005 (s)	REPLACE AIRFRAME DE-ICING PUMP SUCTION FILTER PKG 92	MOS					PKG		
30.045	REF: See Workcard	HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 300007	PURGE ICE PROTECTION SYSTEM	MOS	1						
30.090	REF: See Workcard	HRS/MSC AFL					04-MAR-2019 2892:42 1938	04-APR-2019	
301001	TKS DE-ICER TANK 08301-01	MOS							
30.010	REF: AMM 30-10-35	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301007	AIRFRAME DE-ICING PUMP ASSEMBLY								
30.015	XA9511E009 AST08A55 REF: AMM 30-10-43	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
301013	AIRFRAME DE-ICING FILTER ASSEMBLY								
30.020	PN SN-UNKNOWN REF: AMM 30-10-52	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
301025	DE-ICING VALVE ASSEMBLY								
30.025	FV131-1 AST08C924 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
301037	DE-ICING SYSTEM CONTENTS GAUGE								
30.030	S458-3-191T 83574 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 6:06 3		
301043	DE-ICING SYSTEM CONTENTS FLOAT								
30.035	FRH070001 47070239 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
301063	EMPENNAGE TKS PROPORTION UNIT								
30.050	PN SN-UNKNOWN REF: AMM 30-10-25	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
301067	TKS VENT VALVE								
30.055	FV141 AST08C953 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301069	TKS PRESSURE SWITCH								
30.060	P067D075 AST08D1218 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
304019	NO. 1 WINDSCREEN (A PANEL) CONTROLLER								
30.070	ND0075-2011 L421769 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-DEC-2014 1512:55 984		
304020	NO. 2 WINDSCREEN (A PANEL) CONTROLLER								
30.070	ND0075-2011 L380089 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-JAN-2010 217:42 167		
304022	NO. 1 WINDSCREEN (B PANEL) CONTROLLER								
30.075	ND0075-2001 L375602 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
304023	NO. 2 WINDSCREEN (B PANEL) CONTROLLER								
30.075	ND0075-2001 L375600 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
308001	ROTARY ICE DETECTOR								
30.085	NF0075-667 L375655 REF: AMM 30-80-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
+ 310001 (s)	CHECK FLIGHT DATA RECORDER (IF FITTED)						PKG		
31.085	PKG 94 REF: AFMS INSPECTION E1	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31002	LIGHTNING SENSOR ANTENNA								
31.015	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
310100	LIGHTNING PROCESSOR UNIT								
31.010	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
311001	TKS TIMER								
31.020	100-1805-02 08A385 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
312001	PILOT CLOCK								
31.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
312002	COPILOT CLOCK								
31.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
312008	O.A.T. INDICATOR								
31.030	2141-01-0014 82815 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
312009	PITOT AMMETER								
31.035	2132-01-0062 82967 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313003	NO. 1 CURRENT MONITOR-								
31.300	E37040S 5207 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313004	NO. 2 CURRENT MONITOR-								
31.300	E37040S 5183 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313005	LEFT CURRENT LEVEL INDICATOR								
31.040	770-537 2796 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313006	RIGHT CURRENT LEVEL INDICATOR								
31.040	770-537 2805 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313007	CABIN TEMPERATURE INDICATOR								
31.045	2132-01-0015 82788 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313008	DC VOLTMETER								
31.050	2132-1-12 82771 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313009	LEFT DC AMMETER								
31.055	2132-01-0013 83242 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313010	AC VOLTMETER								
31.060	2132-1-14 82682 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938		
313011	RIGHT DC AMMETER								
31.065	2132-1-13 82902 REF:	MOS HRS/MSC AFL	O/C				21-DEC-2017 2577:06 1721		
313012	FLIGHT DATA ACCELEROMETER								
31.120	971-4193-001 12376 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 0 0		
313014	DUCT AIR TEMPERATURE INDICATOR								
31.070	2132-01-0018 82778 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313015	TEMPERATURE SELECTOR								
31.075	25-6MC415 627578-01729 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313020	FUEL PROCESSOR UNIT								
31.080	0107KPU1 FE065581 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313023	FLIGHT DATA RECORDER								
31.085	980-4710-003 ARFDR-02089 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313030	FILTER UNIT 25-9NF4027-645	MOS		TSN:0			03-OCT-2008		
31.303	L367283 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
313031	FILTER UNIT 25-9NF4027-647	MOS		TSN:0			03-OCT-2008		
31.303	L367484 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
313032	FILTER UNIT 25-9NF4027-649	MOS		TSN:0			03-OCT-2008		
31.303	L367446 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
313033	FILTER UNIT 25-9NF4027-651	MOS		TSN:0			03-OCT-2008		
31.303	L375574 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
313062	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON DK-120	MOS		TSN:0			03-JAN-2018		
31.085	AT78549 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0					
+ 313064	CLEAN/TEST FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON	MOS	24				04-MAR-2019	04-MAR-2021	
31.085	REF:	HRS/MSC AFL					2892:42 1938		
+ 313068	REPLACE FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY DK-120	MOS	72	TSI:0	10		03-JAN-2018	03-NOV-2024	
31.085	AT78549 REF:	HRS/MSC AFL							



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 313074 (s)	TEST FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON								
31.085	REF:	MOS HRS/MSC AFL	24				04-MAR-2019		
313101	ANGLE OF ATTACK INDICATOR COMPUTER								
31.095	C87705-4 948 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313109	NO. 1 ANGLE OF ATTACK INDEXER								
31.100	965-0113-003 3254 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313110	NO. 2 ANGLE OF ATTACK INDEXER								
31.100	965-0113-003 3256 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313201	BRAKE PRESSURE INDICATOR								
31.105	696-1-13 82907 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
313301	FATIGUE METER								
31.110	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	N/R	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
314008	NO. 1 INCLINOMETER								
31.115	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314009	NO. 2 INCLINOMETER								
31.115	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
314012	IAPS (ICC 3000) CARD CAGE								
31.125	822-1129-001 31RVB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
314014	MAINTENANCE DIAGNOSTIC COMPUTER								
31.130	822-1987-005 28JMV REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-FEB-2011 555:15 427		

CHAPTER 32 LANDING GEAR

+ 320001 (s)	TEST BRAKING SYSTEMS						PKG		
32.305	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320002 (s)	FUNCTIONAL TEST MAXARET UNITS						PKG		
32.370	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320003 (s)	CHECK NOSE GEAR LEG ASSEMBLY						PKG		
32.430	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320004 (s)	CHECK NOSE GEAR LEG LOCK AND CHANGE OVER MICROSWITCHES OPERATING MECHANISM						PKG		
32.435	PKG 91 REF: AFMS INSPECTION B12	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 320005 (s)	INSPECT NOSEWHEEL STEERING JACK						PKG		
32.470	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320006 (s)	INSPECT NOSE GEAR RETRACTION AND STEERING SYSTEM SPRING STRUTS						PKG		
32.450	PKG 91 REF: AFMS INSPECTION B12	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320007 (s)	INSPECT NOSEWHEEL STEERING ON/OFF VALVE						PKG		
32.350	PKG 91 REF: AFMS INSPECTION B12	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320008 (s)	CHECK NOSE GEAR DRAG STAY ASSEMBLY						PKG		
32.440	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
320009 (s)	DETAIL INSPECT NOSEWHEEL STEERING JACK SELECTOR VALVE						PKG		
32.545	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320010 (s)	CHECK MAIN GEAR LEG ASSEMBLIES						PKG		
32.420	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320011 (s)	INSPECT MAIN LANDING GEAR SIDE-STAYS						PKG		
32.010	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 320012 (s)	CHECK MAIN LANDING GEAR TORQUE LINKS						PKG		
32.015	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320013 (s)	INSPECT MAIN LANDING GEAR DOORS						PKG		
32.460	PKG 91 REF: AFMS INSPECTION B12	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320014 (s)	INSPECT/CLEAN MAIN LANDING GEAR DOOR UPLOCK SPRING STRUTS						PKG		
32.425	PKG 91 REF: AFMS INSPECTION B12	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320015 (s)	INSPECT REVERSING VALVES AND OPERATING MECHANISMS						PKG		
32.445	PKG 91 REF: AFMS INSPECTION B12	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320016 (s)	CHECK STEERING SYSTEM CABLES AND CHAINS						PKG		
32.475	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 320017 (s)	CHECK NOSE LANDING GEAR RETRACTION SPRING STRUT						PKG		
32.180	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 320018 (s)	CHECK NOSEWHEEL STEERING SYSTEM SPRING STRUT BREAK-OUT LOAD						PKG		
32.350	PKG 92 REF: AFMS INSPECTION C12	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 320019 (s)	INSPECT/CLEAN STEERING SYSTEM FILTER ELEMENT						PKG		
32.385	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
320020 (s)	CLEAN FILTERS, HYDRAULIC SUPPLY (4 OFF)						PKG		
32.185	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
320021 (s)	CLEAN RESTRICTOR VALVES						PKG		
32.145	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 320022 (s)	CHECK BRAKE MASTER CYLINDERS						PKG		
32.465	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 320023 (s)	CHECK BRAKE HOSES TO MASTER CYLINDERS						PKG		
32.455	PKG 92 REF: AFMS INSPECTION C4	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
320024 (s)	REMOVE/INSPECT AXLE/MAXARET/MODULATOR/PLUNGER TUBE						PKG		
32.375	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 320027 (s)	VISUALLY INSPECT NOSE-WHEEL STEERING ON/OFF VALVE						PKG		
32.350	PKG 96 REF: AFMS INSPECTION G	MOS HRS/MSC AFL	48	+2m/-2m			21-DEC-2016 2148:39 1399		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 320028	INSPECT MAIN LANDING GEAR FAIRING STRUT								
32.035	REF: See Workcard	MOS HRS/MSC AFL	48	+3m			21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
320029	CHECK NOSE LANDING GEAR DRAG STAY								
32.070	REF: See Workcard	MOS HRS/MSC AFL	A/R				06-APR-2009 57:24 43		
+ 320033 (s)	DETAIL INSPECT MAIN GEAR RETRACTION ACTUATOR						PKG		
32.095	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
320034 (s)	INSPECT MAIN LANDING GEAR PLUNGER TUBE/AXLE JOINT						PKG		
32.510	PKG 91 REF: AFMS INSPECTION B12	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
320035 (s)	INSPECT MAIN LANDING GEAR MAIN LEG ASSEMBLY RETRACTION LEVER						PKG		
32.520	PKG 92 REF: AFMS INSPECTION C12	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
320036 (s)	INSPECT MAIN LANDING GEAR SIDESTAY ASSEMBLY LOCK MECHANISM LINK						PKG		
32.530	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
320037 (s)	CHECK NOSE LEG ASSEMBLY TORQUE LINKS						PKG		
32.540	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320038	LUBRICATE MAIN LANDING GEAR SIDESTAY SHIMS								
32.570	REF: See Workcard	MOS HRS/MSC AFL	A/R				22-JUL-2018 2823:13 1889		
321001	LEFT MAIN LEG								
32.020	25-8UM523-179A	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
OVERHAUL	DCL0246/08 REF: AMM 32-10-12	HRS/MSC AFL	5000	TSN:0 TSN:0			0 0		5000
321002	RIGHT MAIN LEG								
32.020	25-8UM523-180A	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
OVERHAUL	DCL0249/08 REF: AMM 32-10-12	HRS/MSC AFL	5000	TSN:0 TSN:0			0 0		5000
321013	LEFT SIDESTAY								
32.025	25-8UM3-209A	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
OVERHAUL	ASD0072 REF: AMM 32-10-25	HRS/MSC AFL	5000	TSN:0 TSN:0			0 0		5000
321014	RIGHT SIDESTAY								
32.030	25-8UM3-210A	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
OVERHAUL	ASD0066 REF: AMM 32-10-25	HRS/MSC AFL	5000	TSN:0 TSN:0			0 0		5000
321015	LEFT MAIN LANDING GEAR SIDESTAY UPPER ARM								
32.025	PN	MOS		TSN:0			03-OCT-2008		
LIFE LIMIT	SN-UNKNOWN REF: AMM 32-10-25	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0		10000
321016	RIGHT MAIN LANDING GEAR SIDESTAY UPPER ARM								
32.030	PN	MOS		TSN:0			03-OCT-2008		
LIFE LIMIT	SN-UNKNOWN REF: AMM 32-10-25	HRS/MSC AFL	10000	TSN:0 TSN:0			0 0		10000

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321017	LEFT MAIN LANDING GEAR SIDESTAY LOWER ARM								
	PN	MOS		TSN:0			03-OCT-2008		
32.025	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-25	AFL	12000	TSN:0			0		12000
321018	RIGHT MAIN LANDING GEAR SIDESTAY LOWER ARM								
	PN	MOS		TSN:0			03-OCT-2008		
32.030	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-10-25	AFL	12000	TSN:0			0		12000
321050	LEFT MAIN LANDING GEAR UPPER CASING								
	PN	MOS		TSN:0			03-OCT-2008		
32.390	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	24000	TSN:0			0		24000
321051	RIGHT MAIN LANDING GEAR UPPER CASING								
	PN	MOS		TSN:0			03-OCT-2008		
32.390	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	24000	TSN:0			0		24000
321061	LEFT MAIN LANDING GEAR JACK PIVOT								
	PN	MOS		TSN:0			03-OCT-2008		
32.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
321062	RIGHT MAIN LANDING GEAR JACK PIVOT								
	PN	MOS		TSN:0			03-OCT-2008		
32.040	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
321065	LEFT MAIN LANDING GEAR UPPER TORQUE LINK PIN								
	PN	MOS		TSN:0			03-OCT-2008		
32.400	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321066	RIGHT MAIN LANDING GEAR UPPER TORQUE LINK PIN								
32.400	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
321067	LEFT MAIN LANDING GEAR LOWER TORQUE LINK PIN								
32.495	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
321068	RIGHT MAIN LANDING GEAR LOWER TORQUE LINK PIN								
32.495	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
321071	LEFT MAIN LANDING GEAR JACK DISTANCE PIN								
32.045 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	24000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		24000
321072	RIGHT MAIN LANDING GEAR JACK DISTANCE PIN								
32.045 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	24000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		24000
321075	LEFT MAIN LANDING GEAR PLUNGER TUBE								
32.410 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	17000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		17000
321076	RIGHT MAIN LANDING GEAR PLUNGER TUBE								
32.410 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	17000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		17000

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321081	LEFT MAIN LANDING GEAR UPPER TORQUE LINK								
	PN	MOS		TSN:0			03-OCT-2008		
32.550	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	20000	TSN:0			0		20000
321082	RIGHT MAIN LANDING GEAR UPPER TORQUE LINK								
	PN	MOS		TSN:0			03-OCT-2008		
32.550	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	20000	TSN:0			0		20000
321083	LEFT MAIN LANDING GEAR LOWER TORQUE LINK								
	PN	MOS		TSN:0			03-OCT-2008		
32.555	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	20000	TSN:0			0		20000
321084	RIGHT MAIN LANDING GEAR LOWER TORQUE LINK								
	PN	MOS		TSN:0			03-OCT-2008		
32.555	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	20000	TSN:0			0		20000
321087	LEFT MAIN LANDING GEAR AXLE ASSEMBLY								
	PN	MOS		TSN:0			03-OCT-2008		
32.571	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
321088	RIGHT MAIN LANDING GEAR AXLE ASSEMBLY								
	PN	MOS		TSN:0			03-OCT-2008		
32.572	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
322001	NOSE LEG ASSEMBLY								
	25-9UN1-389A	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
32.050	DCL0241/08	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-20-12	AFL	5000	TSN:0			0		5000

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322003	NOSE LANDING GEAR PIVOT PIN								
	PN	MOS		TSN:0			03-OCT-2008		
32.055	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	16000	TSN:0			0		16000
322007	NOSE LANDING GEAR DRAG STAY								
	25-8UN3-143A	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
32.070	ASD0086	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-20-21	AFL	5000	TSN:0			0		5000
322009	NOSE LANDING GEAR JACK LOWER PIVOT PIN								
	PN	MOS		TSN:0			03-OCT-2008		
32.075	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	22000	TSN:0			0		22000
322011	NOSE LANDING GEAR DRAG STAY BRIDGE CASTING								
	PN	MOS		TSN:0			03-OCT-2008		
32.075	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	33000	TSN:0			0		33000
322015	NOSE LANDING GEAR UPPER TORQUE LINK								
	PN	MOS		TSN:0			03-OCT-2008		
32.080	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	32000	TSN:0			0		32000
322016	NOSE LANDING GEAR LOWER TORQUE LINK								
	PN	MOS		TSN:0			03-OCT-2008		
32.080	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	32000	TSN:0			0		32000
322017	NOSE LANDING GEAR DRAG STRUT PICK-UP								
	PN	MOS		TSN:0			03-OCT-2008		
32.560	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	13900	TSN:0			0		13900

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322025	NOSE GEAR MAIN PICK-UP TRUNNION ATTACHMENT BOLTS								
	PN	MOS		TSN:0			03-OCT-2008		
32.380	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	10000	TSN:0			0		10000
322031	NOSE GEAR RADIUS ROD PICK-UP ATTACHMENT BOLTS								
	PN	MOS		TSN:0			03-OCT-2008		
32.085	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	10000	TSN:0			0		10000
322045	NOSE LANDING GEAR PLUNGER TUBE								
	PN	MOS		TSN:0			03-OCT-2008		
32.075	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	20000	TSN:0			0		20000
323001	NOSE LANDING GEAR RETRACTION JACK								
	AIR45404-1	MOS		TSN:0			03-OCT-2008		
32.090	APB080901	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-30-28	AFL	5000	TSN:0			0		5000
323007	LEFT MAIN LANDING GEAR RETRACTION JACK								
	AIR48502-7	MOS		TSN:0			03-OCT-2008		
32.100	APB081079	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-30-27	AFL	5000	TSN:0			0		5000
323008	RIGHT MAIN LANDING GEAR RETRACTION JACK								
	AIR48503-7	MOS		TSN:0			03-OCT-2008		
32.100	APB081083	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-30-27	AFL	5000	TSN:0			0		5000
323019	LEFT MAIN LANDING GEAR DOOR JACK								
	AIR48485-3	MOS		TSN:0			03-OCT-2008		
32.105	APB081254	HRS/MSC		TSN:0			0		
OVERHAUL	REF:	AFL	5000	TSN:0			0		5000

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323020	RIGHT MAIN LANDING GEAR DOOR JACK								
	AIR48484-3	MOS		TSN:0			03-OCT-2008		
32.105	APB081091	HRS/MSC		TSN:0			0		
OVERHAUL	REF:	AFL	5000	TSN:0			0		5000
323031	LEFT SEQUENCE VALVE								
	AIR48540-1	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
32.110	APB080967	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-30-41	AFL	5000	TSN:0			0		5000
323032	RIGHT SEQUENCE VALVE								
	AIR48540-1	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
32.110	APB080968	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-30-41	AFL	5000	TSN:0			0		5000
323043	LEFT REVERSING VALVE								
	AIR48542-1-3	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
32.115	APB080681	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-30-31	AFL	5000	TSN:0			0		5000
323044	RIGHT REVERSING VALVE								
	AIR48543-1-3	MOS	144	TSN:0			03-OCT-2008	03-OCT-2020	
32.115	APB080971	HRS/MSC		TSN:0			0		
OVERHAUL	REF: AMM 32-30-31	AFL	5000	TSN:0			0		5000
323079	LEFT MAIN LANDING GEAR EXTEND NONRETURN VALVE								
	AIR48026-0-1	MOS		TSN:0			03-OCT-2008		
32.120	APB072862	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
323080	RIGHT MAIN LANDING GEAR EXTEND NONRETURN VALVE								
	AIR48026-0-1	MOS		TSN:0			03-OCT-2008		
32.120	APB072863	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323090	FRAME 15A NON-RETURN VALVE								
32.505	AIR45420-0 APB071651 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
323091	MAIN LANDING GEAR CENTER NONRETURN VALVE								
32.125	AIR48026-0-1 APB072864 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
323097	FRAME 14 NON-RETURN VALVE								
32.130	AIR45420-0 APB081108 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
323098	FRAME 14A NONRETURN VALVE								
32.130	AIR45420-0 APB081108 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
323099	FRAME 15A NONRETURN VALVE								
32.130	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
323103	LANDING GEAR SELECTOR/DUMP VALVE								
32.135	AIR45406-1-2 APB080438 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
323115	LEFT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE								
32.140	AIR45444-0 APB080857 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323116	RIGHT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE								
32.140	AIR45444-0 APB080645 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
323139	LEFT MAIN LANDING GEAR JACK PIVOT BOLT								
32.150	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	30000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		30000
LIFE LIMIT									
323140	RIGHT MAIN LANDING GEAR JACK PIVOT BOLT								
32.150	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	30000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		30000
LIFE LIMIT									
323151	LEFT MAIN LANDING GEAR JACK CYLINDER HEAD								
32.155	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	168 12000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	03-OCT-2022	12000
LIFE LIMIT									
323152	RIGHT MAIN LANDING GEAR JACK CYLINDER HEAD								
32.155	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	168 12000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	03-OCT-2022	12000
LIFE LIMIT									
323163	LEFT MAIN LANDING GEAR JACK EYE END								
32.160	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		10000
LIFE LIMIT									
323164	RIGHT MAIN LANDING GEAR JACK EYE END								
32.160	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		10000
LIFE LIMIT									

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323175	LEFT MAIN LANDING GEAR RETRACTION ARM								
	PN	MOS		TSN:0			03-OCT-2008		
32.165	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	12000	TSN:0			0		12000
<hr/>									
323176	RIGHT MAIN LANDING GEAR RETRACTION ARM								
	PN	MOS		TSN:0			03-OCT-2008		
32.165	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	12000	TSN:0			0		12000
<hr/>									
323181	LEFT MAIN LANDING GEAR RETRACTION ARM PIN								
	PN	MOS		TSN:0			03-OCT-2008		
32.170	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	32000	TSN:0			0		32000
<hr/>									
323182	RIGHT MAIN LANDING GEAR RETRACTION ARM PIN								
	PN	MOS		TSN:0			03-OCT-2008		
32.170	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	32000	TSN:0			0		32000
<hr/>									
323187	LANDING GEAR LEVER LOCK SOLENOID								
	D-5327	MOS		TSN:0			03-OCT-2008		
32.175	K4567	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-30-21	AFL		TSN:0			0		
<hr/>									
324001	NOSE LANDING GEAR AXLE BARREL								
	PN	MOS		TSN:0			03-OCT-2008		
32.195	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-40-31	AFL	30000	TSN:0			0		30000
<hr/>									
324002	NOSE LANDING GEAR AXLE ASSEMBLY								
	PN	MOS		TSN:0			03-OCT-2008		
32.573	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324003	LEFT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY								
32.574	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324004	RIGHT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY								
32.575	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324006	NOSE LANDING GEAR OUTER CASING								
32.576	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324007	LEFT NOSE WHEEL								
32.200	AH52339 5116GH REF: AMM 32-40-21	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
324008	RIGHT NOSE WHEEL								
32.205	AH52339 5103KA REF: AMM 32-40-21	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
324009	NOSE LANDING GEAR TOP LEVER ASSEMBLY								
32.577	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324010	NOSE LANDING GEAR BOTTOM LEVER ASSEMBLY								
32.578	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324019	LEFT NOSE TIRE								
32.200	DR6387T 17281079 REF: AMM 32-40-41	MOS HRS/MSC AFL	T/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
324020	RIGHT NOSE TIRE								
32.205	DR6387T 18094016 REF: AMM 32-40-41	MOS HRS/MSC AFL	T/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
324031	LEFT OUTBOARD MAIN WHEEL								
32.210	AHA1814 5033GL REF: AMM 32-40-12	MOS HRS/MSC AFL	O/C				21-APR-2017 2314:41 1522		
324032	RIGHT OUTBOARD MAIN WHEEL								
32.215	AHA1814 5035GL REF: AMM 32-40-12	MOS HRS/MSC AFL	O/C				27-APR-2017 2325:45 1535		
324033	LEFT INBOARD MAIN WHEEL								
32.220	AHA1814 5155EQ REF: AMM 32-40-12	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
324034	RIGHT INBOARD MAIN WHEEL								
32.225	AHA1814 5154EQ REF: AMM 32-40-12	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
324055	LEFT OUTBOARD MAIN TIRE								
32.210	AR14628T 16308236 REF: AMM 32-40-41	MOS HRS/MSC AFL	T/C				21-APR-2017 2314:41 1522		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324056	RIGHT OUTBOARD MAIN TIRE DR14628T 16308249 REF: AMM 32-40-41	MOS HRS/MSC AFL	T/C				27-APR-2017 2325:45 1535		
32.215									
324057	LEFT INBOARD MAIN TIRE DR14628T 18277223 REF: AMM 32-40-41	MOS HRS/MSC AFL	T/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
32.220									
324058	RIGHT INBOARD MAIN TIRE DR14628T 18276153 REF: AMM 32-40-41	MOS HRS/MSC AFL	T/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
32.225									
324065	RIGHT WHEEL WELL FILTER AIR48538 BF08-0033 REF: AMM 32-30-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
32.230									
324066	LEFT FRAME 14A FILTER AIR48538 BF080178 REF: AMM 32-30-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
32.235									
324067	RIGHT FRAME 14A FILTER AIR48538 BF080170 REF: AMM 32-30-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
32.235									
324068	FRAME 15 FILTER AIR48538 BF080158 REF: AMM 32-30-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
32.235									



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324069	NOSE WHEEL STEERING FILTER								
32.240	AIR45412-0-1 BF08-0077 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324077	PORT SHUTTLE VALVES								
32.407	AH081963 5046FG REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324078	STARBOARD SHUTTLE VALVES								
32.407	AH081963 5050GH REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324079	PORT SHUTTLE VALVES								
32.407	AH081964 5026FE REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324080	STARBOARD SHUTTLE VALVES								
32.407	AH081964 5127GF REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324115	BRAKE CONTROL VALVE								
32.245	AC67732 53GE REF: AMM 32-40-71	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324121	BRAKE CONTROL VALVE LEFT OUTER KNIFE EDGE								
32.245	PN SN-UNKNOWN REF: AMM 32-40-71	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		4500
LIFE LIMIT									

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324122	BRAKE CONTROL VALVE RIGHT OUTER KNIFE EDGE								
	PN	MOS		TSN:0			03-OCT-2008		
32.245	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-40-71	AFL	4500	TSN:0			0		4500
324123	BRAKE CONTROL VALVE INNER KNIFE EDGE								
	PN	MOS		TSN:0			03-OCT-2008		
32.245	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF: AMM 32-40-71	AFL	4500	TSN:0			0		4500
324145	MAIN REDUCING VALVE								
	AC61518	MOS		TSN:0			03-OCT-2008		
32.250	60GE	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
324151	EMERGENCY REDUCING VALVE								
	AC69784	MOS		TSN:0			03-OCT-2008		
32.255	23GE	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 32-40-51	AFL		TSN:0			0		
324157	EMERGENCY REDUCING VALVE LEFT KNIFE EDGE								
	PN	MOS		TSN:0			03-OCT-2008		
32.255	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	4500	TSN:0			0		4500
324158	EMERGENCY REDUCING VALVE RIGHT KNIFE EDGE								
	PN	MOS		TSN:0			03-OCT-2008		
32.255	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	4500	TSN:0			0		4500
324169	EMERGENCY BRAKE PRESSURE NONRETURN VALVE								
	AIR45420-0-1	MOS		TSN:0			03-OCT-2008		
32.500	APB080534	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324175	LEFT OUTBOARD BRAKE UNIT								
32.265	AHA1897 061AW REF: AMM 32-40-114	MOS HRS/MSC AFL	O/C				03-FEB-2011 544:07 420		
324176	RIGHT OUTBOARD BRAKE UNIT								
32.260	AHA1897 5001GL REF: AMM 32-40-114	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324177	LEFT INBOARD BRAKE UNIT								
32.265	AHA1897 5007GL REF: AMM 32-40-114	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324178	RIGHT INBOARD BRAKE UNIT								
32.260	AHA1897 5003GL REF: AMM 32-40-114	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324223	LEFT OUTBOARD MAXARET								
32.270 OVERHAUL	AC65218 25ET REF: AMM 32-40-101	MOS HRS/MSC AFL	3000	TSO:0 TSO:0 TSO:0			11-AUG-2017 2437:29 1613		4613
324224	RIGHT OUTBOARD MAXARET								
32.275 OVERHAUL	AC65216 RJ106 REF: AMM 32-40-101	MOS HRS/MSC AFL	3000	TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938		4938
324225	LEFT INBOARD MAXARET								
32.270 OVERHAUL	AC65216 164GE REF: AMM 32-40-101	MOS HRS/MSC AFL	3000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		3000



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324226	RIGHT INBOARD MAXARET								
32.275	AC65218	MOS		TSN:0			03-OCT-2008		
OVERHAUL	60GG REF: AMM 32-40-101	HRS/MSC AFL	3000	TSN:0 TSN:0			0 0		3000
324260	LEFT MAIN LANDING GEAR DOOR								
32.280	25-8UD505-235A	MOS		TSN:0			03-OCT-2008		
	07120801SAL REF: AMM 32-10-41	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
324261	RIGHT MAIN LANDING GEAR DOOR								
32.280	25-8UD505-236A	MOS		TSN:0			03-OCT-2008		
	07290801SAL REF: AMM 32-10-41	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
324262	LEFT NOSE GEAR DOOR								
32.285	25-8UD501-1A	MOS		TSN:0			03-OCT-2008		
	40089618 REF: AMM 32-20-42	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
324263	RIGHT NOSE GEAR DOOR								
32.285	25-8UD501-2A	MOS		TSN:0			03-OCT-2008		
	40000293 REF: AMM 32-20-42	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
324264	NOSE GEAR DOOR (LEG FAIRING) ASSEMBLY								
32.290	25-8UD503-1A	MOS		TSN:0			03-OCT-2008		
	40085754 REF: AMM 32-20-42	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
324265	LEFT MAIN LANDING GEAR FAIRING								
32.295	25-8UD507-1A	MOS		TSN:0			03-OCT-2008		
	09030801SAL REF: AMM 32-10-32	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324266	RIGHT MAIN LANDING GEAR FAIRING								
32.295	25-8UD507-2A 08110801SAL REF: AMM 32-10-32	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324267	VENTRAL FAIRING ASSEMBLY								
32.295	259W03059-1A CAUP08F015 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324271	LEFT BRAKE MODULATOR								
32.300	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324272	RIGHT BRAKE MODULATOR								
32.300	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324301	PILOT LEFT BRAKE MASTER CYLINDER								
32.310	ACM30946 058GA REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324302	PILOT RIGHT BRAKE MASTER CYLINDER								
32.310	ACM30946 100GB REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324303	COPILOT LEFT BRAKE MASTER CYLINDER								
32.315	ACM30946 101GB REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324304	COPILOT RIGHT BRAKE MASTER CYLINDER								
32.315	ACM30946 057GA REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324325	LEFT EMERGENCY BRAKE PRESSURE WARNING SWITCH								
32.320 OVERHAUL	TP42000 3542 REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	5000	
324326	RIGHT EMERGENCY BRAKE PRESSURE WARNING SWITCH								
32.320 OVERHAUL	TP42000 3534 REF:	MOS HRS/MSC AFL	5000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	5000	
324337	FORWARD HIGH PRESSURE TRANSDUCER								
32.325	695-4-21 7536-2-267 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
324338	AFT HIGH PRESSURE TRANSDUCER								
32.325	695-4-21 7536-2-275 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
325001	STEERING JACK								
32.330	AIR45396-7 APB030466 REF: AMM 32-50-11	MOS HRS/MSC AFL	O/C				27-APR-2017 2325:45 1535		
325003	NOSE LANDING GEAR CONNECTING ROD								
32.335 LIFE LIMIT	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0	20000	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325007	STEERING JACK EYE END								
	PN	MOS		TSN:0			03-OCT-2008		
32.340	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	14400	TSN:0			0		14400
325008	PORT WING TO FUSELAGE FAIRING								
	25-6FC601A	MOS		TSN:0			03-OCT-2008		
32.295	CAVP08C130	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
325009	WING TO FUSELAGE FAIRING								
	25FC5808A	MOS		TSN:0			03-OCT-2008		
32.295	CAVP08G104	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
325010	UNDERCARRIAGE FAIRING								
	25-8FC307-155A	MOS		TSN:0			03-OCT-2008		
32.295	DHB-967	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
325011	NOSE LANDING GEAR TORQUE LINK PICK UP SLEEVE								
	PN	MOS		TSN:0			03-OCT-2008		
32.335	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	20000	TSN:0			0		20000
325012	FAIRING SUB ASSEMBLY								
	25-8FC3603-603A	MOS		TSN:0			03-OCT-2008		
32.295	O7220801SAL	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
325015	NOSE LANDING GEAR STEERING PIN								
	PN	MOS		TSN:0			03-OCT-2008		
32.345	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	25000	TSN:0			0		25000

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325021	NOSE LANDING GEAR MAIN CASING BOLT								
	PN	MOS		TSN:0			03-OCT-2008		
32.345	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	33000	TSN:0			0		33000
325025	NOSE WHEEL STEERING ON/OFF VALVE								
	AIR45408-0	MOS		TSO:0			30-JUL-2011		
32.350	APB081820	HRS/MSC	O/C	TSO:0			667		
	REF:	AFL		TSO:0			489		
325031	NOSE WHEEL ANTI-SHIMMING VALVE								
	AIR48284-2	MOS		TSN:0			03-OCT-2008		
32.355	APB080634	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
325041	NOSE LANDING GEAR UPPER STEERING MAIN MEMBER								
	PN	MOS		TSN:0			03-OCT-2008		
32.360	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	35000	TSN:0			0		35000
325042	NOSE LANDING GEAR LOWER STEERING MAIN MEMBER								
	PN	MOS		TSN:0			03-OCT-2008		
32.360	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	35000	TSN:0			0		35000
325051	NOSE LANDING GEAR STEERING JACK PICK-UP								
	PN	MOS		TSN:0			03-OCT-2008		
32.365	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	18000	TSN:0			0		18000
325058	NOSE LANDING GEAR STEERING SLEEVE								
	PN	MOS		TSN:0			03-OCT-2008		
32.365	SN-UNKNOWN	HRS/MSC		TSN:0			0		
LIFE LIMIT	REF:	AFL	20000	TSN:0			0		20000

CHAPTER 33 LIGHTS

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 330003 (s)	CLEAN/TEST/REPLACE ANTI-COLLISION LIGHT SYSTEM						PKG		
33.080	PKG 91 REF: AFMS INSPECTION B1	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
330007	MAIN CG ILLUMINATED LABEL								
33.015	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
330008	FORWARD CG ILLUMINATED LABEL								
33.015	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
334001	TOP ANTI COLLISION BEACON								
33.020	PN SN-UNKNOWN REF: AMM 33-40-42	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
334002	BOTTOM ANTI COLLISION BEACON								
33.020	01-0790044-54 07447 REF: AMM 33-40-42	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		
334013	LEFT WING STROBE LIGHT								
33.025 REPLACE	01-0770935-02 N/A REF: AMM 33-40-12	MOS HRS/MSC AFL	2000	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938	4892:42	
334014	RIGHT WING STROBE LIGHT								
33.025 REPLACE	01-0770935-02 N/A REF: AMM 33-40-12	MOS HRS/MSC AFL	2000	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938	4892:42	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334016	TEST LEFT WING STROBE LIGHT	INTENSITY							
33.025	01-0770935-02 N/A REF:	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
334017	TEST RIGHT WING STROBE LIGHT	INTENSITY							
33.025	01-0770935-02 N/A REF:	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
334021	NO. 1 POWER CONVERTER								
33.070	LT-55 2772 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
334022	NO. 2 POWER CONVERTER								
33.070	LT-55 2781 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
334044	TAIL STROBE LIGHT								
33.040 REPLACE	31-1840-1 SN-UNKNOWN REF: AMM 33-40-12	MOS HRS/MSC AFL	1500	TSN:0 TSN:0 TSN:0			21-DEC-2017 2577:06 1721	4077:06	
334047	TEST TAIL STROBE LIGHT	INTENSITY							
33.040	31-1840-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				21-DEC-2017 2577:06 1721		
334061	STROBE LIGHTS POWER SUPPLY								
33.045	701571 AD5150 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335001	EMERGENCY LIGHTING INERTIA SWITCH								
33.050	PN SN-UNKNOWN REF: MMA 33-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
335009	FORWARD EMERGENCY LIGHTING POWER SUPPLY								
33.090	60-1321-1 23957 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
335011	AFT EMERGENCY LIGHTING POWER SUPPLY								
33.095	60-1321-1 23966 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
335025	NO. 1 (AA PNL) DIMMER								
33.055	LT52A 19698 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
335027	NO. 2 (AA PNL) DIMMER								
33.055	LT52A 19750 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
335029	NO. 1 (AB PNL) DIMMER								
33.060	LT52A 20724 REF:	MOS HRS/MSC AFL	O/C				22-MAR-2011		
335031	NO. 2 (AB PNL) DIMMER								
33.060	LT52A 19755 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335200	PULSELIGHT CONTROL UNIT								
33.085	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
336027	NO. 5 POWER CONVERTER								
33.070	LT52A 19484 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
336028	NO. 6 POWER CONVERTER								
33.070	LT52A 19486 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
336029	NO. 7 POWER CONVERTER								
33.070	LT52A 19545 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
336030	NO. 8 POWER CONVERTER								
33.070	LT52A 19717 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
336040	ESCAPE HATCH BETALIGHT "EXIT" SIGN								
	132848-11 30476 REF: AMM 33-50-05 Manufacture Date: 09-JAN-2017	MOS HRS/MSC AFL	72				23-MAY-2017 2363:33 1561	09-JAN-2023	
+ 33R799A	INSPECT MECHANICAL AND ELECTRICAL INTEGRITY OF LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT) (900 HRS / 1 YR)								
	REF:	MOS HRS/MSC AFL	12 900	+1m +40			04-MAR-2019 2892:42 1938	04-MAR-2020 3792:42	04-APR-2020 3832:42



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33R799B	INSPECT MECHANICAL AND ELECTRICAL INTEGRITY OF LOPRESTI BOOM BEAM LANDING/TAXI LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT) (1800 HRS/ 2 YRS)	MOS	24	+2m			04-MAR-2019	04-MAR-2021	04-MAY-2021
		HRS/MSC	1800	+50			2892:42	4692:42	4742:42
	REF:	AFL					1938		
+ 33R800A	INSPECT LOPRESTI BOOM BEAM NOSE MOUNTED HID LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT)	MOS	24	+1m			04-MAR-2019	04-MAR-2021	04-APR-2021
		HRS/MSC	1800	+40			2892:42	4692:42	4732:42
	REF:	AFL					1938		
+ 33R800B	INSPECT LOPRESTI BOOM BEAM NOSE MOUNTED HID LIGHTS (IAW INSTRUCTIONS FOR CONTINUED AIRWORTHINESS DOCUMENT) (1800 HRS / 2 YRS)	MOS	24	+2m			04-MAR-2019	04-MAR-2021	04-MAY-2021
		HRS/MSC	1800	+50			2892:42	4692:42	4742:42
	REF:	AFL					1938		
33R802	LEFT HAND TAXI LIGHT BALLAST LSM-500-042 26645	MOS					25-NOV-2008		
	REF:	HRS/MSC	O/C				11		
		AFL					10		
33R803	RIGHT HAND TAXI LIGHT BALLAST LSM-500-042 26647	MOS					25-NOV-2008		
	REF:	HRS/MSC	O/C				11		
		AFL					10		
33R804	LEFT HAND LANDING LIGHT BALLAST LSM-500-042 26646	MOS					25-NOV-2008		
	REF:	HRS/MSC	O/C				11		
		AFL					10		
33R805	RIGHT HAND LANDING LIGHT BALLAST LSM-500-042 26648	MOS					25-NOV-2008		
	REF:	HRS/MSC	O/C				11		
		AFL					10		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33R806	LEFT HAND TAXI LIGHT ASSEMBLY LAMP/ STARTER LSM-500-200-100 26645 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2008 11 10		
33R807	RIGHT HAND TAXI LIGHT ASSEMBLY LAMP/ STARTER LSM-500-200-100 26647 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2008 11 10		
33R808	LEFT HAND LANDING LIGHT ASSEMBLY LAMP/ STARTER LSM-500-200-100 26646 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2008 11 10		
33R809	RIGHT HAND LANDING LIGHT ASSEMBLY LAMP/ STARTER LSM-500-200-100 26648 REF:	MOS HRS/MSC AFL	O/C				25-NOV-2008 11 10		
33R810	LEFT HAND NOSE LIGHT BALLAST LSM-500-047 17547 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 0 0		
33R811	RIGHT HAND NOSE LIGHT BALLAST LSM-500-047 26654 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-NOV-2008 0 0		
33R812	EMERGENCY LIGHTING SYSTEM - LIGHTING DEGRADATION TEST REF:	MOS HRS/MSC AFL	3500	TSI:0			0 00	3500	
CHAPTER 34 NAVIGATION									
340002	DRAIN PITOT/STATIC DRAIN TRAPS 34.025 REF: See Workcard	MOS HRS/MSC AFL	24	+2m			04-MAR-2019 2892:42 1938	04-MAR-2021	04-MAY-2021

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 340003 (s)	INSPECT AUTOPILOT AILERON SERVO UNIT AND MOUNT PKG 92	MOS					PKG 27-JUN-2015		
34.405	REF: AFMS INSPECTION C4	HRS/MSC AFL	1600	+50/-50			1643:39 1058		
+ 340004 (s)	INSPECT AUTOPILOT SERVO UNITS, RUDDER AND ELEVATOR PKG 92	MOS					PKG 27-JUN-2015		
34.410	REF: AFMS INSPECTION C7	HRS/MSC AFL	1600	+50/-50			1643:39 1058		
+ 340005 (s)	INSPECT AUTOPILOT ELEVATOR TRIM SERVO UNIT AND MOUNT PKG 92	MOS					PKG 27-JUN-2015		
34.415	REF: AFMS INSPECTION C7	HRS/MSC AFL	1600	+50/-50			1643:39 1058		
+ 340006	PRESSURE/SUCTION TEST PITOT/STATIC AND STALL WARNING SYSTEMS	MOS	24	+2m			04-MAR-2019 2892:42 1938	04-MAR-2021	04-MAY-2021
34.015	REF: See Workcard	HRS/MSC AFL							
+ 340007	CHECK PITOT SYSTEM ISOLATION VALVES	MOS	24	+2m			03-SEP-2018 2835:14 1893	03-SEP-2020	03-NOV-2020
34.290	REF: AFMS OUT OF PHASE INSPECTIONS	HRS/MSC AFL							
+ 340008 (s)	TEST MACH TRIM SYSTEM PKG 93	MOS					PKG 26-NOV-2008		
34.270	REF: See Workcard	HRS/MSC AFL	3200	+150/-50			0 0		
+ 340010 (s)	TEST AUTOTRIM COMMAND ISOLATION RELAY AND AUTOTRIM SWITCHING RELAY PKG 93	MOS					PKG 26-NOV-2008		
34.425	REF: See Workcard	HRS/MSC AFL	3200	+150/-50			0 0		
+ 340011 (s)	CHECK MACH TRIM FAIL ANNUNCIATION RELAYS PKG 93	MOS					PKG 26-NOV-2008		
34.420	REF: AFMS INSPECTION D1	HRS/MSC AFL	3200	+150/-50			0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 340012	SWING CHECK NO. 1 COMPASS								
34.095	REF: See Workcard	MOS HRS/MSC AFL	36	+2m			25-OCT-2017 2538:28 1684	25-OCT-2020	25-DEC-2020
+ 340012	SWING CHECK NO. 2 COMPASS								
34.095	REF: See Workcard	MOS HRS/MSC AFL	36	+2m			25-OCT-2017 2538:28 1684	25-OCT-2020	25-DEC-2020
+ 340012	SWING CHECK STANDBY COMPASS								
34.095	REF: See Workcard	MOS HRS/MSC AFL	36	+2m			25-OCT-2017 2538:28 1684	25-OCT-2020	25-DEC-2020
340013	COMPLY WITH RVSM REQUIREMENTS FOR THE STATIC PLATES AND AIRFRAME								
34.020	REF: See Workcard	MOS HRS/MSC AFL	A/R				27-OCT-2008		
341001	LEFT PITOT PRESSURE HEAD								
34.010	PN SN-UNKNOWN REF: AMM 34-11-24	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
341002	RIGHT PITOT PRESSURE HEAD								
34.010	PN SN-UNKNOWN REF: AMM 34-11-24	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
341109	LEFT AIRSPEED INDICATOR								
34.050	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
341110	RIGHT AIRSPEED INDICATOR								
34.055	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341111	NO. 1 AIRSPEED REFERENCE PANEL								
34.315	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341112	NO. 2 AIRSPEED REFERENCE PANEL								
34.315	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341115	STANDBY AIRSPEED INDICATOR								
34.045	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341163	LEFT SAT/TAS INDICATOR								
34.320	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341164	RIGHT SAT/TAS INDICATOR								
34.320	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341195	VOICE ADVISORY								
34.060	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341228	NO. 1 AIR DATA COMPUTER								
34.065	822-1109-015 33JDH REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		
341229	NO. 2 AIR DATA COMPUTER								
34.066	822-1109-015 33HLX REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341230	NO. 1 AIR DATA MODULE								
34.325	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341231	NO. 2 AIR DATA MODULE								
34.325	PN SN-UNKNOWN REF: AMM 31-20-66	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341234	SIGNAL INTERFERENCE ADAPTER								
34.330	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341235	(ESIS) MAGNETOMETER								
34.485	19004-00-01 MO21922 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341237	AIR DATA ESIS UNIT								
34.435	39213-00-01 M022975 REF: AMM NO REF	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
+ 341238	TEST AIR DATA ESIS UNIT (FAR 91.411)								
34.435	39213-00-01 M022975 REF: FAR FAR PART 91	MOS HRS/MSC AFL	24				26-FEB-2019	26-FEB-2021	
	MANDATORY								
+ 341240	TEST NO. 1 AIR DATA COMPUTER (FAR 91.411)								
34.065	822-1109-015 33JDH REF: See Workcard	MOS HRS/MSC AFL	24				26-FEB-2019	26-FEB-2021	
	MANDATORY								
+ 341241	TEST NO. 2 AIR DATA COMPUTER (FAR 91.411)								
34.066	822-1109-015 33HLX REF: See Workcard	MOS HRS/MSC AFL	24				26-FEB-2019	26-FEB-2021	
	MANDATORY								

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341276	RADIO ALTIMETER UNIT								
34.070	822-0615-206 33NBV REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341279	LEFT RADIO ALTIMETER ANTENNA								
34.075	S67-2002 543-44397 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
341281	RIGHT RADIO ALTIMETER ANTENNA								
34.080	S67-2002 54344699 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342013	EMERGENCY GYRO HORIZON INDICATOR								
34.090	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342014	SECONDARY FLIGHT DISPLAY								
34.490	39213-00-01 MO22975 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342097	STANDBY COMPASS (E2B) INDICATOR								
34.106	KCA0104W BA9540508 REF: AMM 34-09-112	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342141	NO. 1 VLF/OMEGA SENSOR								
34.105	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342142	NO. 2 VLF/OMEGA SENSOR								
34.105	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342143	H FIELD (TOP) ANTENNA								
34.110	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342144	H FIELD (BOTTOM) ANTENNA								
34.110	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342145	NO. 1 DATA LOADER								
34.115	822-2215-202 30J6G REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-FEB-2011 555:15 427		
342220	NO. 1 FLIGHT MANAGEMENT COMPUTER								
34.350	822-0868-111 4GN3HY REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
342221	NO. 2 FLIGHT MANAGEMENT COMPUTER								
34.350	822-0868-111 4GN3C2 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
342240	REMOTE TUNING UNIT								
34.340	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342253	NO. 1 COMPASS FLUX VALVE								
34.120	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342254	NO. 2 COMPASS FLUX VALVE								
34.120	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342265	NO. 1 AHRs COMPUTER								
34.125	822-1110-002 34K2C REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342266	NO. 2 AHRs COMPUTER								
34.125	822-1110-002 34K1R REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342289	NO. 1 AHRs CONTROLLER								
34.140	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342290	NO. 2 AHRs CONTROLLER								
34.140	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342501	NO. 1 MULTIFUNCTION DISPLAY								
34.130	822-1753-308 33TCY REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342502	NO. 2 MULTIFUNCTION DISPLAY								
34.135	822-1753-308 33TDB REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342513	NO. 1 PRIMARY FLIGHT DISPLAY								
34.130	822-1084-308 33TCP REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342514	NO. 2 PRIMARY FLIGHT DISPLAY								
34.135	822-1084-308 2G87J REF: See Workcard	MOS HRS/MSC AFL	O/C				19-APR-2009 66:54 50		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342515	EFIS MULTIFUNCTION ELECTRONIC DISPLAY								
34.140	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342516	NO. 1 REMOTE INSTRUMENT CONTROL								
34.145	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342517	NO. 2 REMOTE INSTRUMENT CONTROL								
34.145	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342523	MULTIFUNCTION PROCESS UNIT								
34.335	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342525	NO. 1 EFIS DISPLAY PROCESSOR								
34.335	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342526	NO. 2 EFIS DISPLAY PROCESSOR								
34.335	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342527	NO. 1 EFIS SYMBOL GENERATOR								
34.150	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342528	NO. 2 EFIS SYMBOL GENERATOR								
34.150	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342530	MULTIFUNCTION SYMBOL GENERATOR								
34.150	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342537	NO. 1 DISPLAY CONTROL PANEL								
34.155	822-2117-002 30FMP REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342538	NO. 2 DISPLAY CONTROL PANEL								
34.155	822-2117-002 30FMR REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342539	MULTI FUNCTION EFIS CONTROL								
34.160	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342540	FLIGHT GUIDANCE PANEL								
34.440	822-1107-102 34M2R REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342541	NO. 1 CONSOLE CONTROL DISPLAY UNIT								
34.445	822-1485-066 2YTNF REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342542	NO. 2 CONSOLE CONTROL DISPLAY UNIT								
34.450	822-1485-066 2YTJ REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342543	PILOT OPTIONAL CONTROL MODULE								
34.495	822-1484-252 4GN5P7 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342544	COPILOT OPTIONAL CONTROL MODULE								
34.495	822-1484-252 4GN5P6 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
342545	NO. 1 FLUX DETECTOR								
34.500	822-1193-001 39142 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342547	NO. 2 FLUX DETECTOR								
34.500	822-1193-001 40180 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342550	IAPS ENVIROMENTAL CONTROLLER								
34.505	822-1167-001 31PYW REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342561	TCAS COMPUTER								
34.175	822-1294-002 162464 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342562	TCAS (TOP) ANTENNA								
34.180	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342563	TCAS (BOTTOM) ANTENNA								
34.180	622-8973-001 2WJFH REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342601	NO. 1 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT								
34.185	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342602	NO. 2 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT								
34.185	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342624	NO. 1 ADF ANTENNA								
34.190	622-7384-001 30JXF REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342625	NO. 2 ADF ANTENNA								
34.190	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342640	EGPWS COMPUTER								
34.455	965-0976-040-212 EMK5-28146 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342701	NO. 1 DATA CONCENTRATOR UNIT								
34.515	822-1483-002 1VY9L REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			15-SEP-2014 1435:20 942		
342703	NO. 2 DATA CONCENTRATOR UNIT								
34.515	822-1483-002 2TFHX REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342705	NO. 3 DATA CONCENTRATOR UNIT								
34.520	822-1483-002 2TFNH REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342707	NO. 4 DATA CONCENTRATOR UNIT								
34.520	822-1483-002 2TFRH REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342709	DA PANEL ASSEMBLY								
34.525	25-8NF4033-6109 464066 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342801	NO. 1 INPUT / OUTPUT CONCENTRATOR MODULE								
34.530	822-1361-106 4GN3F8 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
342802	NO. 2 INPUT / OUTPUT CONCENTRATOR MODULE								
34.530	822-1361-106 2RYRP REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938		
342805	NO. 1 IAPS POWER SUPPLY								
34.535	822-1137-001 31R6C REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342806	NO. 2 IAPS POWER SUPPLY								
34.535	822-1137-001 31R5F REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342809	AURAL WARNING GENERATOR								
34.540	630-003 1663 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342810	NO. 1 CURSOR CONTROL PANEL								
34.545	822-1746-002 30GDY REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
342811	NO. 2 CURSOR CONTROL PANEL								
34.545	822-1746-002 30GDY REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342812	NO. 1 FILE SERVER UNIT								
34.550	822-1543-101 3G09T REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-APR-2011		
342813	NO. 2 FILE SERVER UNIT								
34.550	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
343001	GLIDE SLOPE AERIAL								
34.195	17-21F6 7859 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
343013	MARKER AERIAL								
34.200	17-5C 7660 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
344001	NO. 1 WEATHER RADAR CONTROL PANEL								
34.205	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
344002	NO. 2 WEATHER RADAR CONTROL PANEL								
34.205	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
344005	WEATHER RADAR TRANSCEIVER								
34.210	622-8441-004 33KCV REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
344016	RADAR CHECKLIST MODULE								
34.215	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344036	ISOLATION VALVE								
34.220	25MC2175 38071339 REF: AMM 34-11-52	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345001	NO. 1 VHF NAVIGATION RECEIVER								
34.300	822-1465-101 33WMB REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345002	NO. 2 VHF NAVIGATION RECEIVER								
34.300	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345003	DATA BASE UNIT								
34.503	822-2215-202 3531Y REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345008	SENSOR UNIT DISPLAY								
34.295	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345009	SENSOR DRIVER DISPLAY								
34.295	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345015	ILS CONVERTER								
34.300	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345019	NO. 1 ADF RECEIVER								
34.310	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345020	NO. 2 ADF RECEIVER								
34.310	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345037	LEFT VOR/LOC AERIAL								
34.230	S65-247-12 7935 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345038	RIGHT VOR/LOC AERIAL								
34.230	S65-247-12 7934 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345049	NO. 1 ADF LOOP ANTENNA								
34.235	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345097	PHASING COUPLER								
34.240	SSPD-113-10 5435 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345098	COUPLER ANTENNA								
34.245	SSPD113-13 1179 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345109	NO. 1 DME AERIAL								
34.250	S65-5366-10L 8661 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345110	NO. 2 DME AERIAL								
34.250	S65-5366-10L 8661 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345133	NO. 1 ATC TRANSPONDER AERIAL								
34.255	S65-5366-10L 8640 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345134	NO. 2 ATC TRANSPONDER AERIAL								
34.255	S65-5366-10L 8640 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345135	FORWARD TRANSPONDER ANTENNA								
34.460	S65-5366-10L 8621 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345136	AFT TRANSPONDER ANTENNA								
34.465	S65-5366-10L 8639 REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345205	NO. 1 DME TRANSCEIVER								
34.305	822-1466-001 2R9GY REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345206	NO. 2 DME TRANSCEIVER								
34.305	822-1466-001 3468B REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345217	NO. 1 ATC TRANSPONDER								
34.260	622-9210-008 34HXD REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345218	NO. 2 ATC TRANSPONDER								
34.260	622-9210-008 34JOD REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 345229	SYSTEM TEST NO. 1 ATC TRANSPONDER (FAR 91.413)								
34.260	622-9210-008	MOS	24				26-FEB-2019	26-FEB-2021	
MANDATORY	34HXD REF: FAR FAR PART 91	HRS/MSC AFL							
+ 345230	SYSTEM TEST NO. 2 ATC TRANSPONDER (FAR 91.413)								
34.260	622-9210-008	MOS	24				26-FEB-2019	26-FEB-2021	
MANDATORY	34JOD REF: FAR FAR PART 91	HRS/MSC AFL							
345305	MACH TRIM COMPUTER								
34.270	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345309	AFIS DMU								
34.470	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345310	AFIS CONFIGURATION MODULE								
34.475	PN SN-UNKNOWN REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345404	NO. 1 GPS SENSOR UNIT								
34.275	822-2189-004 348KV REF: AMM 34-50-45	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
345405	NO. 2 GPS SENSOR UNIT								
34.275	822-2189-004 348LB REF: AMM 34-50-45	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
345406	NO. 1 GPS ANTENNA								
34.280	C1429-410 584835 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345407	NO. 2 GPS ANTENNA								
34.280	CI429-200 569048 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
345413	NO. 1 CONFIGURATION STRAPPING UNIT								
34.285	822-1363-002 31RJH REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345414	NO. 2 CONFIGURATION STRAPPING UNIT								
34.285	822-1363-002 31RHJ REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345513	NO. 1 (AHRs) EXTERNAL COMPENSATION UNIT								
34.480	822-1200-002 2X17L REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345514	NO. 2 (AHRs) EXTERNAL COMPENSATION UNIT								
34.480	822-1200-002 33CHG REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
345515	NO. 1 (IFIS) EXTERNAL COMPENSATION UNIT								
34.555	822-1200-998 34L1R REF: AMM NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
346810	OBSERVERS AMPLIFER								
34.601	DB204 3251 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
349101	PASSENGER SPEAKER AMPLIFIER								
34.606	MODEL 240 4125 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
349998	ADJUSTMENT/TEST COLLINS AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES)								
34.T04	REF: AMM 34-10-19	MOS HRS/MSC AFL	O/C				17-OCT-2008		
349999	ADJUSTMENT/TEST HONEYWELL ADZ-810 AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES)								
34.T05	REF:	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		
CHAPTER 35 OXYGEN									
+ 350001 (s)	CHECK OXYGEN SYSTEM MASTER SUPPLY VALVE						PKG		
35.110	PKG 91 REF: AFMS INSPECTION B4	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 350002 (s)	FUNCTIONAL TEST AUTOMATIC SHUT-OFF VALVE						PKG		
35.035	PKG 93 REF: See Workcard	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 350004 (s)	TEST/INSPECT PASSENGER OXYGEN SYSTEM						PKG		
35.075	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800				04-MAR-2019 2892:42 1938		
+ 350005 (s)	CHECK BAROMATIC CONTROL VALVE						PKG		
35.100	PKG 91 REF: GENERIC NO REF	MOS HRS/MSC AFL	800				04-MAR-2019 2892:42 1938		
+ 350006 (s)	INSPECT CREW MASKS, SMOKE SET MASK (IF FITTED) AND HOSES						PKG		
35.115	PKG 91 REF: AFMS INSPECTION E4	MOS HRS/MSC AFL	800				04-MAR-2019 2892:42 1938		
+ 350007 (s)	INSPECT PORTABLE BREATHING EQUIPMENT						PKG		
35.120	PKG 94 REF: See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 350008 (s)	INSPECT OXYGEN CYLINDERS						PKG		
35.105	PKG 92 REF: AFMS INSPECTION C7	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
351001	MASTER OXYGEN SUPPLY VALVE								
35.030	PN SN-UNKNOWN REF: AMM 35-10-62	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
351013	OXYGEN PRESSURE GAUGE								
35.040	18430901-1 048954 REF: AMM 35-10-32	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
351014	ALTERNATIVE OXYGEN PRESSURE GAUGE								
35.040	PN SN-UNKNOWN REF: AMM 35-10-33	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
351015	OXYGEN CHARGING FILTER ASSEMBLY								
35.215	WKA27942-2 1942 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
351025	OXYGEN REDUCING VALVE								
35.045	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
351031	PILOT OXYGEN MASK								
35.050 OVERHAUL	MF10-03-02 SE17454 REF:	MOS HRS/MSC AFL	72				28-JAN-2014 1262:25 833	27-JAN-2020 M	
351032	COPILOT OXYGEN MASK								
35.050 OVERHAUL	MF10-03-02 SE18571 REF:	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			08-APR-2014 1365:10 899	08-APR-2020	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351043	LEFT OXYGEN OUTLET VALVE								
35.055	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
351044	RIGHT OXYGEN OUTLET VALVE								
35.055	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
+ 351050	CREW CABINET OXYGEN MASK								
35.145	289-601-228 SN-UNKNOWN REF: GENERIC CMM Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			30-JUN-2014 1413:30 929	18-JAN-2020	
+ 351051	NO. 1 PASSENGER OXYGEN MASK								
35.150	289-601-228 SN-UNKNOWN REF: GENERIC CMM Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:00 TSN:0 TSN:00			20-MAY-2014 1259:20 832	18-JAN-2020	
+ 351052	NO. 2 PASSENGER OXYGEN MASK								
35.150	289-601-228 SN-UNKNOWN REF: GENERIC CMM Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351053	NO. 3 PASSENGER OXYGEN MASK								
35.155	289-601-228 SN-UNKNOWN REF: GENERIC CMM Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351054	NO. 4 PASSENGER OXYGEN MASK								
35.155	289-601-228 SN-UNKNOWN REF: GENERIC CMM Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 351055	NO. 5 PASSENGER OXYGEN MASK 289-601-228 35.160 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351056	NO. 6 PASSENGER OXYGEN MASK 289-601-228 35.160 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351057	NO. 7 PASSENGER OXYGEN MASK 289-601-228 35.170 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351058	NO. 8 PASSENGER OXYGEN MASK 289-601-228 35.170 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351059	NO. 9 PASSENGER OXYGEN MASK 289-601-228 35.180 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351060	NO. 10 PASSENGER OXYGEN MASK 289-601-228 35.180 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 351061	NO. 11 PASSENGER OXYGEN MASK 289-601-228 35.190 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
+ 351062	NO. 12 PASSENGER OXYGEN MASK 289-601-228 35.190 OVERHAUL Manufacture Date: 18-JAN-2014	MOS HRS/MSC AFL	72	TSN:0			20-MAY-2014 1393 916	18-JAN-2020	
351080	NO. 1 MASK DEPLOYMENT CONTAINER 833-649-01 35.195 D08080391 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
351081	NO. 2 MASK DEPLOYMENT CONTAINER 833-648-01 35.195 D08070037 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
351082	NO. 3 MASK DEPLOYMENT CONTAINER 833-648-01 35.200 D08070474 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
351083	NO. 4 MASK DEPLOYMENT CONTAINER 833-648-01 35.200 D08070484 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
351084	NO. 5 MASK DEPLOYMENT CONTAINER 833-648-01 35.205 D08070509 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351085	NO. 6 MASK DEPLOYMENT CONTAINER								
35.205	833-648-01 D08070515 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
351086	NO. 7 MASK DEPLOYMENT CONTAINER								
35.210	833-648-01 D8070526 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-NOV-2008 11 10		
351093	OXYGEN PRESSURE SWITCH								
35.125	1106P76-1 1311 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
351101	NO. 1 OXYGEN CYLINDER								
35.010	WKA37447 710196/105 REF: AMM 35-10-14	MOS HRS/MSC AFL	O/C				21-DEC-2017 2577:06 1721		
351102	NO. 2 OXYGEN CYLINDER								
35.015	WKA37447 25102/4801 REF: AMM 35-10-14	MOS HRS/MSC AFL	O/C				21-DEC-2017 2577:06 1721		
351103	NO. 3 OXYGEN CYLINDER								
35.020	WKA37447 718524/18 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-DEC-2017 2577:06 1721		
351104	NO. 4 OXYGEN CYLINDER								
35.025	WKA37447 5779/2839 REF: MMA 35-06-01	MOS HRS/MSC AFL	O/C				21-DEC-2017 2577:06 1721		
+ 351110	HYDROSTATIC TEST NO. 1 OXYGEN CYLINDER								
35.010	WKA37447 710196/105 REF: GENERIC CMM	MOS HRS/MSC AFL	60				21-DEC-2017	21-DEC-2022	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 351110	HYDROSTATIC TEST NO. 2 OXYGEN CYLINDER WKA37447 25102/4801 REF: GENERIC CMM	MOS HRS/MSC AFL	60				21-DEC-2017	21-DEC-2022	
35.015									
+ 351110	HYDROSTATIC TEST NO. 3 OXYGEN CYLINDER WKA37447 718524/18 REF: GENERIC CMM	MOS HRS/MSC AFL	60				21-DEC-2017	21-DEC-2022	
35.020									
+ 351110	HYDROSTATIC TEST NO. 4 OXYGEN CYLINDER WKA37447 5779/2839 REF: GENERIC CMM	MOS HRS/MSC AFL	60				21-DEC-2017	21-DEC-2022	
35.025									
352001	ON/OFF OXYGEN VALVE SDV1012 15746 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
35.065									
352007	BAROMATIC VALVE K39117/3EX 736/1 REF: AMM 35-20-42	MOS HRS/MSC AFL	O/C				04-MAR-2019 2892:42 1938		
35.070									
353031	(PBE) PROTECTIVE BREATHING EQUIPMENT 802300-14 E17020484 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	TSN:0 TSN:0			20-DEC-2017 2577:06 1721	11-SEP-2027	
35.085									
LIFE LIMIT	Manufacture Date: 11-SEP-2017								
354000	AUTOMATIC SHUT OFF VALVE WKA35964-1 1893 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
35.130									

CHAPTER 38 WATER/WASTE



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 380001 (s)	INSPECT TOILET AND GALLEY WATER SYSTEMS						PKG		
38.010	PKG 91 REF: AMM 12-38-00	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 381090	CLEAN GALLEY WATER SYSTEM								
38.020	REF: MMA 38-10-00	DAYS HRS/MSC AFL	30				13-NOV-2018 2867:17 1930	13-DEC-2018	
+ 381091	CLEAN LAVATORY WATER SYSTEM								
38.030	REF: See Workcard	DAYS HRS/MSC AFL	30				13-NOV-2018 2867:17 1930	13-DEC-2018	
CHAPTER 49 AIRBORNE AUXILIARY POWER									
+ 490001	INSPECT PATS APU GTCP36-150W								
49.205	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	12 1000	+1m			04-MAR-2019 2892:42 1938	04-MAR-2020 3892:42	04-APR-2020
490002	REMOVE/CLEAN/INSPECT APU IGNITER PLUG								
49.210	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL APH	750				04-MAR-2019 2892:42 1938 3702	4452	
+ 490003	ACCOMPLISH APU (OPTION 1) OIL AND FILTER CHANGE AND MAGNETIC DRAIN PLUG INSPECTION								
49.220	REF: See Workcard	MOS HRS/MSC AFL	12 1000	+1m			04-MAR-2019 2892:42 1938	04-MAR-2020 3892:42	04-APR-2020
490004	REMOVE AND REPLACE APU FUEL FILTER ELEMENT								
49.230	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL APH	1000				13-JUL-2018 3598	4598	



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
490005	FLOW CHECK APU FUEL NOZZLE ASSEMBLIES								
49.240	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL APH	4500				13-JUL-2018 3598		8098
490006	ACCOMPLISH APU DETAILED HOT SECTION INSPECTION								
49.250	REF: See Workcard	MOS HRS/MSC AFL APH	4500				26-NOV-2008 0 0 0		4500
490007	VISUALLY CHECK APU COMPRESSOR ROTOR								
49.260	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL APH	4500				26-NOV-2008 0 0 0		4500
491005	APU BLEED AIR CHECK VALVE								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
49APU1	APU								
49.APU1	3800304-1 P-1101 REF: AMM 49-11-00	MOS HRS/MSC AFL APH	E/C	TSN:3598			03-AUG-2018 2835:14 1893		
APU Model : GTCP36-150(W) Serial # P-1101 Part # 3800304-1									
491010	APU - TURBINE ROTOR								
49.010	3615880-1 08-01345-01655 REF: GENERIC NO REF	MOS HRS/MSC APUS	10000	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		10000
	LIFE LIMIT								
491020	APU - COMPRESSOR ROTOR								
49.015	3822101-1 080350113962 REF: GENERIC NO REF	MOS HRS/MSC APUS	100000	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		100000
	LIFE LIMIT								



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
491025 (s)	APU - INSPECT COMPRESSOR ROTOR								
49.020	3822101-1 080350113962 REF: MM 49-20-00	MOS HRS/MSC APUS	4500				14-JUL-2008 0 0		
+ 491030 (s)	APU - INSPECT HOT SECTION								
49.025	REF: MM 49-20-00	MOS HRS/MSC APUS	4500				14-JUL-2008 0 0		
493010	APU - FUEL CONTROL								
49.030	3882730-9 33302 REF: MM 49-30-52	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
493020 (s)	APU - REMOVE AND REPLACE FUEL FILTER ELEMENT								
49.035	REF: MM 49-30-52	MOS HRS/MSC APUS	1000				13-JUL-2018 3598		
493030	APU - ORIFICE FITTING								
49.040	PN SN-UNKNOWN REF: MM 49-30-56	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
493040	APU - FUEL SHUTOFF VALVE								
49.045	PN SN-UNKNOWN REF: MM 49-30-54	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
+ 493050 (s)	APU - CHECK FUEL NOZZLE FLOW RATE								
49.050	REF: MM 49-20-00	MOS HRS/MSC APUS	4500				13-JUL-2018 3598 0		
493060	APU - CONTROLLER								
49.055	2118330-2 117-B08070 REF: MM 49-60-46	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493070	APU - LOAD CONTROL VALVE								
49.060	109812-9 4595 REF: MM 49-50-33	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
494010	APU - IGNITION UNIT								
49.065	3888000-2 080218088972 REF: MM 49-40-32	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
494020	APU - IGNITER PLUG								
49.070	CH34313 N/A REF: MM 49-40-33	MOS HRS/MSC APUS	O/C	TSN:29 TSN:0 TSN:0			04-MAY-2017 2991		
+ 494030 (s)	APU - REMOVE AND INSPECT IGNITER PLUG								
49.075	CH34313 N/A REF: MM 49-40-33	MOS HRS/MSC APUS	750				04-MAR-2019 3702		
497010	APU - MOTION PICK UP TRANSDUCER								
49.080	PN SN-UNKNOWN REF: MM 49-60-43	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
497020	APU - IMMERSION THERMOCOUPLE								
49.085	PN SN-UNKNOWN REF: MM 49-60-45	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
497030	APU - HOURMETER								
49.090	PN SN-UNKNOWN REF: MM 49-70-41	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
499010	APU - ROTARY OIL PUMP								
49.095	PN SN-UNKNOWN REF: MM 49-90-51	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499030 (s)	APU - CHANGE OIL								
49.105	REF: MM 49-20-00	MOS HRS/MSC APUS	12 750				04-MAR-2019 3702		
499040 (s)	APU - REMOVE AND REPLACE OIL FILTER ELEMENT								
49.110	REF: MM 49-90-47	MOS HRS/MSC APUS	12 750				04-MAR-2019 3702		
499050	APU - PRESSURE REGULATOR VALVE								
49.115	PN SN-UNKNOWN REF: MM 49-90-52	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2008 0 0		
499060	APU - HIGH OIL TEMPERATURE SWITCH								
49.120	3888030-1 09227 REF: MM 49-60-46	MOS HRS/MSC APUS	O/C				03-AUG-2018 3598		
499070	APU - LOW OIL PRESSURE SWITCH								
49.125	3876001-8 N/A REF: MM 49-60-43	MOS HRS/MSC APUS	O/C				03-AUG-2018 3600		
CHAPTER 51 STD PRACTICES AND STRUCT-GENRL									
+ 510001	INSPECT NOSE LANDING GEAR BAY SIDEWALLS								
51.100	REF: See Workcard	MOS HRS/MSC AFL	144 5000	+3m +10%			26-NOV-2008 0 0	26-NOV-2020 5000	26-FEB-2021 5500
+ 510002	DETAIL INSPECT FRONT PRESSURE BULKHEAD								
51.010	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	5000	+10%			26-NOV-2008 0 0	5000	5500
+ 510003	INSPECT FLIGHT COMPARTMENT SKIN AND WINDOW STRUCTURE ABOVE WINDSHIELDS								
51.020	REF: See Workcard	MOS HRS/MSC AFL	144	+3m			26-NOV-2008 0 0	26-NOV-2020	26-FEB-2021

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 510004	DETAIL INSPECT UPPER CANOPY RAIL AT INTERSECTION WITH THE CANOPY POSTS								
51.030		MOS HRS/MSC AFL	20000	+500			26-NOV-2008 0 0	20000	20500
	REF: AFMS STRUCTURAL INSPECTIONS								
+ 510005	INSPECT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, NOSE LANDING GEAR BAY TO FRAME 13 AND FRAMES 16 TO 19								
51.040		MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
	REF: See Workcard								
+ 510006	DETAIL INSPECT STRUCTURE BELOW ESCAPE HATCH, FRAMES 13 TO 14								
51.050		MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
	REF: AFMS STRUCTURAL INSPECTIONS								
+ 510007	INSPECT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 8 TO 17								
51.060		MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
	REF: See Workcard								
+ 510008	X-RAY CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 13 TO 16								
51.070		MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
	REF: See Workcard								
+ 510009	DETAIL INSPECT ENTRY DOOR SURROUND								
51.080		MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
	REF: AFMS STRUCTURAL INSPECTIONS								
+ 510010	INSPECT CENTER FUSELAGE STRUCTURE, ABOVE THE FLOOR								
51.090		MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
	REF: See Workcard								

CHAPTER 52 DOORS

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 520004 (s)	CHECK MAIN ENTRY DOOR "NOT LOCKED" WARNING MICROSWITCHES						PKG		
52.025	PKG 92 REF: AFMS INSPECTION C6	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 520005 (s)	CHECK ESCAPE HATCH RELEASE MECHANISM						PKG		
52.015	PKG 91 REF: AMM 52-20-00	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 520006 (s)	INSPECT ESCAPE HATCH SEALS						PKG		
52.035	PKG 91 REF:	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 520007 (s)	INSPECT/CHECK ENTRY DOOR						PKG		
52.010	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 520008	INSPECT MAIN ENTRY DOOR								
52.010	REF: NTM 52-80-102	MOS HRS/MSC AFL	144	+3m			26-NOV-2008 0 0	26-NOV-2020	26-FEB-2021
+ 520009	DETAIL INSPECT ESCAPE HATCH								
52.015	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
+ 520010 (s)	INSPECT MAIN ENTRY DOOR - FOLDING HANDRAIL (IF FITTED)						PKG		
52.050	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
521001	MAIN ENTRY DOOR ASSEMBLY								
52.010	259W03838-1A SD-DH-859 REF: AMM 52-11-00	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521016	LONG RANGE TANK DOOR								
52.055	25-8PT111-87A PZLDH827 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
522001	ESCAPE HATCH								
52.015	25-8FC3601-151A 06040801SAL REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 53 FUSELAGE									
+ 530001	DETAIL INSPECT SKIN EXTERIOR UNDER THE DORSAL INTAKE, FORWARD OF FRAME 19								
53.115	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 530002	INSPECT FUSELAGE SKIN UNDER WING-TO-FUSELAGE FAIRINGS								
53.040	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 530003	DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL FUEL TANK (IF FITTED).								
53.110	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
+ 530004	DETAIL INSPECT VENTRAL FUEL TANK AND ATTACHMENTS, (IF FITTED)								
28.015	REF: See Workcard	MOS HRS/MSC AFL	180	+3m			26-NOV-2008 0 0	26-NOV-2023	26-FEB-2024
+ 530007	DETAIL INSPECT WING TO FUSELAGE ATTACHMENT LINKS, BRACKETS AND BOLTS								
53.105	REF: AMM 53-40-01	MOS HRS/MSC AFL	144	+3m			26-NOV-2008 0 0	26-NOV-2020	26-FEB-2021



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 530009	INSPECT FUSELAGE LAP JOINTS								
53.125	REF: NTM 53-10-104	MOS HRS/MSC AFL	27000	+500			26-NOV-2008 0 0	27000	27500
530010	DETAIL INSPECT SKIN OF THE FUSELAGE, WING ATTACHMENT BRACKETS, DRAG SPIGOT BEARING AND DRAG SPIGOT HOUSING								
53.020	REF:	MOS HRS/MSC AFL	A/R				26-NOV-2008 0 0		
+ 530011	INSPECT FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)								
53.175	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 530012	INSPECT FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)								
53.070	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	96	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2024	26-FEB-2025
+ 530013	INSPECT PYLON ENGINE MAIN MOUNTING ATTACHMENT FITTINGS								
53.030	REF: See Workcard	MOS HRS/MSC AFL	10000	+500			26-NOV-2008 0 0	10000	10500
+ 530014	INSPECT REAR ENGINE MOUNT FITTINGS								
53.035	REF: See Workcard	MOS HRS/MSC AFL	20000	+500			26-NOV-2008 0 0	20000	20500
+ 530015	INSPECT VERTICAL STABILIZER ROOT ATTACHMENT TO FUSELAGE								
53.015	REF: See Workcard	MOS HRS/MSC AFL	30000	+500			26-NOV-2008 0 0	30000	30500



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 530016	DETAIL INSPECT ENGINE BEAM								
53.080	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	10000	+500			26-NOV-2008 0 0	10000	10500
530017	INSPECT NO. 1 ENGINE MOUNTING BRACKETS								
53.200 PART OF MPI	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	E/C				26-NOV-2008 0 0		
530017	INSPECT NO. 2 ENGINE MOUNTING BRACKETS								
53.200 PART OF MPI	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	E/C				26-NOV-2008 0 0		
530018	DETAIL INSPECT FUSELAGE SKIN ADJACENT TO CABIN WINDOW CUTOUTS								
53.205	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	4800	+10%			26-NOV-2008 0 0	4800	5280
530019	DETAIL INSPECT APU SUPPORT STRUCTURE EXTERNAL TO THE FIRE ENCLOSURE								
53.210	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	12	+1m			03-NOV-2018 2867:17 1930	03-NOV-2019	03-DEC-2019
+ 530021	DETAIL INSPECT APU SUPPORT STRUCTURE								
53.010	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL APH	3000				04-MAY-2017 2342:38 1547 2997	5997	
530022	DETAIL INSPECT APU MOUNTING HARDWARE								
53.215	REF: See Workcard	MOS HRS/MSC AFL APH	4500				03-AUG-2018 2835:14 1893 3598	8098	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
530023	DETAIL INSPECT FUSELAGE STRUCTURE FOR CRACKS								
53.220	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL APH	4500				03-AUG-2018 2835:14 1893 3598	8098	
530024	FLUORESCENT PENETRANT INSPECT APU SUPPORT HARDWARE								
53.225	REF: See Workcard	MOS HRS/MSC AFL APH	22500				26-NOV-2008 0 0 0	22500	
+ 530025	DETAIL INSPECT APU EXHAUST AND INLET DOUBLER FRAMES AND STRINGERS								
53.170	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	10000	+500			26-NOV-2008 0 0	10000	10500
+ 530027 (s)	VISUAL INSPECTION FUSELAGE SKIN								
53.235	PKG 96 REF: AFMS INSPECTION G	MOS HRS/MSC AFL	48	+2m/-2m			PKG 21-DEC-2016 2148:39 1399		
531146	RADOME								
53.135	PN SN-UNKNOWN REF: AMM 53-50-14	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		
531152	TAIL CONE FAIRING								
53.140	251W00120-3A CAVP08F049 REF: AMM 53-50-16	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		
531154	FUSELAGE								
53.145	25-8FA1-47A 258963 REF:	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		

CHAPTER 55 STABILIZERS

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 550001	DETAIL INSPECT ELEVATORS AND TABS								
27.070	REF: See Workcard	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
550002	LUBRICATE/REPLACE ELEVATOR TRIM TABS, CONNECTING RODS								
55.075	REF: See Workcard	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 550003	XRAY ELEVATORS								
55.055	REF: See Workcard	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 550004	DETAIL INSPECT RUDDER AND TAB								
27.045	REF: See Workcard	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
550005	INSPECT RUDDER CONNECTING RODS, RUDDER TRIM TAB AND ANTI-SERVO TAB								
55.065	REF: See Workcard	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 550006	X-RAY RUDDER (IN-SITU)								
27.045	REF: See Workcard	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 550007	DETAIL INSPECT RUDDER HINGE BRACKETS AND ATTACHMENTS								
27.045	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	96	+3m			21-DEC-2016 2148:39 1399	21-DEC-2024	21-MAR-2025
+ 550008 (s)	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER REAR ATTACHMENT FITTING								
55.010	REF: AFMS INSPECTION F8	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 550009	DETAIL INSPECT HORIZONTAL STABILIZER	MOS	96	+3m			21-DEC-2016	26-NOV-2024	26-FEB-2025
55.040	REF: AFMS STRUCTURAL INSPECTIONS	HRS/MSC AFL			-25		2148:39 1399		
+ 550010	DETAIL INSPECT VERTICAL STABILIZER	MOS	180	+3m			26-NOV-2008	26-NOV-2023	26-FEB-2024
55.050	REF: See Workcard	HRS/MSC AFL					0 0		
+ 550011	INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER ATTACHMENTS	MOS	192	+3m			26-NOV-2008	26-NOV-2024	26-FEB-2025
55.025	REF: AFMS STRUCTURAL INSPECTIONS	HRS/MSC AFL					0 0		
+ 550012	INSPECT/TEST HORIZONTAL STABILIZER	MOS	288	+3m			26-NOV-2008	26-NOV-2032	26-FEB-2033
55.045	REF: See Workcard	HRS/MSC AFL					0 0		
+ 550013	X-RAY HORIZONTAL STABILIZER	MOS	180	+3m			26-NOV-2008	26-NOV-2023	26-FEB-2024
55.035	REF: See Workcard	HRS/MSC AFL					0 0		
+ 550014	DETAIL INSPECT HORIZONTAL STABILIZER TOP SKIN 'T' FITTING AND JOINT STRAP AT THE CENTER LINE OF THE STABILIZER	MOS	15000	+500			26-NOV-2008	15000	15500
55.060	REF: AFMS STRUCTURAL INSPECTIONS	HRS/MSC AFL					0 0		
+ 550015	INSPECT ELEVATOR MASS BALANCE WEIGHTS AND SPIGOTS	MOS	24	+2m			04-MAR-2019	21-DEC-2020	21-FEB-2021
55.070	REF: See Workcard	HRS/MSC AFL			-73		2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
551004	UPPER VERTICAL STABILIZER								
55.015	25-8TF513-1A CAVP08F006 REF: AMM 55-32-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
551006	TAILPLANE								
55.020	25-8TP509-1A SD-DH-096 REF: AMM 55-13-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
551010	BULLET FAIRING								
55.030	25-8GF501-6155A 40105719 REF: AMM 53-50-18	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
553005	FIN LEADING EDGE								
55.305	25-8TF133-3A CAVP08B008 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 56 WINDOWS									
+ 560004 (s)	INSPECT WINDOWS DRY-AIR SYSTEM FILTER ELEMENT (IF FITTED)						PKG		
56.065	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 560005 (s)	CHECK PASSENGER CABIN WINDOWS						PKG		
56.090	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 560006 (s)	INSPECT WINDSHIELD PANEL 'C' SILICA GEL CONTAINER						PKG		
56.070	PKG 91 REF: AFMS INSPECTION B4	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
561001	LEFT (PANEL A) HEATED WINDSCREEN								
56.010	NF24016-415 L471490 REF: AMM 56-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-DEC-2017 2577:06 1721		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561002	RIGHT (PANEL A) HEATED WINDSCREEN								
56.010	NH24016-92 L423119 REF: AMM 56-10-11	MOS HRS/MSC AFL	O/C				27-JUN-2015 1643:39 1058		
561003	LEFT DIRECT VIEW B WINDOW								
56.015	NH24016-91 L466365 REF: AMM 56-10-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-DEC-2017 2577:06 1721		
561004	RIGHT DIRECT VIEW B WINDOW								
56.015	NH24016-92 L464946 REF: AMM 56-10-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-DEC-2017 2577:06 1721		
561005	LEFT C WINDOW								
56.020	25-8FN353-43A CW0829 REF: AMM 56-10-31	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-MAR-2019 2892:42 1938		
561006	RIGHT C WINDOW								
56.020	PAS25-8FN353-44A 25367 REF: AMM 56-10-31	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
562001	NO. 1 LEFT CABIN WINDOW								
56.025	LA25FC7881-53 4274 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562002	NO. 1 RIGHT CABIN WINDOW								
56.025	LA25FC7881-53 3838 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562003	NO. 2 LEFT CABIN WINDOW								
56.030	LA25FC7881-53 4484 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562004	NO. 2 RIGHT CABIN WINDOW LA25FC7881-53 3756 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562005	NO. 3 LEFT CABIN WINDOW LA25FC7881-53 4474 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562006	NO. 3 RIGHT CABIN WINDOW LA25FC7881-53 4508 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562007	NO. 4 LEFT CABIN WINDOW LA25FC7881-53 4319 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562008	NO. 4 RIGHT CABIN WINDOW LA25FC7881-53 4353 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562009	NO. 5 LEFT CABIN WINDOW LA25FC7881-53 4480 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562010	NO. 5 RIGHT CABIN WINDOW LA25FC7881-53 4373 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
562011	NO. 6 LEFT CABIN WINDOW LA25FC7881-53 4518 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562012	NO. 6 RIGHT CABIN WINDOW								
56.050	LA25FC7881-53 4442 REF: AMM 56-20-11	MOS HRS/MSC AFL	O/C	TSN:125 TSR:0 TSR:0 TSN:1938 TSR:0			04-MAR-2019 2892:42 1938		
CHAPTER 57 WINGS									
+ 570001 (s)	INSPECT LEFT FLAP HINGE FITTINGS						PKG		
57.095	PKG 91 REF: AFMS INSPECTION B9	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 570002 (s)	INSPECT RIGHT FLAP HINGE FITTINGS						PKG		
57.095	PKG 91 REF: AFMS INSPECTION B10	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 570003 (s)	DETAIL INSPECT LEFT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4						PKG		
57.090	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 570004	INSPECT LEFT FLAP SKIN PROTECTION PANELS (IF FITTED)							26-NOV-2008	
57.140	REF: AFMS INSPECTION F9	MOS HRS/MSC AFL	N/R				0 0		
+ 570005 (s)	DETAIL INSPECT RIGHT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4						PKG		
57.090	PKG 95 REF: See Workcard	MOS HRS/MSC AFL	24	+2m/-2m			04-MAR-2019 2892:42 1938		
+ 570006	INSPECT RIGHT FLAP SKIN PROTECTION PANELS (IF FITTED)							26-NOV-2008	
57.140	REF: AFMS INSPECTION F10	MOS HRS/MSC AFL	N/R				0 0		
+ 570007	X-RAY WING BOTTOM SKINS AND STRINGERS BETWEEN THE FRONT AND REAR SPARS, RIB 0 TO RIB 1 AND BETWEEN THE CENTER SPAR AND REAR SPAR FROM RIB 1 TO RIB 4								
57.040	REF: See Workcard	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 570008	DETAIL INSPECT MAIN LANDING GEAR AND SIDESTAY ATTACHMENT FITTINGS								
57.035	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021
+ 570009	DETAIL INSPECT WING BOTTOM SKIN (LH AND RH) ADJACENT TO FLAP OUTBOARD HINGE AT RIB 8								
57.070	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	4800	+10%			26-NOV-2008 0 0	4800	5280
+ 570010	DETAIL INSPECT WING FRONT SPAR, FORWARD FACE								
57.020	REF: See Workcard	MOS HRS/MSC AFL	96 4800	+3m +10%	-25		21-DEC-2016 2148:39 1399	26-NOV-2024 6948:39	26-FEB-2025 7428:39
+ 570011	INSPECT WING REAR SPAR, REAR FACE								
57.030	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48 2400	+3m +10%	-25		21-DEC-2016 2148:39 1399	26-NOV-2020 4548:39	26-FEB-2021 4788:39
+ 570012	DETAIL INSPECT LEFT LOWER AIRBRAKE								
27.240	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48 2400	+3m +10%	-25		21-DEC-2016 2148:39 1399	26-NOV-2020 4548:39	26-FEB-2021 4788:39
+ 570012	DETAIL INSPECT LEFT UPPER AIRBRAKE								
27.240	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48 2400	+3m +10%	-25		21-DEC-2016 2148:39 1399	26-NOV-2020 4548:39	26-FEB-2021 4788:39
+ 570012	DETAIL INSPECT RIGHT LOWER AIRBRAKE								
27.245	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48 2400	+3m +10%	-25		21-DEC-2016 2148:39 1399	26-NOV-2020 4548:39	26-FEB-2021 4788:39



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 570012	DETAIL INSPECT RIGHT UPPER AIRBRAKE	MOS	48	+3m			21-DEC-2016	26-NOV-2020	26-FEB-2021
27.245	REF: AFMS STRUCTURAL INSPECTIONS	HRS/MSC AFL	2400	+10%			2148:39 1399	4548:39	4788:39
+ 570013	DETAIL INSPECT AILERONS	MOS	48	+3m			21-DEC-2016	26-NOV-2020	26-FEB-2021
27.020	REF: See Workcard	HRS/MSC AFL	2400	+10%			2148:39 1399	4548:39	4788:39
570014	LUBRICATE CONNECTING RODS, AILERON TRIM AND SERVO TABS	MOS	48	+3m			21-DEC-2016	26-NOV-2020	26-FEB-2021
57.145	REF: See Workcard	HRS/MSC AFL	2400	+10%			2148:39 1399	4548:39	4788:39
+ 570015	INSPECT/X RAY AILERONS	MOS	48	+3m			21-DEC-2016	26-NOV-2020	26-FEB-2021
57.100	REF: See Workcard	HRS/MSC AFL	2400	+10%			2148:39 1399	4548:39	4788:39
+ 570016	INSPECT/X RAY FLAPS AND FLAP VANES	MOS	48	+3m			21-DEC-2016	26-NOV-2020	26-FEB-2021
57.130	REF: See Workcard	HRS/MSC AFL	2400	+10%			2148:39 1399	4548:39	4788:39
+ 570017	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO FRONT SPAR, BETWEEN RIBS 1 AND 7	MOS					26-NOV-2008		
57.055	REF: See Workcard	HRS/MSC AFL	24000	+500			0 0	24000	24500
+ 570018	DETAIL INSPECT WING BOTTOM SKIN CENTERLINE JOINT STRAP	MOS					26-NOV-2008		
57.080	REF: See Workcard	HRS/MSC AFL	24000	+500			0 0	24000	24500
+ 570019	INSPECT UPPER SURFACE OF THE WING BOTTOM SKIN AT THE ATTACHMENT TO THE CENTERLINE JOINT ADJACENT TO RIB 0	MOS					26-NOV-2008		
57.060	REF: See Workcard	HRS/MSC AFL	24000	+500			0 0	24000	24500



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 570020	INSPECT WING BOTTOM SKIN CENTERLINE BUTT STRAP AND CENTER SECTION BEAMS (24 POSITIONS)								
57.075	REF: See Workcard	MOS HRS/MSC AFL	24000	+500			26-NOV-2008 0 0	24000	24500
570021	DETAIL INSPECT WING TOP SKIN IN THE AREA THAT IS COVERED BY THE FUSELAGE STRUCTURE AND MAIN ATTACHMENT BRACKETS.								
57.010	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	A/R				26-NOV-2008 0 0		
+ 570022	DETAIL INSPECT REAR SPAR, REAR FACE BETWEEN RIB 1 LH AND RIB 1 RH								
57.050	REF: See Workcard	MOS HRS/MSC AFL	4800	+10%			26-NOV-2008 0 0	4800	5280
+ 570023	DETAIL INSPECT AILERON HORN BALANCE WEIGHT								
57.135	REF: See Workcard	MOS HRS/MSC AFL	N/R				26-NOV-2008 0 0		
+ 570024	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO RIB 1 LH AND RH								
57.065	REF: See Workcard	MOS HRS/MSC AFL	12000	+500			26-NOV-2008 0 0	12000	12500
+ 570025	DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO THE REAR SPAR, BETWEEN RIB 1 LH AND RIB 1 RH								
57.050	REF: See Workcard	MOS HRS/MSC AFL	4800	+10%			26-NOV-2008 0 0	4800	5280
+ 570026	INSPECT WING LEADING EDGES								
57.025	REF: AFMS STRUCTURAL INSPECTIONS	MOS HRS/MSC AFL	48	+3m	-25		21-DEC-2016 2148:39 1399	26-NOV-2020	26-FEB-2021



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 570027	DETAIL INSPECT WING INTERNAL STRUCTURE FORWARD OF THE CENTER SPAR INCLUDING THE FRONT AND CENTER SPARS FROM RIBS 0 TO 4, AND BETWEEN AND INCLUDING THE FRONT AND REAR SPARS FROM RIB 4 TO THE WING TIP								
57.045	REF: See Workcard	MOS HRS/MSC AFL	96 4800	+3m +10%		-25	21-DEC-2016 2148:39 1399	26-NOV-2024 6948:39	26-FEB-2025 7428:39
+ 570028	INSPECT AILERON AT OUTBOARD HINGE CASTING								
57.125	REF: See Workcard	MOS HRS/MSC AFL	N/R				26-NOV-2008 0 0		
+ 570029	VISUALLY INSPECT WING OUTER, UPPER AND LOWER SKINS								
57.155	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	300	+10%			27-JUN-2018 2788:08 1862	3088:08	3118:08
571010	WING								
57.010	25-8WA7-1 258963 REF:	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		
571109	REPLACE LEFT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS								
57.150 LIFE LIMIT	REF:	MOS HRS/MSC AFL	14600				03-OCT-2008 0 0	14600	
571110	REPLACE RIGHT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS								
57.150 LIFE LIMIT	REF:	MOS HRS/MSC AFL	14600				03-OCT-2008 0 0	14600	
574001	LEFT LEADING EDGE ASSEMBLY								
57.085	25-8WS3299-3A AST08E1229 REF:	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
574002	RIGHT LEADING EDGE ASSEMBLY								
57.085	25-8WS3299-4A AST07H456 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 71 POWER PLANT									
710049	COMPRESSOR WASH NO. 1 ENGINE								
71.025	REF: GENERIC CMM	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		
710050	COMPRESSOR WASH NO. 2 ENGINE								
71.025	REF: GENERIC CMM	MOS HRS/MSC AFL	O/C				03-OCT-2008 0 0		
710081	NO. 1 ENGINE INLET COWL								
71.055	C46B-11000-21 B736 REF: AMM 71-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
710082	NO. 2 ENGINE INLET COWL								
71.055	C46B-11000-22 B736 REF: AMM 71-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
710083	NO. 1 ENGINE UPPER FAN COWL DOOR								
71.060	PN SN-UNKNOWN REF: AMM 71-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
710084	NO. 2 ENGINE UPPER FAN COWL DOOR								
71.060	PN SN-UNKNOWN REF: AMM 71-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
710089	NO. 1 ENGINE LOWER FAN COWL DOOR								
71.070	PN SN-UNKNOWN REF: AMM 71-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710090	NO. 2 ENGINE LOWER FAN COWL DOOR								
71.070	PN SN-UNKNOWN REF: AMM 71-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
712001	NO. 1 ENGINE MOUNTING								
71.075	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
712002	NO. 2 ENGINE MOUNTING								
71.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	3075160-4 P129435 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C	TSN:0 TSN:0 TSN:0			15-SEP-2008 0 0		
71EN2	NO. 2 ENGINE								
71.EN2	3075160-4 P129434 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C	TSN:0 TSN:0 TSN:0			15-SEP-2008 0 0		

ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4

+ 714010	NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS								
71.030	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC ENC	400				04-MAR-2019 2892:42 1944	(3292:42) 3292:42	
+ 715010	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS								
71.040	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC ENC	400				04-MAR-2019 2892:42 1944	(3292:42) 3292:42	

ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 714010	NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS								
71.030	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC ENC	400				04-MAR-2019 2892:42 1944	(3292:42) 3292:42	
715010	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS								
71.040	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC ENC	400				04-MAR-2019 2892:42 1944	(3292:42) 3292:42	
CHAPTER 72 ENGINE									
+ 720002	INSPECT NO. 1 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT								
72.030 PART OF MPI	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	2100	+10%	-48:39		21-DEC-2016 2148:39 1399	4200	4410
+ 720002	INSPECT NO. 2 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT								
72.030 PART OF MPI	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	2100	+10%	-48:39		21-DEC-2016 2148:39 1399	4200	4410
+ 720003	DETAIL INSPECT NO. 1 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP								
72.040 PART OF MPI	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	2100	+10%	-48:39		21-DEC-2016 2148:39 1399	4200	4410
+ 720003	DETAIL INSPECT NO. 2 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP								
72.040 PART OF MPI	REF: AFMS OUT OF PHASE INSPECTIONS	MOS HRS/MSC AFL	2100	+10%	-48:39		21-DEC-2016 2148:39 1399	4200	4410
ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4									
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								
71.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	2100	+100	-48:39		16-NOV-2016 2148:39 1402	(4200) 4200	4300

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710130	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								
71.020	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	400				04-MAR-2019 2892:42 1944	(3292:42) 3292:42	
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE								
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK								
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE								
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
+ 723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)								
72.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	4200	+200			16-JUN-2008 0 0	(4200) 4200	4400
724110	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE								
72.020	3075749-5 08P07838 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:101 TSN:2148:39 TSN:1402			16-NOV-2016 2148:39 1402		
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE								
72.030	3075749-5 08P07838 REF: LMM 72-40-04	MOS HRS/MSC ENC	2100	+500			16-NOV-2016 2148:39 1402	(4248:39) 4248:39	4748:39
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC								
72.040	70080021-2 14-156103-00747 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				16-NOV-2016 2148:39 1402	(11402) 11396	
LIFE LIMIT									

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3075425-1 070322903408	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
72.050 LIFE LIMIT	REF: GENERIC NO REF								
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3075574-7 070322904049	MOS HRS/MSC ENC	12000	TSN:2148:39 TSN:1402			16-NOV-2016 2148:39 1402		(12000) 11994
72.060 LIFE LIMIT	REF: GENERIC NO REF								
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC 3075814-1 08-13651-01005	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
72.070 LIFE LIMIT	REF: LMM 72-50-06								
725050	NO. 1 ENGINE - FAN DISC 3074621-4 08-13651-00637	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
72.080 LIFE LIMIT	REF: GENERIC NO REF								
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 07-03160-04618	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
72.090 LIFE LIMIT	REF: GENERIC NO REF								
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3075839-1 070316004419	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(20000) 19994
72.100 LIFE LIMIT	REF: GENERIC NO REF								
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 070316004600	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(20000) 19994
72.110 LIFE LIMIT	REF: GENERIC NO REF								
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 07-03501-11704	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(20000) 19994
72.120 LIFE LIMIT	REF: GENERIC NO REF								

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725091	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								
72.130	3074744-1 08P07538 REF: LMM 72-30-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725110	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER								
72.140 LIFE LIMIT	3075765-1 070322905937 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0	(10000) 9994	
725130	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT								
72.150 LIFE LIMIT	3072545-1 08P08679 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0	(12000) 11994	
725140	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE								
72.160 LIFE LIMIT	3075579-1 080316000556 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0	(30000) 29994	
725150	NO. 1 ENGINE - FAN DRIVE SHAFT								
72.170	3074641-4 08P13076 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								
72.180	PN SN-UNKNOWN REF: LMM 72-50-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE								
72.190	3075406-8 08P15092 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL								
72.200	3073765-9 08-17565-03623 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT								
72.210	3074052-2 08-17565-04048 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725230	NO. 1 ENGINE - FAN SPINNER								
72.220	3074623-3 16-5060-00131 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-NOV-2016 2148:39 1402		
726110	NO. 1 ENGINE - ACCESSORY GEARBOX								
72.230	3070003-29 S-3478 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX								
72.240	3070003-29 S-3478 REF: LMM 72-60-02	MOS HRS/MSC ENC	4200	+200			16-JUN-2008 0 0	(4200) 4200	4400
726130	NO. 1 ENGINE - TRANSFER GEARBOX								
72.250	3070093-12 08P14824 REF: LMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
726140	NO. 1 ENGINE - INSPECT TRANSFER GEARBOX								
72.280	3070093-12 08P14824 REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
+ 727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY								
72.270	REF: LMM 72-70-06	MOS HRS/MSC ENC	4200	+200			16-JUN-2008 0 0	(4200) 4200	4400
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)								
71.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	2100	+100	-48:39		11-NOV-2016 2148:39 1402	(4200) 4200	4300



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710130	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES								
71.020	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	400				04-MAR-2019 2892:42 1944	(3292:42) 3292:42	
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE								
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK								
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE								
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
+ 723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)								
72.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	4200	+200			16-JUN-2008 0 0	(4200) 4200	4400
724110	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE								
72.020	3075749-5 08P07839 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:101 TSN:2148:39 TSN:1402			11-NOV-2016 2148:39 1402		
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE								
72.030	3075749-5 08P07839 REF: LMM 72-40-04	MOS HRS/MSC ENC	2100	+500			11-NOV-2016 2148:39 1402	(4248:39) 4248:39	4748:39
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC								
72.040	70080021-2 14-156103-00748 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000		TSN:0 TSN:0 TSN:0		16-NOV-2016 2148:39 1402	(11402) 11396	
LIFE LIMIT									

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3075425-1 070322903405 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3075574-7 070322902917 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:2148:39 TSN:1402			16-NOV-2016 2148:39 1402		(12000) 11994
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC 3075814-1 08-13651-01002 REF: LMM 72-50-06	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
725050	NO. 2 ENGINE - FAN DISC 3074621-4 08-13651-00638 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 07-03160-04624 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(10000) 9994
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3075839-1 070316004414 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(20000) 19994
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 070316001909 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(20000) 19994
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 07-03501-11705 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		(20000) 19994

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725091	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD								
72.130	3074744-1 7P26698 REF: LMM 72-30-10	MOS HRS/MSC ENC	O/C	TSO:0 TSN:12862:32 TSO:0 TSN:8600 TSO:0			16-NOV-2016 2148:39 1402		
725110	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER								
72.140	3075765-1 070322905938 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0	(10000) 9994	
LIFE LIMIT									
725130	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT								
72.150	3072545-1 08P08678 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0	(12000) 11994	
LIFE LIMIT									
725140	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE								
72.160	3075579-1 080316000560 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0	(30000) 29994	
LIFE LIMIT									
725150	NO. 2 ENGINE - FAN DRIVE SHAFT								
72.170	3074641-4 08P13077 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT								
72.180	3075292-4 08P09856 REF: LMM 72-50-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725180	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE								
72.190	3075406-8 08P15093 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:101 TSN:2148:39 TSN:1402			16-NOV-2016 2148:39 1402		
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL								
72.200	3073765-9 08-17565-03549 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT								
72.210	3074052-2 08-17565-04052 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
725230	NO. 2 ENGINE - FAN SPINNER								
72.220	3074623-3 16-5060-00101 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-NOV-2016 2148:39 1402		
726110	NO. 2 ENGINE - ACCESSORY GEARBOX								
72.230	3070003-29 S-3448 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX								
72.240	3070003-29 S-3448 REF: LMM 72-60-02	MOS HRS/MSC ENC	4200	+200			16-JUN-2008 0 0	(4200) 4200	4400
726130	NO. 2 ENGINE - TRANSFER GEARBOX								
72.250	3070093-12 08P14823 REF: LMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
726140	NO. 2 ENGINE - INSPECT TRANSFER GEARBOX								
72.280	3070093-12 08P14823 REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				16-JUN-2008 0 0		
+ 727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY								
72.270	REF: LMM 72-70-06	MOS HRS/MSC ENC	4200	+200			16-JUN-2008 0 0	(4200) 4200	4400
CHAPTER 73 ENGINE FUEL AND CONTROL									
+ 730001 (s)	DRAIN PT2 PIPELINES TO FUEL COMPUTERS						PKG		
73.050	PKG 91 REF: AFMS INSPECTION B7	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732025	NO. 1 ENGINE LOW FUEL PRESSURE SWITCH HTE690014-2	MOS		TSN:0			03-OCT-2008		
73.020	16080945 REF: AMM 73-32-11	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
732026	NO. 2 ENGINE LOW FUEL PRESSURE SWITCH HTE690014-2	MOS		TSN:0			03-OCT-2008		
73.020	18080846 REF: AMM 73-32-11	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
732037	NO. 1 ENGINE FUEL FILTER TEMPERATURE SWITCH HE60010	MOS		TSN:0			03-OCT-2008		
73.025	1986TW REF: AMM 73-33-11	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
732038	NO. 2 ENGINE FUEL FILTER TEMPERATURE SWITCH HE60010	MOS		TSN:0			03-OCT-2008		
73.025	1985TW REF: AMM 73-33-11	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
732109	ENGINE FUEL SYNCHRONIZER 2118756-1	MOS		TSN:0			03-OCT-2008		
73.035	38-C0682 REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
733013	NO. 1 ENGINE FUEL FLOW INDICATOR PN	MOS		TSN:0			03-OCT-2008		
73.045	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
733014	NO. 2 ENGINE FUEL FLOW INDICATOR PN	MOS		TSN:0			03-OCT-2008		
73.045	SN-UNKNOWN REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4									
731110	NO. 1 ENGINE - FUEL PUMP 3060710-23	MOS		TSN:0			16-JUN-2008		
73.010	1448 REF: LMM 73-20-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731120	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					04-MAR-2019		
73.010	REF: LMM 73-21-02 TR 73-5	HRS/MSC ENC	400				2892:42 1944	(3292:42) 3292:42	
731130	NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1	MOS		TSN:0			16-JUN-2008		
73.030	11401 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731140	NO. 1 ENGINE - FUEL HEATER 158670-5	MOS		TSN:0			16-JUN-2008		
73.040	8992 REF: LMM 73-10-04	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731160	NO. 1 ENGINE - FUEL HEATER CHECK VALVE PN	MOS		TSN:0			16-JUN-2008		
73.060	SN-UNKNOWN REF: LMM 73-10-04	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732110	NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-45	MOS		TSR:0			16-NOV-2016		
73.070	A9573C REF: LMM 73-20-01	HRS/MSC ENC	O/C	TSR:0 TSR:0			2148:39 1402		
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE 3070685-6	MOS		TSN:0			16-JUN-2008		
73.080	17787 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732160	NO. 1 ENGINE - FUEL FLOW TRANSMITTER 9-127-55	MOS		TSN:0			16-JUN-2008		
73.090	J10438 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									
731110	NO. 2 ENGINE - FUEL PUMP 3060710-23	MOS		TSN:0			16-JUN-2008		
73.010	1444 REF: LMM 73-20-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731120	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					04-MAR-2019		
73.010	REF: LMM 73-21-02 TR 73-5	HRS/MSC ENC	400				2892:42 1944	(3292:42) 3292:42	
731130	NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1	MOS		TSN:0			16-JUN-2008		
73.030	11402 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731140	NO. 2 ENGINE - FUEL HEATER 158670-5	MOS		TSN:0			16-JUN-2008		
73.040	8991 REF: LMM 73-10-04	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
731160	NO. 2 ENGINE - FUEL HEATER CHECK VALVE PN	MOS		TSN:0			16-JUN-2008		
73.060	SN-UNKNOWN REF: LMM 73-10-04	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-45	MOS		TSR:0			16-NOV-2016		
73.070	A9284C REF: LMM 73-20-01	HRS/MSC ENC	O/C	TSR:0 TSR:0			2148:39 1402		
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE 3070685-6	MOS		TSN:0			16-JUN-2008		
73.080	17943 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
732160	NO. 2 ENGINE - FUEL FLOW TRANSMITTER 9-127-55	MOS		TSN:0			16-JUN-2008		
73.090	J10482 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		

CHAPTER 74 IGNITION

ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741110	NO. 1 ENGINE - IGNITION UNIT 3073776-1	MOS					30-JUL-2014		
74.010	080218088063 REF: LMM 74-00-01	HRS/MSC ENC	O/C						
+ 741120	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 0	MOS					16-NOV-2016		
74.010	REF: LMM 74-00-01	HRS/MSC ENC	1400				2148:39 1402	(3548:39) 3548:39	
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG PN	MOS					16-JUN-2008		
74.030	SN-UNKNOWN REF: LMM 74-00-01	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
+ 742120	NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					04-MAR-2019		
74.030	REF: LMM 74-00-01	HRS/MSC ENC	1400				2892:42 1944	(4292:42) 4292:42	
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG 3074541-4	MOS					04-MAR-2019		
74.050	N/A REF: LMM 74-00-01	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			2892:42 1944		
+ 742140	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					04-MAR-2019		
74.050	REF: LMM 74-00-01	HRS/MSC ENC	1400				2892:42 1944	(4292:42) 4292:42	
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									
741110	NO. 2 ENGINE - IGNITION UNIT 3073776-1	MOS					16-JUN-2008		
74.010	80218088068 REF: LMM 74-00-01	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
+ 741120	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 0	MOS					11-NOV-2016		
74.010	REF: LMM 74-00-01	HRS/MSC ENC	1400				2148:39 1402	(3548:39) 3548:39	

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG								
74.030	PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
+ 742120	NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE								
74.030	PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1400				04-MAR-2019 2892:42 1944	(4292:42) 4292:42	
742130	NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG								
74.050	PN SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
+ 742140	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE								
74.050	PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1400				04-MAR-2019 2892:42 1944	(4292:42) 4292:42	
CHAPTER 75	AIR								
751013	NO. 1 ENGINE THERMAL ANTI-ICE VALVE								
75.020	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
751014	NO. 2 ENGINE THERMAL ANTI-ICE VALVE								
75.021	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
754010	NO. 1 ENGINE ANTI-ICE PRESSURE SWITCH								
75.015	12423 5011TW REF: AMM 75-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
754011	NO. 2 ENGINE ANTI-ICE PRESSURE SWITCH								
75.015	12423 5020TW REF: AMM 75-40-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4									
750130	NO. 1 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR								
	3070816-12	MOS		TSN:0			16-JUN-2008		
75.010	081789319125	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 75-40-01	ENC		TSN:0			0		
<hr/>									
751010	NO. 1 ENGINE - ANTI-ICE VALVE								
	F10A5SCP102-5	MOS		TSN:0			16-JUN-2008		
75.020	3BD47	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
<hr/>									
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									
750130	NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR								
	3070816-12	MOS		TSN:0			16-JUN-2008		
75.010	081789319130	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 75-40-01	ENC		TSN:0			0		
<hr/>									
751010	NO. 2 ENGINE - ANTI-ICE VALVE								
	F10A5SCP102-5	MOS		TSN:0			16-JUN-2008		
75.020	3BD45	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
<hr/>									
CHAPTER 76 ENGINE CONTROLS									
+ 760001 (s)	CHECK THROTTLE LEVER CONTROLS						PKG		
	PKG 91	MOS					04-MAR-2019		
76.030		HRS/MSC	800	+40/-10			2892:42		
	REF: See Workcard	AFL					1938		
<hr/>									
+ 760002 (s)	CHECK ENGINE POWER CONTROL CABLES						PKG		
	PKG 92	MOS					27-JUN-2015		
76.010		HRS/MSC	1600	+50/-50			1643:39		
	REF: See Workcard	AFL					1058		
<hr/>									
760003	CHECK POWER CONTROL CABLES								
		MOS					10-DEC-2009		
76.020		HRS/MSC	O/C				157:48		
	REF: AMM 76-10-00	AFL					135		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
760004	LUBRICATE NO. 1 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING								
76.040	REF: AFMS LUBRICATION	MOS HRS/MSC AFL	2100				21-DEC-2016 2148:39 1399	4248:39	
760004	LUBRICATE NO. 2 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING								
76.040	REF: AFMS LUBRICATION	MOS HRS/MSC AFL	1200				21-DEC-2016 2148:39 1399	3348:39	
ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4									
760130	NO. 1 ENGINE - DOWNLOAD ECTM								
76.050	REF: See Workcard	MOS HRS/MSC ENC	40	+10			04-MAR-2019 2892:42 1944	(1984) 1978	1994
761310	NO. 1 ENGINE - SURGE BLEED VALVE								
76.030	978812-7-1 15180 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		16-NOV-2016 2148:39 1402		
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE								
76.040	109696-4-1 13182 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		16-JUN-2008 0 0		
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									
760130	NO. 2 ENGINE - DOWNLOAD ECTM								
76.050	REF: See Workcard	MOS HRS/MSC ENC	40	+10			04-MAR-2019 2892:42 1944	(1984) 1978	1994
761310	NO. 2 ENGINE - SURGE BLEED VALVE								
76.030	978812-7-1 9877 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C		TSO:0 TSO:0 TSO:0		16-NOV-2016 2148:39 1402		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE								
76.040	109696-4-1 13193 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
CHAPTER 77 ENGINE INDICATING									
771025	NO. 1 ENGINE LOW-PRESSURE (N1) INDICATOR								
77.010	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
771026	NO. 2 ENGINE LOW-PRESSURE (N1) INDICATOR								
77.010	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
771037	NO. 1 ENGINE HIGH-PRESSURE (N2) INDICATOR								
77.015	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
771038	NO. 2 ENGINE HIGH-PRESSURE (N2) INDICATOR								
77.015	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
773005	LEFT TIME DELAY SWITCH								
77.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
773006	RIGHT TIME DELAY SWITCH								
77.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
774013	NO. 1 ENGINE ITT INDICATOR								
77.030	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774014	NO. 2 ENGINE ITT INDICATOR								
77.030	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4									
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER								
77.010	PN SN-UNKNOWN REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
771120	NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								
77.020	PN SN-UNKNOWN REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
772110	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS								
77.030	3073605-1 1615027700272 REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-NOV-2016 2148:39 1402		
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									
771110	NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER								
77.010	PN SN-UNKNOWN REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
771120	NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER								
77.020	PN SN-UNKNOWN REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
772110	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS								
77.030	PN SN-UNKNOWN REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
CHAPTER 78 EXHAUST									

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 780001 (s)	INSPECT THRUST REVERSER LINK ARM ASSEMBLIES						PKG		
78.110	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780002 (s)	INSPECT REVERSER DOOR SEALS						PKG		
78.120	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780003 (s)	TEST THRUST REVERSER STOW/DEPLOY MICROSWITCHES						PKG		
78.130	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 780004 (s)	INSPECT PYLON SKIN PANELS						PKG		
78.135	PKG 92 REF: AFMS INSPECTION C11	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 780005 (s)	DETAIL INSPECT DOOR LINK RODS AND PIVOT BRACKETS						PKG		
78.140	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
+ 780006 (s)	CHECK THRUST REVERSER LEVER BAULK MECHANISM						PKG		
78.125	PKG 93 REF: AFMS INSPECTION D4	MOS HRS/MSC AFL	3200	+150/-50			26-NOV-2008 0 0		
+ 780009 (s)	INSPECT THRUST REVERSER AFTERBODY, DOORS AND FAN FLAPS						PKG		
78.155	PKG 91 REF: AFMS INSPECTION B11	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780010 (s)	INSPECT THRUST REVERSER HYDRAULIC LINES AND WIRING HARNESS						PKG		
78.160	PKG 91 REF: AFMS INSPECTION B7	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 780011 (s)	DETAIL INSPECT THRUST REVERSER EXHAUST NOZZLES PKG 91	MOS					PKG		
78.165	REF: AFMS INSPECTION B11	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780012 (s)	INSPECT THRUST REVERSER HYDRAULIC LINES PKG 91	MOS					PKG		
78.170	REF: AFMS INSPECTION B11	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780013 (s)	INSPECT THRUST REVERSER WIRE HARNESSSES PKG 91	MOS					PKG		
78.175	REF: AFMS INSPECTION B11	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780014 (s)	INSPECT THRUST REVERSER FAN DUCTS PKG 91	MOS					PKG		
78.180	REF: AFMS INSPECTION B11	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780015 (s)	INSPECT THRUST REVERSER LATCH BOX SPRINGS PKG 91	MOS					PKG		
78.185	REF: AFMS INSPECTION B11	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780016 (s)	OPERATIONAL TEST THRUST REVERSER LATCH MONITORING SWITCHES PKG 91	MOS					PKG		
78.190	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780017 (s)	INSPECT THRUST REVERSER LATCHES AND LATCH RECEPTACLES PKG 91	MOS					PKG		
78.195	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780018 (s)	INSPECT THRUST REVERSER PRIMARY AND LATCH HYDRAULIC ACTUATORS PKG 91	MOS					PKG		
78.200	REF: See Workcard	HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 780019 (s)	INSPECT THRUST REVERSER THROTTLE RETARD HYDRAULIC ACTUATORS						PKG		
78.205	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780020 (s)	INSPECT THRUST REVERSER FAN FLAP HYDRAULIC ACTUATORS						PKG		
78.210	PKG 91 REF: See Workcard	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780021 (s)	INSPECT THRUST REVERSER PYLON PLUGS						PKG		
78.215	PKG 91 REF: AFMS INSPECTION B11	MOS HRS/MSC AFL	800	+40/-10			04-MAR-2019 2892:42 1938		
+ 780022 (s)	CHECK DOOR LINK RODS						PKG		
78.220	PKG 92 REF: See Workcard	MOS HRS/MSC AFL	1600	+50/-50			27-JUN-2015 1643:39 1058		
781001	NO. 1 ENGINE THRUST REVERSER AFTERBODY								
78.015	5451101-79 HX602-79 REF: AMM 78-33-40	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
781002	NO. 2 ENGINE THRUST REVERSER AFTERBODY								
78.015	5451101-81 HX602-81 REF: AMM 78-33-40	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
781013	NO. 1 ENGINE THRUST REVERSER ASSEMBLY								
78.010	HS7830100-3 HX602-3 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		
781014	NO. 2 ENGINE THRUST REVERSER ASSEMBLY								
78.011	HS7830100-4 HX602-4 REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
781026	NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR								
78.020	PN SN-UNKNOWN REF: AMM 78-32-40	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781027	NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR								
78.020	PN SN-UNKNOWN REF: AMM 78-32-40	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781028	NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR								
78.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781029	NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR								
78.025	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781053	NO. 1 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY								
78.030	PN SN-UNKNOWN REF: AMM 78-32-50	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781054	NO. 1 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY								
78.030	PN SN-UNKNOWN REF: AMM 78-32-50	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781055	NO. 2 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY								
78.035	PN SN-UNKNOWN REF: AMM 78-32-50	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781056	NO. 2 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY								
78.035	PN SN-UNKNOWN REF: AMM 78-32-50	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
781090	NO. 1 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY								
78.040	PN SN-UNKNOWN REF: AMM 78-32-60	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781091	NO. 1 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY								
78.040	5453511-15 HX559-27-02A REF: AMM 78-32-60	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			04-MAR-2019 2892:42 1938		
781092	NO. 2 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY								
78.045	PN SN-UNKNOWN REF: AMM 78-32-60	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781093	NO. 2 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY								
78.045	PN SN-UNKNOWN REF: AMM 78-32-60	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781117	NO. 1 ENGINE RETARD THROTTLE ASSEMBLY								
78.050	5453305-3 HX375-5-01 REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781118	NO. 2 ENGINE RETARD THROTTLE ASSEMBLY								
78.050	5453305-3 HX0630-5 REF: AMM 78-32-30	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1938		
781129	THRUST REVERSER TIME DELAY RELAY								
78.055	5400619-1 HX416-110 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781130	CONTROL RELAY BOX								
78.060	5400612-1 HX449-102 REF: AMM 78-33-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
781136	AUXILIARY RELAY BOX								
78.065	5400605-1 HX524-1 REF: AMM 78-33-30	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781142	NO. 1 ENGINE THRUST REVERSER CONTROL VALVE								
78.070	064135141-11 A30041608 REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781143	NO. 2 ENGINE THRUST REVERSER CONTROL VALVE								
78.070	064135141-11 A30040886 REF: AMM 78-32-20	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-DEC-2016 2148:39 1399		
781155	THRUST REVERSER ACCUMULATOR								
78.075	DS259-3 60209-1380 REF: AMM 78-32-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-JUN-2011 643:25 476		
781156	HYDRAULIC RELIEF VALVE								
78.080	MS28893-D6 74946 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781161	THRUST REVERSER CONTROL PANEL								
78.085	5412600-3 HX409-103 REF: AMM 78-33-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781167	NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH								
78.090	2365-15 4219 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
781169	NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH								
78.090	2365-15 4211 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
781173	THRUST REVERSER PRESSURE GAUGE								
78.090	MS28061T7 2286 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
783008	NO. 1 ENGINE LOWER THRUST REVERSER DOOR								
78.095	PN SN-UNKNOWN REF: AMM 78-31-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
783009	NO. 2 ENGINE LOWER THRUST REVERSER DOOR								
78.095	PN SN-UNKNOWN REF: AMM 78-31-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
783010	NO. 1 ENGINE UPPER THRUST REVERSER DOOR								
78.100	PN SN-UNKNOWN REF: AMM 78-31-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
783011	NO. 2 ENGINE UPPER THRUST REVERSER DOOR								
78.100	PN SN-UNKNOWN REF: AMM 78-31-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
783013	NO. 1 ENGINE INNER FAN DUCT ASSEMBLY								
78.230	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
783014	NO. 2 ENGINE INNER FAN DUCT ASSEMBLY								
78.231	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
CHAPTER 79 OIL									
792144	NO. 1 ENGINE OIL LOW PRESSURE SWITCH								
79.030	HTE690012 18081262 REF: AMM 79-33-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792145	NO. 2 ENGINE OIL LOW PRESSURE SWITCH								
79.030	HTE690012 18081263 REF: AMM 79-33-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
793001	NO. 1 ENGINE OIL PRESSURE TRANSMITTER								
79.040	APTE-354-1000-70G 7473-3-125 REF: AMM 79-32-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
793002	NO. 2 ENGINE OIL PRESSURE TRANSMITTER								
79.040	APTE-354-1000-70G 7445-2-609 REF: AMM 79-32-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
793037	NO. 1 ENGINE OIL PRESSURE INDICATOR								
79.045	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
793038	NO. 2 ENGINE OIL PRESSURE INDICATOR								
79.045	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
793049	NO. 1 ENGINE OIL TEMPERATURE INDICATOR								
79.050	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		
793050	NO. 2 ENGINE OIL TEMPERATURE INDICATOR								
79.050	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-OCT-2008 0 0		

ENGINE NO. 1 Model : TFE731-5BR-1H Serial # P129435 Part # 3075160-4

+ 790110	NO. 1 ENGINE - ANALYZE OIL AND FILTER								
79.010	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			04-MAR-2019 2892:42 1944	(3042:42) 3042:42	3142:42

Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: **TEXTRON FINANCIAL CORPORATION**

Report Date: **28-MAY-2019**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790120	NO. 1 ENGINE - CHANGE OIL								
79.020	REF: See Workcard	MOS HRS/MSC ENC	1200	+100			16-NOV-2016 2148:39 1402	(3348:39) 3348:39	3448:39
+ 790130	NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR								
79.030	PKG 1 REF: LMM 79-20-03	MOS HRS/MSC ENC	200	+50			04-MAR-2019 2892:42 1944	(3092:42) 3092:42	3142:42
792110	NO. 1 ENGINE - OIL PUMP								
79.040	3060785-3 051405700783 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C				TSO:0 TSO:0 TSO:0 27-APR-2017 2325:45 1538		
792120	NO. 1 ENGINE - BY-PASS INDICATOR VALVE								
79.050	PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C				TSN:0 TSN:0 TSN:0 16-JUN-2008 0 0		
792130	NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY								
79.060	PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C				TSN:0 TSN:0 TSN:0 16-JUN-2008 0 0		
792140	NO. 1 ENGINE - UPPER OIL COOLER								
79.070	158600-7 13606 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C				TSN:0 TSN:0 TSN:0 16-JUN-2008 0 0		
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER								
79.080	159900-3 10981 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C				TSN:0 TSN:0 TSN:0 16-JUN-2008 0 0		
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER								
79.090	159910-3 9821 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C				TSN:0 TSN:0 TSN:0 16-JUN-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792170	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR								
79.100	158610-8 11156 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
ENGINE NO. 2 Model : TFE731-5BR-1H Serial # P129434 Part # 3075160-4									
+ 790110	NO. 2 ENGINE - ANALYZE OIL AND FILTER								
79.010	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			04-MAR-2019 2892:42 1944	(3042:42) 3042:42	3142:42
790120	NO. 2 ENGINE - CHANGE OIL								
79.020	REF: See Workcard	MOS HRS/MSC ENC	1200	+100			11-NOV-2016 2148:39 1402	(3348:39) 3348:39	3448:39
+ 790130	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR								
79.030	PKG 1 REF: LMM 79-20-03	MOS HRS/MSC ENC	200	+50			04-MAR-2019 2892:42 1944	(3092:42) 3092:42	3142:42
792110	NO. 2 ENGINE - OIL PUMP								
79.040	3060785-3 991405700203 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			27-APR-2017 2325:45 1538		
792120	NO. 2 ENGINE - BY-PASS INDICATOR VALVE								
79.050	PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY								
79.060	3075323-3 18P27756 REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2019 2892:42 1944		
792140	NO. 2 ENGINE - UPPER OIL COOLER								
79.070	158600-7 13604 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		



Status Report

HAWKER 850XP S/N 258980 (N850TK): 2893:12 HRS, 1939 AFL as of 13-Mar-2019

Owner/Operator: TEXTRON FINANCIAL CORPORATION

Report Date: 28-MAY-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER								
79.080	159900-3 10979 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER								
79.090	159910-3 9819 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		
792170	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR								
79.100	158610-8 11155 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			16-JUN-2008 0 0		